

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

EQ

Owner : Kang Tiong Peng

Accident Date : 5-Jul-19

Vehicle No : FY 4446 T

Vehicle Model : Yamaha YXZ

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fender	\$ 65.00 X
2	Fork inner tubes	\$ 210.00 X
2	Fork outer tubes	\$ 220.00 X
1	Fork under bracket	\$ 145.00 X
1	Front brake disc	\$ 135.00 X
1	Front sport rim	\$ 250.00 X
1	Front rim shaft	\$ 38.00 X
1	Top cowl	\$ 85.00 X
1	Headlamp	\$ 70.00 X
1	Side mirror -R/H	\$ 35.00 X
1	Front signal	\$ 40.00
1	Handle bar -R/H	\$ 68.00 X
1	Hand grip (1 set)	\$ 35.00 X
1	Handle bar end	\$ 18.00
1	Brake lever	\$ 25.00
1	Front footrest -R/H	\$ 32.00
1	Front footrest bracket	\$ 55.00
1	Brake pedal	\$ 32.00 X
1	Rear footrest -R/H	\$ 28.00
1	Exhaust assy	\$ 450.00
2	Exhaust protectors	\$ 100.00
1	Rear tailboard -R/H	\$ 70.00 X
		\$ 2,206.00
Less 10%		\$ 220.60
		\$ 1,985.40

Not A part
n/s \$ 850/
3 dy.
10/7/19
The Rep. Agent

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

748

c/f: \$ 1,985.40

Special Nett Items

1	Number plate (1 set)	\$	Set	28.00	10
2	Fork oils	\$	17	30.00	q
2	Fork oil seals	\$	17	56.00	q
1	Steering cone (1 set)	\$	17	75.00	X
1	Rear box	\$	047	250.00	180
1	Rear box bracket	\$	17	100.00	X
				\$	539.00

S/No. **Labour**

1	To provide towing service.	\$	35	50.00	X
2	To check wiring and reset headlamp focusing	\$	17	80.00	X
3	To provide labour.	\$	200	380.00	
				\$	510.00

Grand Total \$ 3,034.40


EROFIA MOTOR TRADING PTE LTD