

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4
 #02-37 Premier @ Kaki Bukit
 Singapore 415875
 Tel : 94513429

ESTIMATE

AXA Insurance Singapore Pte Ltd
 8 Shenton Way
 #27-01 AXA Tower
 Singapore 068811

Date: 11.07.2019
 Vehicle no: SLR 5620R
 Model: Peugeot 3008
 DOA: 09.07.2019

PARTS

01) Rear bumper	\$ <i>de</i>	1,280.00	—
02) Rear bumper clips	\$ <i>reb</i>	80.00	—
03) Rear bumper reinforcement	\$	850.00	?
04) Rear bumper lower pad	\$ <i>de</i>	450.80	—
05) Rear bumper bracket @125.00 x2	\$ <i>rr</i>	250.00	X
	\$	2,910.80	
	Less 10%	\$ (291.08)	
	\$	2,619.72	

S/Nett

06) Rear number plate with garnish	\$ <i>Buy</i>	75.00	<i>40 s.n</i>
07) Reverse sensor	\$ <i>shhd</i>	320.00	<i>200 s.n</i>
	\$	395.00	

Labour charges

08) To check wiring and replace sensor	\$	100.00	<i>50</i>
09) to apply anti rust chemical	\$ <i>rr</i>	100.00	<i>X</i>
10) To knock out dent on affected areas and renew parts	\$	600.00	<i>400</i>
11) To putty & respray painting	\$	800.00	<i>400</i>
	\$	1,600.00	

Sub Total \$ **4,614.72**

for JA AUTOCARE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*not about
 the
 weight before pay,
 2 day.
 15/7/19*