

INS. CASE OWNER:

cc 6, WPC 190 12192, A/c 3n2

LKK:
IDAC:

Surveyor:

Imp

DOI:

ASSIGNMENT

9/12/19

Date / Time:

9/12/19

Registered in Merimen:

Pre-assign / CCU / FTE

SKB 813J



Insured Vehicle No.:

Claim No.:

18/19/19/19/05/01/049

Name of Insured:

UM BE CHINA KELVIN

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

6/12/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES NO; TP GIA REPORT: YES NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SLN 1806 U



INSRS:

WSP:

Tel:

Liability:

RMKS:

My Solution



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SLN 1806 U - X; SKB 813J - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: L/S S\$ 4,400

(4 days) Reduction: 45 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

6/12/2019 Confirm with Wong.

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 1

If NO or B 28, Ass. Lia:

Repair Cost: (W/ST) S\$ 4,708

Loss of Rental (LOR):

S\$ -

(- days)

Loss of Use (LOU):

S\$ 240

(\$ 60 x 4 days)

Loss of Income (LOI):

S\$ -

(\$ - x - days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

9400

Total:

S\$ 4,955.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payor 1:

S\$ 4,955.45

Name 1:

MA SOLUTION PTE LTD

Payee 1: (Strike if N/A)

S\$ -

Name 2:

Payee 3: (Strike if N/A)

S\$ -

Name 3:

Adrian

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OO / TP / WS / TP RES / OO RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLN1806U Yr Regn: 2017 AprilType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel cc 1496Colour: Black AC: Insured / Std / NI / NASp. Reading: 188140 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2U31229747Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRip / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS / DUN / EXNOVA / QY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 09/07/18Survey held at M4 SolutionDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Con Pac

(L/S 4,400 / Red \$ 3,261.68 / 45%)

mv:

pv:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS. \$

Photos

Others

TOTAL

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: LONPAC	DATE	: 08/07/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	: <i>1chancha</i>		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLN1806U		
MODEL	: HONDA VEZEL 1.5 X A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
DATE		: 06-07-2019	
TIME		: 16:50HRS	
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,055.30	\$ 1,055.30
2	FRONT BUMPER SIDE RETAINER <i>RH side</i>	2	\$ 65.90	\$ 131.80
3	FRONT BUMPER LOWER GRILLE <i>Distorted</i>	1	\$ 210.00	\$ 210.00
4	FRONT BUMPER REINFORCEMENT <i>Distorted</i>	1	\$ 360.00	\$ 360.00
5	FRONT BUMPER LOWER LID <i>Distorted</i>	1	\$ 195.30	\$ 195.30
6	FRONT GRILLE <i>Cracked</i>	1	\$ 433.00	\$ 433.00
7	FRONT GRILLE BASE <i>Cracked</i>	1	\$ 555.00	\$ 555.00
8	FRONT GRILLE LOGO <i>new</i>	1	\$ 55.00	\$ 55.00
9	HID HEADLAMP LH <i>cracked</i>	1	\$ 1,850.00	\$ 1,850.00
10	HEADLAMP LOWER BRACKET LH <i>cracked</i>	1	\$ 65.90	\$ 65.90
11	FRONT FENDER LH <i>Upper Bunched</i>	1	\$ 748.50	\$ 748.50
12	FRONT FENDER INNER COWLING LH <i>RH side</i>	1	\$ 94.80	\$ 94.80
13	WHEEL ARCH LH <i>Cracked</i>	1	\$ 210.00	\$ 210.00

TOTAL PRICE \$ 5,964.80
LESS 20% \$ 1,192.92
SUB TOTAL PRICE \$ 4,771.68

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Not Need</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>Need</i>	1	\$ 20.00	\$ 20.00
3	FRONT BUMPER LOWER GRILLE CLIPS(SET) <i>Need</i>	1	\$ 20.00	\$ 20.00
4	FRONT BUMPER CENTRE LOWER LID <i>Not Need</i>	1	\$ 400.00	\$ 400.00
5	FRONT BUMPER FOGLAMP WITH GARNISH <i>Could</i>	1	\$ 320.00	\$ 320.00
6	HEADLAMP CLIPS <i>Need</i>	1	\$ 20.00	\$ 20.00
7	FRONT GRILLE CLIP (SET) <i>Need</i>	1	\$ 20.00	\$ 20.00
8	FRONT LOGO GARNISH CLIPS (SET) <i>Not Need</i>	1	\$ 20.00	\$ 20.00
9	FRONT FENDER INNER COWLING CLIP (SET) <i>Not Need</i>	1	\$ 20.00	\$ 20.00
10	WHEEL ARCH CLIPS (SET) <i>Need</i>	1	\$ 20.00	\$ 20.00

TOTAL \$ 910.00

320

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	600	
3	WIRING CHECK	\$ 120.00	30	
4	TO REFOCUS HEADLAMP BEAM	\$ 80.00	x	

TOTAL \$2,380.00

1130

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,681.68
TOTAL LABOUR COST : \$ 2,380.00
TOTAL REPAIR COST : \$ 8,061.68

APPROVED DETAILS
SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian LG
H/S 09/07/19.

04 Days.

Total 333216

H/S A HK. ✓

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 12 July, 2019 3:15 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving SKB8213J (OI : LPC - TBA) AND SLN1806U (TP : LKK REF - CC6/LPC19012192/Aka3) on 06/07/2019 [External Confidential]
Attachments: 12072019151211.pdf
Categories: HMK

Lonpac External - Confidential


Our Ref : 18/19/19/VP05/022049

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

The premium for the policy has been settled.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 12 July, 2019 1:28 PM
To: MT_Claim_SG
Cc: ONG LI LI; GERALD POH WEE BIN; Khanchna (LKK Auto); CS A Team; Admin A
Subject: Direct Settlement - Accident Involving SKB8213J (OI : LPC - TBA) AND SLN1806U (TP : LKK REF - CC6/LPC19012192/Aka3) on 06/07/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SLN 1806U at M/s MG Solution Pte Ltd - Kaki Bukit on a WP basis and TP repairer proposed for a direct settlement.

Khanchna (LKK Auto)

From: MG Solution <mg3solution@gmail.com>
Sent: Tuesday, 18 February 2020 10:33 AM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: Re: 3rd Party Claim for Accident involving Vehicle SLN1806U & SKB8213J on 06/07/2019
Attachments: DV for SLN1806U.pdf; TI209048 for SLN1806U (SMG198281).pdf

Your Ref: **SKB8213J**

Our Ref: **SLN1806U**

Dear Khanchna,

Please find attached **TAX INVOICE** and **DISCHARGE VOUCHER** for your kind onward action.
Original copy will sent to you by post.

Best Regards,

Ms Wong
MG SOLUTION PTE LTD
No 23 Kaki Bukit Avenue 4
AAS Kaki Bukit Centre
#02-03B Singapore 415933
Tel: 6243 1373 | Fax: 6243 1376

On Tue, Dec 17, 2019 at 10:23 AM Khanchna (LKK Auto) <khanchna@lkkauto.com> wrote:

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

Thank you for the acceptance.

We attach herewith a copy of the DV.

Kindly send us (LKK) all the documents below for our necessary action: -

- **Original LOD**
- **Original Final Repair Tax Invoice**
- **Original Letter of Authorisation & hardcopy of the DV**

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: MG Solution <mg3solution@gmail.com>

Sent: Friday, 6 December 2019 9:33 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: 3rd Party Claim for Accident involving Vehicle SLN1806U & SKB8213J on 06/07/2019

Your Ref: **SKB8213J**

Our Ref: **SLN1806U**

Dear Khanchna,

We refer to below, we are pleased to accept the offer at \$4,955.45.

Please kindly let us have your **DV** soonest.

Best Regards,

Su Wong

MG SOLUTION PTE LTD

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376

On Fri, Dec 6, 2019 at 9:16 AM Khanchna (LKK Auto) <khanchna@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows:

1. Cost of Repair (w/GST)	\$ 4,708.00
2. Loss of Use (4 days x \$60)	\$ 240.00
3. LTA Search Fee	\$ 7.45
Total	\$ 4,955.45

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: MG Solution <mg3solution@gmail.com>

Sent: Wednesday, 23 October 2019 11:30 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: 3rd Party Claim for Accident involving Vehicle SLN1806U & SKB8213J on 06/07/2019

Your Ref: **SKB8213J**

Our Ref: **SLN1806U**

Dear Khanchna,

Please refer to below mentioned email, as we have sent out our LOD previously to your side on 23/08/2019.

We have not receive any offer from your side.

Resend LOD for your reference and hope to receive an offer from your side soon.

Best Regards,

Su Wong

MG SOLUTION PTE LTD

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376

On Fri, Aug 23, 2019 at 10:12 AM MG Solution <mg3solution@gmail.com> wrote:

Your Ref: **SKB8213J**

Our Ref: **SLN1806U**

Dear Khanchna,

Please find attached our LOD for your onward action. Original Copy will send to you by **POST**. Please feel free to contact the under mentioned should you require any further information. Your prompt action will be greatly appreciated.

Best Regards,

Su Wong

MG SOLUTION PTE LTD

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

X

MOTOR CLAIM DISCHARGE

INSURED: ZHEN XIANG JUN EXPRESS

CAR/LORRY/CYCLE: REG NO: SLN1806U POLICY NO:

ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle

Registered No. SLN1806U from the repairers,

Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was involved on or about the 06 day of 07 2019 have been completed to my / our satisfaction, and that

I / we have no further claim on the above company in Respect thereof.

Date: Signature:

Co's Stamp: NRIC No:



09/07/2019-PR1

Vehicle In - 09/07/2019

Vehicle Out - 12/07/2019

Lou - 4 days x \$200

= \$800



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

PROFORMA BILL

Bill To:

LONPAC INSURANCE BHD

NO.100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Bill No : 198281

Date : 23-August-2019

Vehicle Number : *SLN 1806U*

ATTN : MOTOR CLAIMS DEPARTMENT

QTY	CLAIM	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 4,400.00
BEFORE GST		4,400.00
7% GST		308.00
TOTAL		\$ 4,708.00

Tax Invoice will be issue upon amount finalised.

Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis with sole intention of resolving the matter amicably without parties resorting to legal proceeding. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.



Co's stamp & Authorised Signature




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC6/LPC19012192/Aka3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 20-02-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKB 8213J	Veh. Inspected	SLN 1806U	
Policy No.	Z18VP05021144	Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/022049	Excess (\$)	0.00	
Assign From		Assign Date	09/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31229747	Colour	BLACK	
Odometer	188140	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MICHELIN	6 mm	
L/H Front Tyre	215/60 R16	MICHELIN	6 mm	
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/07/2019	Inspection Date	09/07/2019	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 1806U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DISTORTED	1,055.30	880.00
2	FRONT BUMPER SIDE RETAINER @\$65.90	O/S NECESSARY	131.80	65.90
1	FRONT BUMPER LOWER GRILLE	DEFORMED	210.00	210.00
1	FRONT BUMPER REINFORCEMENT	BENT	360.00	360.00
1	FRONT BUMPER LOWER LID	DEFORMED	195.30	195.30
1	FRONT GRILLE	CRACKED	433.00	433.00
1	FRONT GRILLE BASE	CRACKED	555.00	268.90
1	FRONT GRILLE LOGO	NECESSARY	55.00	55.00
1	HID HEADLAMP LH	CRACKED	1,850.00	1,850.00
1	HEADLAMP LOWER BRACKET LH	CRACKED	65.90	65.90
1	FRONT FENDER LH	BUCKLED	748.50	558.70
1	FRONT FENDER INNER COWLING LH	NOT NECESSARY	94.80	-
1	WHEEL ARCH LH	CRACKED	210.00	160.00
	LESS 20% DISCOUNT		-1,192.92	-1,020.54
			4,771.68	4,082.16
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	SET FRONT BUMPER LOWER GRILLE CLIPS (SN)	NOT NECESSARY	20.00	-
1	FRONT BUMPER CENTRE LOWER LID (SN)	NOT NECESSARY	400.00	-
1	FRONT BUMPER FOGLAMP WITH GARNISH (SN)	CRACKED	320.00	250.00
1	HEADLAMP CLIPS (SN)	NECESSARY	20.00	10.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	20.00	20.00
1	SET FRONT LOGO GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET FRONT FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	20.00	-
1	SET WHEEL ARCH CLIPS (SN)	NECESSARY	20.00	20.00
			910.00	320.00
LABOUR				
	PANEL BEATING, REMOVING AND REPLACING PARTS.		1,200.00	500.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	600.00

Report Ref No. CC6/LPC19012192/Aka3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHECK.		120.00	30.00
	TO REFOCUS HEADLAMP BEAM.	NOT NECESSARY	60.00	-
			2,380.00	1,130.00
GRAND TOTAL			8,061.68	5,532.16

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00
---	--	--	--	----------

Report Ref No. CC6/LPC19012192/Aka3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.