

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: LONPAC	DATE	: 08/07/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<i>Ichancha.</i>			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLN1806U		
MODEL	: HONDA VEZEL 1.5 X A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 06-07-2019
		TIME	: 16:50HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,055.30	\$ 1,055.30
2	FRONT BUMPER SIDE RETAINER <i>RH x1</i>	2	\$ 65.90	\$ 131.80
3	FRONT BUMPER LOWER GRILLE <i>Del'd</i>	1	\$ 210.00	\$ 210.00
4	FRONT BUMPER REINFORCEMENT <i>Del'd</i>	1	\$ 360.00	\$ 360.00
5	FRONT BUMPER LOWER LID <i>Del'd</i>	1	\$ 195.30	\$ 195.30
6	FRONT GRILLE <i>Cracked</i>	1	\$ 433.00	\$ 433.00
7	FRONT GRILLE BASE <i>Cracked</i>	1	\$ 555.00	\$ 555.00
8	FRONT GRILLE LOGO <i>new</i>	1	\$ 55.00	\$ 55.00
9	HID HEADLAMP LH <i>cracked</i>	1	\$ 1,850.00	\$ 1,850.00
10	HEADLAMP LOWER BRACKET LH <i>cracked</i>	1	\$ 65.90	\$ 65.90
11	FRONT FENDER LH <i>Page Buckled</i>	1	\$ 748.50	\$ 748.50
12	FRONT FENDER INNER COWLING LH <i>x1p New</i>	1	\$ 94.80	\$ 94.80
13	WHEEL ARCH LH <i>Cracked</i>	1	\$ 210.00	\$ 210.00

5102.70

4082.16

TOTAL PRICE	\$ 5,964.60
LESS 20%	\$ 1,192.92
SUB TOTAL PRICE	\$ 4,771.68

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Not New</i>	1	\$ 50.00	\$ 50.00	f
2	FRONT BUMPER CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
3	FRONT BUMPER LOWER GRILLE CLIPS(SET) <i>me</i>	1	\$ 20.00	\$ 20.00	f
4	FRONT BUMPER CENTRE LOWER LID <i>Not New</i>	1	\$ 400.00	\$ 400.00	x
5	FRONT BUMPER FOGLAMP WITH GARNISH <i>could</i>	1	\$ 320.00	\$ 320.00	250
6	HEADLAMP CLIPS <i>New</i>	1	\$ 20.00	\$ 20.00	10.
7	FRONT GRILLE CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
8	FRONT LOGO GARNISH CLIPS (SET) <i>me</i>	1	\$ 20.00	\$ 20.00	f
9	FRONT FENDER INNER COWLING CLIP (SET) <i>Not New</i>	1	\$ 20.00	\$ 20.00	x.
10	WHEEL ARCH CLIPS (SET) <i>me</i>	1	\$ 20.00	\$ 20.00	✓
		320	TOTAL	\$ 910.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	600	
3	WIRING CHECK	\$ 120.00	30.	
4	TO REFOCUS HEADLAMP BEAM	\$ 60.00	x	
TOTAL		\$2,380.00		1130

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,681.68
TOTAL LABOUR COST : \$ 2,380.00
TOTAL REPAIR COST : \$ 8,061.68

APPROVED DETAILS

SURVEYOR :
CONTACT NO :

FAX :

Adrian Lj
h/s 09/07/19.
04 Days.

Total: 5532-16

h/s 44K. ✓

PART BY PART / LUMP SUM :
NO OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: