



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 17/07/2019 OUR REF: UAPL1278
REPAIR ESTIMATE YOUR TOYOTA MARK X NO: SJJ6192T

1 REAR BUMPER ASSY / *CPA*
2 REAR BUMPER SIDE SUPPORT HOLDER CLIPS X NN
2 REAR BUMPER TOW COVER GARNISH X NN
1 REAR R/H BUMPER INNER BRACKET X NN
10 REAR BUMPER CLIPS / *HBC*
1 REAR TAIL END PANEL X NN
1 REAR R/H TAILLAMPS ASSY X NN
1 REAR R/H EXHAUST CHROME X NN

\$ 1,965.00 *1250*
\$ 240.00
\$ 68.00
\$ 107.00
\$ 55.00
\$ 877.00
\$ 675.00
\$ 189.00
\$ 4,176.00
\$ 417.60
\$ 3,758.40

LESS 10%

SPECIAL NETT:-

1 REAR REVERSE SENSOR / *DM*

\$ 280.00 *200*

LABOUR CHARGES:-

TO DISM/REWIRE REAR DAMAGED PORTION

\$ 80.00 X NN

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS

\$ 1,000.00 *200*

TO DISM/RENEW REAR REVERSE SENSOR

\$ 80.00 *40*

TO PUTTY AND RESPRAY DAMAGED PORTION

\$ 800.00 *200*

TO SPRAY UNDERCOATING IN REPAIR

\$ 200.00 X NN
\$ 8,198.40

440

1814.5

20%: 1450

3 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: