

ASS: REC. BY:

REF:

CS/FCI19012201 (K1v3/2)

Special Instruction:

Summary: ResulASSIGNMENT (Office)From (Person): Jocanne Yongof FCIDate/Time: 9/7/19 @ 2:13pm

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLC 1084T

Insured:

SHD 3027M

at Workshop m/s

Tc Autoclinic

Tel:

6 703 8432

of

No. 1 sixth tokyong Road

Policy No.:

Claim No.:

D1900 4436 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/7/2019

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

3:08pm @ 9/7/19

Person Contacted:

HOVehicle IN / OUT

Date/Time

Action/Instruction

Volume/✓

SHD 3027M : CS3/FCI18016556/ACD/352 D.O.A. 30/6/2018

SLC 1084T : CC6/A2G17007241/UPH352 D.O.A. 10/6/2017

23/7/19

Email preli revised to FCI

2/8/19

Submit preli report

MOTOR SURVEY ASSIGNMENT

Date	08-07-2019	Our Ref No. D19004436MFSH
Accident Date	04-07-2019	Claim Type. Third Party
Insured Vehicle	SHD3027M	Third Party Vehicle. SLC1084T
Survey Location	NO. 1 SIXTH LOK YANG ROAD	
Contact Person.	YM HO	
Contact No.	67038432/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TC AUTOCLINIC PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 23 July 2019 12:15 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004436MFSH/1-SLC 1084T
Attachments: SLC 1084T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLC 1084T

Date of survey: 22/7/2019

Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 10 July 2019 4:56 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004436MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 9 July 2019 2:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong

<Joanneyong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19004436MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004436MFSH

Our Ref: CS/FCI19012201/R1vf3

Date : 23/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO: SLC 1084T


We thank you for your instruction on 9/7/2019

Please be informed that we had conducted the inspection of the above mentioned 22/7/2019 at the premises of M/s TC AUTOCLINIC PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$11,753.20
Revised Estimate Amount	: S\$2,944.52
"Check" Items Amount	: S\$1,813.36
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor



CERTIFICATE OF INSURANCE

NISSAN AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Teresa Lim Lay Hong
Period of Insurance : 29 Apr 2019 To 28 Apr 2020
Engine No. : HRA2267146A
Chassis No. : SJNFEAJ11U1647431

Vehicle No. : SLC1084T
Policy No. : 2100463856-03
Endorsement No. :
Issued Date : 04 Apr 2019

ABOUT THE COVER

Make/Model : NISSAN QASHQAI 1.2 DIG-TURBO
Engine Capacity/Tonnage : 1,197.00 CC
Sum Insured :
Market Value :
Driver Restriction : NA
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

1. The Policyholder
 2. Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of S\$ 500 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1800cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

EXCESS

Section 1

Fire - S\$ Own Damage - S\$2000 Theft - S\$ Flood Cover - S\$

Section 2

Property Damage - S\$

Windscreen : S\$100

Named Driver and Excess (where applicable)*

Teresa Lim Lay Hong - S\$2000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. TC AutoClinic Add: No. 1, Seah Lim Yang Road Singapore 526099 62622512
2. Autolution Industrial Add: 19 Ubi Road 4 Singapore 409523 64909695
3. TC AutoClinic Add: 25 Leng Kee Road Singapore 159097 57039511 67039512 67039513
4. Tan Chong Motor Sales Add: 913 Bukit Timah Road Singapore 589623 64694091 64694092 64694093
5. Tan Chong Motor Sales Add: 17 Lorong 8 Toa Payoh Singapore 319254 62570753 62570754

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan : DBS BANK LTD

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).)

0500610528

TAN CHONG CREDIT PTE LTD - TKH
 911 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE
 SINGAPORE 589622 ANSP-MOTOR
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

53074

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1767719E



TERESA LIM LAY HONG
林麗鴻
Race: CHINESE
Date of Birth: 28-03-1966
Gender: F
MARRIAGE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S1767719E
Name: TERESA LIM LAY HONG
Issue Date: 25 Mar 1997
Expire Date: 24 Apr 2004

001293296C

NRIC No. S1767719E

RESIDENCE

APT BLK 124 SERANGOON NORTH AVENUE #04-05
SINGAPORE 550124
NRIC No: S1767719E Date: 18-08-2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Description	Issue Date
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	22 Aug 1997

NP 428A

License No. S1767719E



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/07/2019 11:50
Date Of Accident	04/07/2019 22:00
Exact Location Of Accident	PIE BEFORE BKE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC1084T
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	TERESA LIM LAY HONG
NRIC No	S1767719E
Email Address	BADFRIEND66@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97646343
Alternative Phone No	OTHERS-97646343

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI-1.2 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100463856-03
Cover Note Number	

Driver

Name of Driver	TERESA LIM LAY HONG
NRIC No	S1767719E
Date Of Birth	25/03/1966
Occupation	INDOOR
Date Of Driving Pass	22/08/1997
Driving Experience	21 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97646343
Fax Number	
Contact Number	OTHERS-97646343
Email Address	BADFRIEND66@HOTMAIL.COM

Address	BLK 124 SERANGOON NORTH AVE 1 #04-85
Postcode	550124
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD3027M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	MUHAMMAD REYES VIJAY@VIJAY
NRIC/Passport Number	S7614624A
Contact Number	91146503
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required;
 - (ii) for complying with requirements under any regulations, laws or court orders.

TAN HONG MOTOR SALES PTE LTD
 17 Toa Payoh Lorong 8
 Singapore 319254
 Tel: 6357 0756 Fax: 6356 4922

Policyholder's Signature
Date & Time:

RM 5/7/19, 10.15 hrs


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *Aishah*
NRIC/FIN No.: *51660822/2*

AM

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7 Jul 2019, abt 2200hrs, while I was driving along PIE, a car in front of me suddenly jam-braked, but as I had kept my ~~safe~~ safety distance, I was able to brake & avoided the car. But the taxi behind me had tailgated me quite closely hit my ~~car~~ car from the back.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature] 5/7/19; 1015hrs

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

AN CHONG MOTOR SALES PTE LTD
17 Tuu Payoh Lorong 6
Singapore 319254
Tel: 6357 0758 Fax: 6356 4922

[Signature]
Reporting Centre Personnel's Signature
Name: Aishah
NRIC/FIN No.: S1660831/2

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 122/IC/TC/HO/2019

DATE : 06-JUL-2019

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

owner claim 104

OWNER'S NAME : MISS TERESA LIM LAY HONG
ADDRESS : BLK 124 SERANGOON NORTH AVENUE 1
#04-85
S(550124)
TELEPHONE NO : 97646343

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : MS FIRST CAPITAL 3RD PARTY DIR
VEHICLE NO : SLC1084T (2964-2016)
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2267146A
CHASSIS NO : SJNFEAJ11U1647431
MILEAGE : 1 KM 48439
DATE IN : 06/07/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 04/07/2019

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLC1084T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-REAR	60.00	X
2	RCI	REMOVE/INSTALL REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	X
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
4	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	/
5	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00/PANEL X 2 PANELS	200.00	100?
6	ZZ/001	REMOVE/INSTALL REAR BUMPER, END PANEL, BACK DOOR AND AFFECTED PORTION. REPAIR LHR FENDER AND RHR FENDER	1560.00	780
7	ZZ/002	RESPRAY PAINT REAR BUMPER, END PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER	1600.00	625
8	ZZ/003	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	240.00	60
9	ZZ/004	TRANSFER BACK DOOR MECHANISM TO NEW DOOR AND CHECK DOOR CENTRAL LOCKING SYSTEM	80.00	X
10	ZZ/005	RENEW BACK DOOR WINDSCREEN GLASS	240.00	X
11	ZZ/006	RENEW BACK DOOR WINDSCREEN GLASS SOLAR FILM	150.00	X
12	ZZ/007	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	/
TOTAL LABOUR CHARGES			4500.00	

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLC1084T

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	CLIP-LH REAR OVER FENDER @\$2.50EACH X3PCS <i>ue</i>	76847-JG00A	7.50		
2	CLIP-LH REAR OVER FENDER @\$2.50EACH X3PCS <i>ue</i>	76847-4EA0A	7.50		
3	OVER FENDER-REAR,LH <i>de</i>	93829-4EA0A	483.00		
4	CLIP-REAR LUGGAGE PLATE @\$1.20EACH X2PCS ?	01553-05933	2.40		
5	CLIP-REAR LUGGAGE PLATE @\$1.20EACH X4PCS ?	01554-00181	4.80		
6	PLATE-LUGGAGE,REAR ?	84992-4EA0A	127.00		
7	DRAFTER-AIR @\$62.30EACH X2PCS ?	76804-JD00A	124.60		
8	LOCK ASSY-BACK DOOR <i>X nn</i>	90502-4EA1B	154.80		
9	WEATHER STRIP-BACK DOOR <i>X nn</i>	90830-4EA0B	158.70		
10	BUMPER RUBBER-BACK DOOR @\$6.50EACH X2PCS <i>X nn</i>	90878-4EA0A	13.00		
11	EMBLEM-REAR <i>X nn</i>	90892-4EA0A	87.00		
12	EMBLEM-REAR <i>X nn</i>	90890-4EA0A	59.70		
13	REAR W/SCREEN SEALANT <i>X nn</i>	SEALANT - 4			80.00
14	RUBBER-DUM <i>X nn</i>	G2G16-89901	60.20		
15	GLASS-BACK DOOR WINDSCREEN GLASS <i>X nn</i>	90300-4EA0D	930.00		
16	DOOR ASSY-BACK <i>X nn</i>	K0100-HV0MB	2936.80		
17	LH REAR BUMPER STAY ?	H5211-4EAMA	126.00		
18	RH REAR BUMPER STAY ?	H5210-4EAMA	126.00		
19	REAR BUMPER REINFORCEMENT ?	H5030-4EAMA	619.20		
20	REAR BUMPER ENERGY ABSORBER ?	85090-4EA0B	126.40		
21	RETAINER-REAR BUMPER SIDE,RH <i>ue</i>	79184-4EA0A	23.80		
22	RETAINER-REAR BUMPER SIDE,LH <i>ue</i>	79185-4EA0A	23.80		
23	RH REAR BUMPER SIDE BRACKET <i>ue</i>	85220-4EA0A	35.90		
24	LH REAR BUMPER SIDE BRACKET <i>ue</i>	85221-4EA0A	35.90		
25	CANOE RIVET-REAR BUMPER @\$6.50EACH X2PCS <i>ue</i>	76882-0M000	13.00		

TC AUTOCLINIC PTE LTD
 1 SIXTH LOK YANG ROAD
 SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLC1084T

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 REAR BUMPER UPPER CLIP @\$7.40EACH X3PCS <i>m/</i>	85284-JD00A	22.20		
27 REAR BUMPER LOWER CLIP @\$1.20EACH X4PCS <i>m/</i>	01553-05933	4.80		
28 REVERSE SENSOR(4EYE) <i>m/</i>	SENSOR-4-FUM			250.00
29 FINISHER-REAR BUMPER <i>X nn</i>	85071-4EA0A	16.80		
30 REAR BUMPER FASCIA <i>de/</i>	85022-4EA0H	717.00		
31 REAR END PANEL <i>repair?</i>	G9110-4EAMA	436.60		
32 LAMP ASSY-REAR COMBI,RH TRUNK <i>X nn</i>	26550-4EA5E	306.30		
33 LAMP ASSY-REAR COMBI,LH TRUNK <i>X nn</i>	26555-4EA6E	215.90		
34 LAMP ASSY-REAR COMBI,RH <i>X nn</i>	26550-4EA0A	323.70		
35 LAMP ASSY-REAR COMBI,LH <i>?</i>	26555-4EA0A	323.70		
SUB TOTAL		8654.00	0.00	330.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1730.80	0.00	0.00
GRAND TOTAL		6923.20	0.00	330.00
OVERALL TOTAL		7253.20		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLC1084T

TOTAL LABOUR CHARGES	4500.00
TOTAL SPARE PARTS CHARGES	7253.20
GRAND TOTAL	11753.20 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Rasul - Hp 90010062

5 days

22/07/19 e1155

Resny bekm perhit

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


23/7/19

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 2 August 2019 11:39 AM
To: Ho Yue Meng; SUR
Subject: RE: SLC 1084T-DOA: 4/7/2019

Dear Yue Meng,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ho Yue Meng <ho_yue_meng@tanchong.com>
Sent: Friday, 2 August 2019 11:23 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SLC 1084T-DOA: 4/7/2019
Importance: High

Dear Ms Veron,

Owner was involved in a separate accident (Own Damage) and the vehicle was beyond economical repair.

Therefore, owner will not proceed with the direct settlement repair in this case.

You may close your case at your side.

Thank-you.

Best Regards
YM Ho
TC Autoclinic Pte Ltd
No 1 Sixth Lok Yang Road
Singapore 628099
DID : 67038432

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: 1 August, 2019 2:21 PM
To: Norsipah <norsipah@tanchong.com>; Ho Yue Meng <ho_yue_meng@tanchong.com>
Subject: SLC 1084T-DOA: 4/7/2019

Dear Sipah/Mr Ho,

- Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19012201/R1vf3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-08-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3027M	Veh. Inspected	SLC 1084T
Policy No.		Coverage (\$)	0.00
Claim No.	D19004436MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	09/07/2019
2. Vehicle Particulars & Condition			
Make & Model	NISSAN QASHQAI 1.2	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	SJNFEAJ11U1647431	Colour	GREY
Odometer	48439	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	CONTINENTAL	6 mm
L/H Front Tyre	215/60 R16	CONTINENTAL	6 mm
R/H Rear Tyre	215/60 R16	CONTINENTAL	6 mm
L/H Rear Tyre	215/60 R16	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/07/2019	Inspection Date	22/07/2019
Survey held at	TC AUTOCLINIC PTE LTD 1 SIXTH LOK YANG ROAD SINGAPORE 628099		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 1084T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
3	CLIP-LH REAR OVER FENDER @\$2.50 (N)	NECESSARY	7.50	7.50
3	CLIP-LH REAR OVER FENDER @\$2.50 (N)	NECESSARY	7.50	7.50
1	OVER FENDER-REAR, LH (N)	DEFORMED	483.00	483.00
2	CLIP-REAR LUGGAGE PLATE @\$1.20 (N)	* CHECK	2.40	-
4	CLIP-REAR LUGGAGE PLATE @\$1.20 (N)	* CHECK	4.80	-
1	PLATE-LUGGAGE, REAR (N)	* CHECK	127.00	-
2	DRAFTER-AIR @\$62.30 (N)	* CHECK	124.60	-
1	LOCK ASSY-BACK DOOR (N)	NOT NECESSARY	154.80	-
1	WEATHER STRIP-BACK DOOR (N)	NOT NECESSARY	158.70	-
2	BUMPER RUBBER-BACK DOOR @\$6.50 (N)	NOT NECESSARY	13.00	-
1	EMBLEM-REAR (N)	NOT NECESSARY	87.00	-
1	EMBLEM-REAR (N)	NOT NECESSARY	59.70	-
1	RUBBER-DUM (N)	NOT NECESSARY	60.20	-
1	GLASS-BACK DOOR WINDSCREEN GLASS (N)	NOT NECESSARY	930.00	-
1	DOOR ASSY-BACK (N)	NOT NECESSARY	2,936.80	-
1	LH REAR BUMPER STAY (N)	* CHECK	126.00	-
1	RH REAR BUMPER STAY (N)	* CHECK	126.00	-
1	REAR BUMPER REINFORCEMENT (N)	* CHECK	619.20	-
1	REAR BUMPER ENERGY ABSORBER (N)	* CHECK	126.40	-
1	RETAINER-REAR BUMPER SIDE, RH (N)	NECESSARY	23.80	23.80
1	RETAINER-REAR BUMPER SIDE, LH (N)	NECESSARY	23.80	23.80
1	RH REAR BUMPER SIDE BRACKET (N)	NECESSARY	35.90	35.90
1	LH REAR BUMPER SIDE BRACKET (N)	NECESSARY	35.90	35.90
3	REAR BUMPER UPPER CLIP @\$7.40 (N)	NECESSARY	22.20	22.20
4	REAR BUMPER LOWER CLIP @\$1.20 (N)	NECESSARY	4.80	4.80
1	FINISHER-REAR BUMPER (N)	NOT NECESSARY	16.80	-
1	REAR BUMPER FASCIA (N)	DEFORMED	717.00	717.00
1	REAR END PANEL (N)	* CHECK	436.60	-
1	LAMP ASSY-REAR COMBI, RH TRUNK (N)	NOT NECESSARY	306.30	-
1	LAMP ASSY-REAR COMBI, LH TRUNK (N)	NOT NECESSARY	215.90	-
1	LAMP ASSY-REAR COMBI, RH (N)	NOT NECESSARY	323.70	-

Report Ref No. CS/FCI19012201/R1v3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LAMP ASSY-REAR COMBI, LH (N)	* CHECK	323.70	-
2	CANOE RIVET-REAR BUMPER @\$6.50 (N) LESS 20% DISCOUNT	NECESSARY	13.00	13.00
			-1,730.80	-274.88
			6,923.20	1,099.52
	<u>SPECIAL NETT ITEMS</u>			
1	REAR W/SCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (4EYE) (SN)	NECESSARY	250.00	250.00
			330.00	250.00
	<u>LABOUR</u>			
	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-REAR.	NOT NECESSARY	60.00	-
	REMOVE / INSTALL REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST.	NOT NECESSARY	120.00	-
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	NOT NECESSARY	120.00	-
	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST.		110.00	110.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00/PANEL X 2 PANELS.	* CHECK	200.00	-
	REMOVE / INSTALL REAR BUMPER, END PANEL, BACK DOOR AND AFFECTED PORTION. REPAIR LHR FENDER AND RHR FENDER.		1,560.00	780.00
	RESPRAY PAINT REAR BUMPER, END PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER.		1,600.00	625.00
	REMOVE / INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR.		240.00	60.00
	TRANSFER BACK DOOR MECHANISM TO NEW DOOR AND CHECK DOOR CENTRAL LOCKING SYSTEM.	NOT NECESSARY	80.00	-
	RENEW BACK DOOR WINDSCREEN GLASS.	NOT NECESSARY	240.00	-
	RENEW BACK DOOR WINDSCREEN GLASS SOLAR FILM.	NOT NECESSARY	150.00	-
	CHECK REAR LIGHTINGS AND WIRING SYSTEM.		20.00	20.00
			4,500.00	1,595.00
GRAND TOTAL			11,753.20	2,944.52

Report Ref No. CS/FCI19012201/R1v3e2



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,813.36 NETT)				2,944.52
---	--	--	--	----------

Report Ref No. CS/FCI19012201/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.