

Trans-cab Auto Services Pte Ltd

AAD1907-087

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9500Z

*Not Authorized
Resurvey B4paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

09 JUL 2019

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9500Z

JTDKB3FU403080996

TOYOTA

PRIUS

8.7.19

AXA

31/5/2019

		PART		LIST	
1	1	REAR BUMPER	\$	Bu 458.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$	318.80	?
3	1	REAR BUMPER TOWING COVER	\$	na 14.70	✓
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	Bu/na 552.60	✓
5	1	REAR BUMPER SIDE RETAINER LH	\$	su 112.70	} X
6	1	REAR BUMPER SIDE RETAINER RH	\$	su 112.70	
7	1	REAR TAILGATE	\$	na 1,547.27	
8	1	REAR TAILGATE OUTER GARNISH	\$	su 905.10	
9	1	COVER, REAR COMBINATION LAMP, RH	\$	su 54.70	
10	1	COVER, REAR COMBINATION LAMP, RH	\$	su 54.70	
11	1	GARNISH, BACK DOOR SIDE, LH	\$	su 93.60	
12	1	GARNISH, BACK DOOR SIDE, RH	\$	su 93.60	
13	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	su 55.40	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	su 55.40	
15	1	BOARD ASSY, BACK DOOR TRIM	\$	su 254.40	
16	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	su 51.20	
17	1	REAR TAILGATE WEATHERSTRIP	\$	su 365.20	
18	1	REAR END PANEL	\$	na 602.10	
19	1	TAILLAMP LOWER RH	\$	su 548.40	
20	1	TAILLAMP UPPER RH	\$	su 557.90	
21	1	REAR BUMPER SIDE RH	\$	na/na 232.00	✓
22	1	REAR BUMPER SIDE LH	\$	su 232.00	X
23	1	TAILLAMP LOWER LH	\$	su 548.40	} X
24	1	TAILLAMP UPPER LH	\$	su 557.90	
25	1	REAR FENDER RH	\$	na 817.50	
26	1	REAR FENDER LH	\$	na 817.50	
27	1	BOARD, BACK DOOR TRIM	\$	su 220.70	
28	1	PAN, REAR FLOOR	\$	na 572.10	
29	1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	na 77.00	

Trans-cab Auto Services Pte Ltd

AAD1907-087

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9500Z

30	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	<i>na</i>	192.90 X
31	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	<i>na</i>	77.00 X
32	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	<i>na</i>	192.90 X
33	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	<i>na</i>	290.50 X

TOTAL	\$	11,637.47
25%	\$	2,909.37
	\$	8,728.10

Special Nett

1	1SET PARKING AID	\$	<i>Phay</i>	700.00 <i>2500</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	22.00
3	2 REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00
4	1 WINDSCREEN MOULDING	\$	<i>na</i>	100.00
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>na</i>	47.00
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i>	52.90
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i>	53.50
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i>	80.00
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i>	80.00
11	1 REAR BUMPER PROTECTOR	\$	<i>na</i>	100.00

TOTAL	\$	1,415.40
--------------	-----------	-----------------

TOTAL PARTS	\$	10,143.50
--------------------	-----------	------------------

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *na* 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 4,500.00 *2000*

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ *na* 170.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 *2800*

Trans-cab Auto Services Pte Ltd

AAD1907-087

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9500Z

To transfer of rear windscreen fittings and conduct water seepage test.	\$	na	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	na	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00	X
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	151
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na	380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	na	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	380.00	X
TOTAL	\$		12,100.00	
Over All Total	\$		22,243.50	

(PART-BY-PART) Repair Days ~~15 Days~~ **2 days**

ERK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: