

155Q110

INS. CASE OWNER:

CC 3/AIG1901 2205, PK # 52 S3

LKK:
IDAC:

Surveyor: Keaneth DOI: ASSIGNMENT 1/3/19 Date / Time: 1/3/19
Registered in Merimen: 10/3/19

Pre-assign / CCU / FTE



Insured Vehicle No.: SKP 6900Z Claim No.: 64242464159
Name of Insured: UM 200 VENG LIM RUMING Policy No.:
Insured Tel No.: HP: Make / Model :
Excess Sec II :SS D.O.A: 5/3/19 Place of Accident :
Is driver the owner? (YES / NO) Nature of Accident :
If NO. Driver Name / Age: OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO
Driver Tel No.: (V/L YES / NO) Insured Liability: % Final ? Yes / No

SMD 55AP



INRS: TRANS
WSP: CAB
Tel:
Liability:
RMKS:



INRS:
WSP:
Tel:
Liability:
RMKS:



INRS:
WSP:
Tel:
Liability:
RMKS:



INRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
SMD 55AP - SKP 6900Z -	Non-Reporting ltr (1st):	
no OI GIA. CBWT UNT 2ST LETTER.	Non-Reporting ltr (2nd):	
24/7 OI GIA Report in.	Non-Reporting ltr (Final):	
17/3/20 KHONCHRA	Notification ltr (if non-pickup):	
File pass to mk to close.	Call OI:	1/25/19 KHONCHRA
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by:

FINALIZATION Date/Time: Confirm with: Confirm by: Repair Cost: PIP SS 3,044.34 (2 days) Reduction: 89 % Email Call

FINAL SETTLEMENT Date/Time: 7/3/2020 Confirm with: Jasmine Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27
Repair Cost: (CALC) SS 3,257.44
Loss of Rental (LOR): SS 202.54 (2 days) x \$101.27
Loss of Use (LOU): SS (S x - days)
Loss of Income (LOI): SS (S x - days)
LOR only LOU only LOR + LOU LOR + LO (Tick only one)
GIA/LTA Search SS 7.49
Medical: SS
Disbursement: SS (e.g. Tow/ Independent)
Legal Cost SS
Total: SS 3467.47 Global Sum SS: 3,400
If NO or B 28, Ass. Lia: (O/D REAR END TP)
COPIY SENT 19/3/2020
1) Claim status: Normal/Reject/Private Settle
2) Report Format: TR
3) Survey fee: \$320

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 3,400 Name 1: TRANS-CAB SERVICES PTE LTD
Payee 2: (Strike if N.A.) SS Name 2:
Payee 3: (Strike if N.A.) SS Name 3:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 559P

AAD1907-076

Not Authorized

Resurvey B4 paint

83044.34

Vehicle No.:
 Chassis No.: 09 JUL 2019
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD 559P
 VF1ABL15AUC283471
 RENAULT
 LATITUDE
 5.7.19
AIG
 3/7/2017

PART		LIST	
1	1 BUMPER COVER REAR	\$ Bu	1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ N.1/6 Bu	768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ Su	113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$ Su	135.97 X
5	1 BUMPER RETAINER RH REAR	\$ Su	44.99 X
6	1 BUMPER REFLECTOR RH	\$ Su	43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$ Su	135.97 X
8	1 BUMPER RETAINER LH REAR	\$ Su	44.99 X
9	1 BUMPER REFLECTOR LH	\$ Su	43.61 X
10	1 BUMPER BEAM REAR	\$ Bu	777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ N	225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$ N	225.95
13	1 OUTER PANEL REAR (End Panel)	\$ N	1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM	\$ Su	404.56
15	1 TAILLAMP RH	\$ Su	552.55
16	1 TAILLAMP PANEL RH	\$ N	986.70
17	1 TAILLAMP LH	\$ Su	552.55
18	1 TAILLAMP PANEL LH	\$ N	986.70
19	1 BOOT REAR	\$ N	2,872.68 X
20	1 BOOT FINISHER	\$ Su	470.06
21	1 BOOT WHEATERSTRIP	\$ Su	323.05
22	1 BOOT REFLECTOR LAMP LH	\$ Su	493.35
23	1 BOOT REFLECTOR LAMP RH	\$ Su	493.35
24	1 BOOT BADGE 'RENAULT'	\$ N	225.36
25	1 BOOT BADGE	\$ N	225.36
26	1 BOOT STRUT LH	\$ Su	276.08
27	1 BOOT STRUT RH	\$ Su	276.08
28	1 BOOT HINGE LH	\$ N	367.84
29	1 BOOT HINGE RH	\$ N	367.84

Trans-cab Auto Services Pte Ltd

AAD1907-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 559P

30	1	BOOT INNER TRIM	\$	<i>Pn</i>	586.45	X
31	1	BOOT SWITCH	\$	<i>Sn</i>	168.13	X
32	1	BOOT LOCK	\$	<i>n</i>	202.67	X
33	1	BOOT LOCK CATCH	\$	<i>n</i>	74.40	X
TOTAL			\$		16,046.87	
10%			\$		1,604.69	
			\$		14,442.19	

Special Nett

1	1SET	PARKING AID	\$	<i>Pn</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>n</i>	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>n</i>	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>n</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>n</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>n</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>n</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>n</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>n</i>	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	<i>n</i>	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	<i>n</i>	30.00	
12	1	EXHAUST MOUNTING REAR	\$	<i>n</i>	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	<i>n</i>	80.00	
14	1	WINDSCREEN MOULDING	\$	<i>n</i>	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>n</i>	100.00	
16	1	BOOT INNER TRIM CLIP	\$	<i>n</i>	45.00	
17	1SET	BOOT FINISHER CLIP	\$	<i>n</i>	24.20	
18	1	TAILLAMP CLIP LH	\$	<i>n</i>	5.00	
19	1	TAILLAMP CLIP RH	\$	<i>n</i>	5.00	
TOTAL			\$		1,384.02	

TOTAL PARTS \$ 15,826.21**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	<i>10/</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>n</i>	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1907-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 559P

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nr</i> 380.00 X
To Rust-Proofing Of The Affected Areas.	\$	<i>nr</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 <i>2001</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>2201</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nr</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nr</i> 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nr</i> 380.00 X

TOTAL \$ 11,550.00

Over All Total \$ 27,376.21 *19*

PART BY PART (REPAIR DAY)

L&K Auto Consultants has approved the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

15 DAYS
2 day,

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD559P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Jul 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003252
Chassis No.:	VF1ABL15AUC283471
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	03 Jul 2017
First Registration Date:	03 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jul 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	
PQP Paid:	\$: 160.00
COE Rebate Amount:	€ 838.00
Total Rebate Amount:	43,836.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Jul 2019

OK

View Received Message

This mail is associated with :

***SHD559P (6424214641SG)
[SKP6900Z]**

TP
TRANS-CAB SERVICES PTE LTD
Jul 5 2019 8:00PM
[LIM JOO LENG (LIN RULING)]
Trans-cab Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 11/07/2019 09:53 AM.
To LKK_HQ
Subject No OI GIA Report

Hi,

Please be informed that no OI GIA report received till date,
Please find OI details below for your further action.

OI name: LIM JOO LENG (LIN RULING)

Address:
202B SENGKANG EAST ROAD
#09-74
Singapore 542202

Contact No: 97235186

Email Address: mabelim21@yahoo.com.sg

Regards,
Wah Xin

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19012205/Kwb3

16 July, 2019

LIM JOO LENG (LIN RULING)
202B SENGKANG EAST ROAD #09-74
Singapore 542202

Dear Sirs,

**ACCIDENT INVOLVING SKP 6900Z AND SHD 559P ON 05/07/2019 ALONG
/AT BOON LAY WAY**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vivian Lau
Claims
Tel : 6841 8625
Fax: 6741 4108
Email : vivianlau@lkkauto.com

*c.c. Claims Manager
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 26 August 2019 2:01 PM
To: claims@transcab.com.sg; jasminetan@transcab.com.sg; Ng Wai Yin
Cc: Admin A
Subject: ACCIDENT INVOLVING SHD 559P (TP) & SKP 6900Z (OI-AIG) ON 05/07/2019
Attachments: TP ESTIMATE- MARKED.pdf

Tracking:	Recipient	Delivery
	claims@transcab.com.sg	
	jasminetan@transcab.com.sg	
	Ng Wai Yin	
	Admin A	
	olivialau@lkkauto.com	Delivered: 26/8/2019 2:01 PM
	Meikwan@lkkauto.com	Delivered: 26/8/2019 2:01 PM
	shupei@lkkauto.com	Delivered: 26/8/2019 2:01 PM

Without Prejudice

YOUR REF: AAD1907-076
OUR REF: CC3/AIG19012205/Kkb3

Dear Sir/Madam,

The above matter and your LOD dated 18/7/2019 refers.

Kindly let us have your breakdown for loss of rental for 6 days as our surveyor's recommended days of repair is 2 days.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 4 March 2020 3:40 PM
To: Ng Wai Yin
Cc: Admin A; 'claims'
Subject: RE: ACCIDENT INVOLVING SHD 559P (TP) & SKP 6900Z (OI-AIG) ON 05/07/2019 -- AAD1907-076

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement on a global sum for **\$3,400.00(all in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Monday, 26 August 2019 2:41 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; 'claims' <claims@transcab.com.sg>

Subject: FW: ACCIDENT INVOLVING SHD 559P (TP) & SKP 6900Z (OI-AIG) ON 05/07/2019 -- AAD1907-076

WITHOUT PREJUDICE

Dear Khanchna

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 11 March 2020 10:28 AM
To: Jasmine Tan; 'Ng Wai Yin'
Cc: Admin A; 'claims'
Subject: RE: ACCIDENT INVOLVING SHD 559P (TP) & SKP 6900Z (OI-AIG) ON 05/07/2019 -- AAD1907-076
Attachments: AIG DV.pdf

WITHOUT PREJUDICE

Dear Sir/Madam,

Thank you for the acceptance.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jasmine Tan <jasminetan@transcab.com.sg>

Sent: Saturday, 7 March 2020 12:37 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; 'claims' <claims@transcab.com.sg>

Subject: RE: ACCIDENT INVOLVING SHD 559P (TP) & SKP 6900Z (OI-AIG) ON 05/07/2019 -- AAD1907-076

Without Prejudice

Dear Khanchna

Please proceed to send us the DV.

Khanchna (LKK Auto)

From: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>
Sent: Tuesday, 3 March 2020 5:23 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: Your Ref: TP / 6424214641SG [ACCIDENT INVOLVING SHD 559P & SKP 6900Z [AIG] ON 05/07/2019]

Dear Khanchna,

You may offer up to global sum \$3,500.00 for this case. Kindly settle at best.

Best regards,
Chan Kian Meng
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1678
KianMeng.Chan1@aig.com | www.aig.sg

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Tuesday, January 21, 2020 9:23 AM
To: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: [EXTERNAL] RE: Your Ref: TP / 6424214641SG [ACCIDENT INVOLVING SHD 559P & SKP 6900Z [AIG] ON 05/07/2019]

This message is from an external sender; be cautious with links and attachments.

Dear Mr. Chan,

Summary mandate IA uploaded in Merimen.

All the relevant documents had been uploaded in Merimen.

For your approval please.

Thank you.

Wishing you a Happy and Prosperous Lunar New Year



Best Regards,
Khanchna | Case Handler

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jul 2019 Edit Reg		09 Jul 2019 00:00 Edit Adj Rpt	S\$3,044.34 Edit Estimates	S\$3,044.34 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LIM JOO LENG (LIN RULING) , ID: S7906655I		
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD559P	Date of Loss:	05/07/2019 20:00 - :59 [24 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6424214641SG	Policy/Cover Note No.:	1900067730 (Comprehensive)
Vehicle Reg. No. (Insured):	SKP6900Z	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (03/03/2020): Alert - Adj Mandate Approved (S\$3500.00) - SHD559P - Claim Handler: Chan, Kian-M...
- AIG_SG (11/07/2019): No OI GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD559P (6424214641SG)**
[SKP6900Z]
TP
TRANS-CAB SERVICES PTE LTD
Jul 5 2019 8:10PM
[LIM JOO LENG (LIN RULING)]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser ▾
Letters/Correspondences			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	26/08/19 16:18	Adjuster Immediate Advice		Load HTM
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	23/07/19 15:11	Accident Statement From:SC - Reg. No: SKP6900Z, Claimant: LIM JOO LENG (LIN RULING)		Load HTM
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
2	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
3	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
4	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
5	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
6	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
7	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
8	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
9	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
10	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
11	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
12	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
13	26/08/19 16:00	Chassis Number		Load JPG <input checked="" type="checkbox"/>
14	26/08/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	11/07/19 09:11	TP ESTIMATE- MARKED.		Load PDF
2	11/07/19 09:11	TP GIA REPORT.		Load PDF
3	16/07/19 09:52	Non reporting letter		Load PDF
4	25/07/19 14:10	LETTER TO OI		Load PDF
5	18/02/20 08:54	TP LOD, Final Repair Invoice, Rental supporting doc and LTA Search Fee		Load PDF
6	31/03/20 14:09	Authorisation to Act		Load PDF
7	31/03/20 14:09	LOD		Load PDF
8	31/03/20 14:09	LTA SEARCH		Load PDF
9	31/03/20 14:09	Release Voucher		Load PDF
10	31/03/20 14:09	RENTAL MILEAGE		Load PDF
11	31/03/20 14:09	RENTAL RECEIPT		Load PDF
12	31/03/20 14:09	WORKSHOP INVOICE		Load PDF

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKP6900Z (Insd veh)	Model:	RENAULT LATITUDE 2.0 L (A)
	SHD559P (TP veh)		
Date of Accident:	05/07/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:\$		29,292.52
Final Repair Cost	:\$		3,400.00
Loss of Use	:\$		days at \$0.00 per day
Rental (if any)	:\$		2 days
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$		3,400.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	:\$	3,400.00
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

31 Mar
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19012205/KKS3S2
Date: 31/03/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900067730
Claimant Vehicle No :	SHD559P	Insured Vehicle No :	SKP6900Z
Date of Loss:	05/07/2019	Nature of Claim:	TP
		Claim No:	6424214641SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD559P	Engine No:	M9R8839C003252
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC283471
Reg. Date:	03/07/2017 (Man. Year: 2016)	Odometer:	224635 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,826.19	2,554.34	13,271.85	83.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,550.00	490.00	11,060.00	95.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,376.19	3,044.34	24,331.85	88.88
+ GST 7.00/7.00% (S\$)	1,916.33	213.10	1,703.23	88.88
Nett Amount (S\$)	29,292.52	3,257.44	26,035.08	88.88
+ Car Rental (2.0 x S\$101.27/day) (S\$)		202.54		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,467.47		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment:	09/07/2019		
Date Inspected:	09/07/2019	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

3/31/2020

Adjuster Report

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*-FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*-FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*-FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*-FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*-FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*-FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*-FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*-FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*-FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*-FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*-FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*-FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*-FL
18	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*-FL
19	1		*BOOT REAR	Repair	2,872.68 FL	*-FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*-FL
21	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*-FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*-FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*-FL
24	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*-FL
25	1		*BOOT BADGE	Not Necessary	225.36 FL	*-FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*-FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*-FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*-FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*-FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*-FL
31	1		*BOOT SWITCH	Serviceable	168.13 FL	*-FL
32	1		*BOOT LOCK	Repair	202.67 FL	*-FL
33	1		*BOOT LOCK CATCH	Repair	74.40 FL	*-FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*-FS
35	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
39	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
40	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
41	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
42	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
43	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS
44	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS
45	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*-FS
46	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
47	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
48	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
49	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
50	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
51	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	10.00
2	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
4	TO RUST-PROOFING PF THE AFFECTED AREAS.	New	170.00	0.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
7	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	4,500.00	200.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	4,500.00	220.00
9	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
12	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
Gross Labour Cost (S\$)			11,550.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >