

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 559P

AAD1907-076

Not Authored

Resurvey B4 paint

83044.34

Vehicle No.:		SHD 559P
Chassis No.:	09 JUL 2019	VF1ABL15AUC283471
Vehicle Make:		RENAULT
Vehicle Model:		LATITUDE
Date of Accident :		5.7.19
Third Party Insurer :		AIG
Date of Registration :		3/7/2017

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>BU</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>BU/LWR BU</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>BU</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>BU</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$	<i>BU</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>BU</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>BU</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>BU</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>BU</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>BU</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>BU</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>BU</i> 225.95
13	1 OUTER PANEL REAR (End Panel)	\$	<i>BU</i> 1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>BU</i> 404.56
15	1 TAILLAMP RH	\$	<i>BU</i> 552.55
16	1 TAILLAMP PANEL RH	\$	<i>BU</i> 986.70
17	1 TAILLAMP LH	\$	<i>BU</i> 552.55
18	1 TAILLAMP PANEL LH	\$	<i>BU</i> 986.70
19	1 BOOT REAR	\$	<i>BU</i> 2,872.68 X
20	1 BOOT FINISHER	\$	<i>BU</i> 470.06
21	1 BOOT WHEATERSTRIP	\$	<i>BU</i> 323.05
22	1 BOOT REFLECTOR LAMP LH	\$	<i>BU</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$	<i>BU</i> 493.35
24	1 BOOT BADGE 'RENAULT'	\$	<i>BU</i> 225.36
25	1 BOOT BADGE	\$	<i>BU</i> 225.36
26	1 BOOT STRUT LH	\$	<i>BU</i> 276.08
27	1 BOOT STRUT RH	\$	<i>BU</i> 276.08
28	1 BOOT HINGE LH	\$	<i>BU</i> 367.84
29	1 BOOT HINGE RH	\$	<i>BU</i> 367.84

Trans-cab Auto Services Pte Ltd

AAD1907-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 559P

30	1	BOOT INNER TRIM	\$	<i>Sm</i>	586.45	X
31	1	BOOT SWITCH	\$	<i>Sm</i>	168.13	X
32	1	BOOT LOCK	\$	<i>n</i>	202.67	X
33	1	BOOT LOCK CATCH	\$	<i>n</i>	74.40	X
TOTAL			\$		16,046.87	
10%			\$		1,604.69	
			\$		14,442.19	

Special Nett

1	1SET	PARKING AID	\$	<i>Sm</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>n</i>	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>n</i>	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>n</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>n</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>n</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>n</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>n</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>n</i>	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	<i>n</i>	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	<i>n</i>	30.00	
12	1	EXHAUST MOUNTING REAR	\$	<i>n</i>	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	<i>n</i>	80.00	
14	1	WINDSCREEN MOULDING	\$	<i>n</i>	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>n</i>	100.00	
16	1	BOOT INNER TRIM CLIP	\$	<i>n</i>	45.00	
17	1SET	BOOT FINISHER CLIP	\$	<i>n</i>	24.20	
18	1	TAILLAMP CLIP LH	\$	<i>n</i>	5.00	
19	1	TAILLAMP CLIP RH	\$	<i>n</i>	5.00	
TOTAL			\$		1,384.02	

TOTAL PARTS \$ 15,826.21**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	<i>10/</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>n</i>	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1907-076

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 559P

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nr</i> 380.00 X
To Rust-Proofing Of The Affected Areas.	\$	<i>nr</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 <i>2001</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>2201</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nr</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nr</i> 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nr</i> 380.00 X

TOTAL \$ 11,550.00

Over All Total \$ 27,376.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PART BY PART (REPAIR DAY)

15 DAYS
2 days