

AIG INSURANCE

78 Shenton Way,

#07-16, AIG Building

Singapore 079120

Vehicle number	SMJ7257Z
Make / Model	MERCEDES/C200
Chassis number	WDD2040012A895700
Accident date	07 July 2019
Reference	1907-24

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER UPPER / RL	2119.45
1	REAR BUMPER INNER GUIDE ?	60.00
2	REAR BUMPER RETAINER / RL	101.20
2	REAR BUMPER BRACKET ?	195.50
1	REAR BUMPER REINFORCEMENT ?	895.85
2	REAR BUMPER REINFORCEMENT BRACKET ?	220.50
1	REAR BUMPER LOWER / RL	231.15
1	REAR BUMPER LOWER GARNISH X	130.00
4	PDC SENSOR ?	1412.20
4	SENSOR HOLDER / nbl.	90.00
1	BOOTLID / DD	2141.32
1	BOOTLID LOCK X NN	404.80
1	BOOTLID EMBLEM -LOGO / fmc	61.10
1	BOOTLID EMBLEM - C200 / fmc	97.75
1	SPARE TYRE TOP BOARD X	410.55
1	SPARE TYRE INNER FLOOR GARNISH x NN	368.00
2	FENDER INNER TRIM X	405.00
1	END PANEL ?	1639.90
1	END PANEL TOP GARNISH ?	90.00
1	REAR EXHAUST PIPE X	1669.80
2	REAR EXHAUST MOUNTING X NN	144.00
1	REAR EXHAUST HEAT SHIELD X	250.80
2	REAR TAILLAMP X	1872.20
1	DRIVER HEATREST ASSY Repair. X	2256.30
1	PASSENGER HEATREST ASSY Repair. X	2256.30
		19523.67
Less 5 %		976.18
Subtotal		18547.49
Balance C/F		18547.49

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	18547.49
1 SET	REAR BUMPER CLIP / MC	40.00
1 SET	REAR FENDER INNER TRIM CLIP X	30.00
1	JOINT SELANT ? X 5 NN	150.00
1	REAR NUMBER PLATE X	80.00
	Subtotal	300.00
	Balance C/F	18847.49
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	18847.49
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200.00 60
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40
4	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 x NN
5	DIAGNOIS CHECK AND CLEAR FAULT CODE	400.00 250
6	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 60
7	PANEL BEATING ON AFFECTED AREAS	1500.00 500 ?
8	SPRAY PAINTING ON AFFECTED AREAS	1400.00 600
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 ?
	Subtotal	4210.00
	Grand total	23057.49

5 Days. (6)

Unpainted repair.

After repair photos.

Geni Corp - 82880282

18/7/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: