



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SKT9812D

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 28/06/2019

TP VEH REG NO : SKT9812D

ESTIMATE

NO : QUOT201907-000029(00)

DATE : 08/07/2019

POLICY NO : 999995580

VEH REG NO : GBJ2923Y

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323566325

ENGINE NO : 65195034991890

REG. DATE : 2019

Not withash
Purway Bg painting
4 days

Estimate Repair Cost to Vehicle No : GBJ2923Y

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
NET PRICE			
1 Tailgate	1	2,105.00	2,105.00 ✓
2 Tailgate weathestrip	1	191.00	191.00 X
3 Tailgate lock	1	222.00	222.00 ?
4 Tailgate centre inner trim	1	65.00	65.00 X
5 Tailgate center logo	1	84.00	84.00 —
6 Tailgate VITO emblem	1	49.00	49.00 —
7 Tailgate C&C emblem	1	38.00	38.00 —
8 Tailgate 114 CDI emblem	1	58.00	58.00 —
9 Rear end panel (outer)	1	380.00	380.00 ?
10 Taillamp assy - LH	1	330.00	330.00 X
11 Taillamp lower garnish LH/RH	2	67.00	134.00 ✓
			3,656.00
		Less 10%	365.60
			3,290.40
SPECIAL NET			
12 Rear windscreen sealant		60.00	60.00 ✓
13 Rear bumper reverse sensor (set)	1	380.00	380.00 X
14 Rear number plate	1	40.00	40.00 ✓
15 Tailgate "70km/h" sticker	1	25.00	25.00 15m
16 Tailgate "6pax" sticker	1	25.00	25.00 15m
			530.00
LABOUR			
17 To remove and refit rear windscreen glass	1	120.00	120.00 ✓
18 To transfer damage tailgate interior mechanism to new tailgate	1	150.00	150.00 60m
19 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut and weld rear end panel, including replacement of parts and align where necessary action, to refit and adjust the same	1	1,000.00	1,000.00 ?
20 To putty and spray paint on affected areas	1	800.00	800.00 440m
21 To apply rust-proofing on replaced and repaired panels	1	80.00	80.00 ?
22 To supply artwork and paste advertisement on tailgate	1	500.00	500.00 ?
			2,650.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : SKT9812D
CLAIM TYPE : THIRD PARTY
TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD
ACCIDENT DATE : 28/06/2019
TP VEH REG NO : SKT9812D

ESTIMATE

NO : QUOT201907-000029(00)
DATE : 08/07/2019
POLICY NO : 999995580
VEH REG NO : **GBJ2923Y**
MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR
CHASSIS NO : WDF44760323566325
ENGINE NO : 65195034991890
REG. DATE : 2019

Estimate Repair Cost to Vehicle No : GBJ2923Y

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
		TOTAL	S\$ 6,470.40
		ADD GST @ 7%	452.93
		GRAND TOTAL	S\$ 6,923.33

SINGAPORE DOLLAR SIX THOUSAND NINE HUNDRED TWENTY-THREE AND CENTS THIRTY-THREE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE