

SERVE YOU MOTOR SERVICE

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-265, SINGAPORE 569536

TEL. NO: 64810555 / FAX NO. 64831654

E-MAIL: elainesyms@gmail.com

INS: AIG ASIA PACIFIC INSURANCE PTE LTD

COMPANY: EDS HOLDING PTE LTD

Registration no. : YM 3746 Y / MITSUBISHI FK617MSJRDEC

Date of accident: 22.05.2019

Date : 10-Jul-19

Quotation No. : CM190514

S/N	Qty	Item	Amount
<u>SPECIAL NETT ITEMS</u>			
1	1	Front tyre LH side	\$270.00 X
2	1	Front tyre rim LH side	\$680.00 Y
Total:			\$950.00
<u>LABOUR & MISC CHARGES</u>			
1		To straighten and panel beating on front LH sides for accident damaged portion.	\$380.00
2		To putty, re-spray painting affected areas.	\$480.00
3		To remove and refit front LH tyre to facilitate repairs	\$60.00
TOTAL			\$920.00
Total Parts and Labour Cost of Repair			\$1,870.00

bump

Not with air
Resurvey After painting
84401

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: