

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Reg. No: 201427944N

TO : AXA DATE : 08/07/2019

ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM

ESTIMATE REPORT : *Vivian*

VEHICLE DETAILS

VEHICLE NO : SLG7449P

MODEL : MITSUBISHI OUTLANDER2.4 A

CHASSIS NO

ACCIDENT DETAILS DATE : 8-Jul-19
TIME : 14:46HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Distorted</i>	1	\$ 1,088.90	\$ 1,088.90
2	TAILGATE LOGO <i>new</i>	1	\$ 60.00	\$ 60.00
3	TAILGATE EMBLEM 'OUTLANDER' <i>3 new</i>	1	\$ 130.00	\$ 130.00
4	TAILGATE 'C&C' <i>2</i>	1	\$ 80.00	\$ 80.00
5	TAILGATE LOCK <i>Distorted</i>	1	\$ 450.00	\$ 450.00
6	TAILGATE LAMP <i>cracked</i>	1	\$ 410.00	\$ 410.00
7	TAILGATE BUZZEL <i>cracked</i>	1	\$ 80.00	\$ 80.00
8	TAILGATE ALTERNATIVE <i>cracked</i>	1	\$ 150.00	\$ 150.00
9	TAILGATE INNER BOARD <i>cracked</i>	1	\$ 630.00	\$ 630.00
10	TAILGATE WEATHERSTRIP <i>at</i>	1	\$ 230.00	\$ 230.00
11	TAILGATE NUMBLEM LAMP GARNISH WITH CHROME <i>cracked</i>	1	\$ 680.00	\$ 680.00
12	TAILGATE WINDSCREEN MOULDING(SET) <i>new</i>	1	\$ 180.00	\$ 180.00
13	TAILGATE AUTO START MOTOR <i>Distorted</i> <i>new</i>	1	\$ 2,350.00	\$ 2,350.00
14	REAR BUMPER <i>Distorted</i>	1	\$ 950.00	\$ 950.00
15	REAR BUMPER LOWER LID <i>Distorted</i>	1	\$ 530.00	\$ 530.00
16	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.50	\$ 125.00
17	REAR BUMPER REFELCTOR <i>RH cracked</i>	2	\$ 210.00	\$ 420.00
18	REAR BUMPER REINFORCEMENT BRACKET <i>sent</i>	2	\$ 140.00	\$ 280.00

19	TAILLAMP <i>could</i>	2	\$ 650.00	\$ 1,300.00 <i>1188</i>
20	REAR FENDER INNER TRIM <i>could</i>	2	\$ 890.00	\$ 1,780.00 <i>796</i>
21	REAR END PANEL <i>Bent</i>	1	\$ 580.00	\$ 580.00
22	REAR END SIDE PANEL <i>Repair</i>	2	\$ 280.00	\$ 560.00
23	REAR END PANEL TOP GARNISH <i>Bent</i>	1	\$ 380.00	\$ 380.00
24	REAR FLOOR PANEL <i>Repair</i>	1	\$ 890.00	\$ 890.00
25	REAR EXHAUST PIPE <i>Repair</i>	1	\$ 980.00	\$ 980.00

spare tyre tray could 292 TOTAL PRICE \$ 15,293.90
Tools tray could 202 LESS 10% \$ 1,529.39
 9052 SUB TOTAL PRICE \$ 13,764.51
 8146.80

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 22.00	\$ 22.00
2	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 20.00	\$ 20.00
3	TAILGATE INNER BOARD CLIPS(SET) <i>new</i>	1	\$ 25.00	\$ 25.00
4	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
5	REAR BUMPER TOP CHROME <i>Bent</i>	1	\$ 380.00	\$ 380.00 <i>250</i>
6	REAR BUMPER REFLECTOR CHROME HOUSING <i>new</i>	2	\$ 220.00	\$ 440.00 <i>360</i>
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00 <i>60</i>
8	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 <i>10</i>
9	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00
10	REVERSE CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00
11	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>200</i>

957 TOTAL \$ 1,870.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00 <i>1200</i>
2	TO SPRAY PAINT ON AFFECTED AREA	\$ 2,000.00 <i>1000</i>
3	TUFF COAT	\$ 150.00 <i>80</i>
4	WIRING CHECK	\$ 150.00 <i>30</i>
6	TO REMOVE AND REFIX TAILGATE MECAHNISM	\$ 180.00 <i>80</i>
6	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 160.00 <i>120</i>
7	TO REMOVE AND REFIX REVERSE SENSOR AND SETTING	\$ 100.00 <i>50</i>
8	TO REMOVE AND REFIX REVERSE CAMERA AND SETTING	\$ 100.00 <i>50</i>
8	TO REMOVE AND REFIX EXHAUST PIPE	\$ 240.00 <i>80</i>

2790

TOTAL

\$5,080.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,634.51

TOTAL LABOUR COST : \$ 5,080.00

TOTAL REPAIR COST : \$ 20,714.51

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Ly total 11893.80
4/s 10/07/19. 4/s: 9.5K
08 Days.

- LKK Auto Consultants** hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9.5K ✓