



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TPAXA Via

Page No. 1

Vehicle No. SKA2155M NISSAN QASHQAI

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
2	FRONT FENDER LH & RH @\$978.00	Distorted	1956.00	✓ 1366
2	FRONT FENDER SPLASH SHIELD LH & RH @\$238.00	RH torn	476.00	238 196
2	FRONT FENDER ARC LH & RH @\$225.00	RH Bent	450.00	225
1	FRONT BUMPER	Distorted	1245.00	✓ 676
2	FRONT BUMPER SIDE RETAINER LH & RH @\$120.00	RH Distorted	240.00	120
2	FRONT BUMPER FOG LAMP COVER LH & RH @\$190.00	RH Missing	380.00	190 95
2	FRONT BUMPER FOG LAMP LH & RH @\$480.00	RH cracked	960.00	480 327
1	FRONT WIPER WASHER TANK W/MOTOR	new	342.00	X
1	FRONT SUPPORT PANEL	Distorted	942.00	✓ 792
1	FRONT BONNET	Dented	2658.00	✓ 961
1	FRONT BONNET CHROME GRILLE	new	325.00	X
2	FRONT HEADLAMP LH & RH @\$1280.00	cracked	2560.00	✓
2	FRONT SHOCK ABSORBER LH & RH @\$692.00	RH Bent	1384.00	692 421
2	FRONT LOWER ARM LH & RH @\$378.00	RH Bent	756.00	378
2	FRONT TIE ROD LH & RH @\$178.00		356.00	178
2	FRONT KNUCKLE ARM LH & RH @\$492.00	RH Bent	984.00	492
2	FRONT WHEEL BEARING LH & RH @\$242.00	RH new	484.00	242
1	FRONT STEERING RACK & PINION	Bent	2850.00	✓ 1850
1	FRONT WING MIRROR ASSY	new	650.00	X
1	FRONT WING MIRROR COVER	missing	220.00	✓
1	FRONT DOOR LHS	Repair	2245.00	X
1	REAR DOOR LHS		2150.00	X
1	REAR TAILGATE	Distorted	2936.80	✓
1	REAR TAILGATE CENTRE COVER	cracked	742.50	✓ 336
1	REAR TAILGATE INNER LOCK	Damaged	157.40	✓
1	REAR TAILGATE LOCK CATCH	Bent	31.70	✓
1	REAR TAILGATE INNER TRIM	cracked	436.00	✓
2	REAR TAILGATE REFLECTOR LH & RH @\$592.50	new	1185.00	X
2	REAR TAILGATE DAMPER LH & RH @\$214.50	new	429.00	X
1	REAR TAILGATE WEATHERSTRIP	new	158.70	✓
1	REAR TAILGATE LOGO	new	70.00	✓
1	REAR TAILGATE "QASHQAI" EMBLEM	new	92.00	✓
1	REAR TAILGATE "XTRONIC CVT" EMBLEM	new	71.00	✓
1	REAR TAILGATE (LIZARD) EMBLEM	new	81.00	✓
1	REAR BUMPER	Distorted	1152.00	✓ 798
2	REAR BUMPER SIDE BRACKET LH & RH @\$85.00	new	170.00	X
2	REAR BUMPER SIDE RETAINER LH & RH @\$98.00	new	196.00	✓
2	REAR BUMPER REFLECTOR LH & RH @\$16.80	new	33.60	X
1	REAR BUMPER CENTRE COVER	Missing	742.50	58
1	REAR BUMPER TOW COVER	new	35.10	✓
1	REAR BUMPER REINFORCEMENT	Bent	692.00	✓
1	REAR BUMPER ENERGY ABSORBER	new	226.00	X
1	REAR END PANEL	Distorted	982.00	✓ 541
1	REAR END PANEL TOP LUGGAGE PLATE	new	63.50	X
1	REAR END PANEL TOP GARNISH	new	210.00	✓
1	REAR SPARE TYRE PANEL	Distorted	1270.00	✓
1	REAR SPARE TYRE PANEL TOP BOARD	new	550.00	X
1	REAR EXHAUST PIPE	Dented	2285.00	✓ 890
2	REAR FENDER ARC LH & RH @\$195.00	RH Missing	390.00	195
2	REAR TAILLAMP LH & RH @\$1129.00	RH Bent	2258.00	✓ 1129 415

20769.7

18/02/22

			less	30%	42259.80 12677.94 29581.86	30%
SPECIAL NETT ITEMS						
2	FRONT SPORT RIM LH & RH @ \$780.00	LH at			1560.00	450
2 SET	FRONT FENDER INNER SHIELD CLIPS	nw			120.00	30
2 SET	FRONT & REAR BUMPER CLIPS	nw			160.00	60
1	FRONT TYRE RH	Punctured			310.00	180.
1	REAR BUMPER LOWER SPOILER	nw			380.00	+
1	REAR NUMBER PLATE WITH HOLDER	nw			70.00	+
1 SET	REVERSE SENSOR	Dented			280.00	-200
1	REAR END PANEL SEALANT	Zper			100.00	60
1	REAR WINDSCREEN SEALANT				120.00	60.
Total Parts					32681.86	

1040.



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SKA2155M NISSAN QASHQAI

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	2000.00	1900
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	3600.00	2000
3	To remove and refix wiring at damaged areas	180.00	60
4	To perform anti rust treatment on affected areas	150.00	120
5	To remove and replace frnt radiator and press test	180.00	60
6	To remove and replace aircon condenser and top up A/C gas	150.00	60
7	To remove and replace inter cooler assy	150.00	X
8	To respray kuff tote	280.00	60
9	To conduct wheel alignment test	150.00	80
10	To remove and replace undercarriage part	300.00	✓
11	To remove and replace rear windscreen	140.00	120
12	To remove and refix door components	240.00	X
13	To remove and refix rear exhaust pipe	200.00	80
	Labour Total :	7720.00	
	TOTAL (PARTS & LABOUR) :	40401.86	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4840.

total: 24572.73.

L/S: 9K (Nett Value)

124 Days