

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0839/2019/TG
Date	:	10-Jul-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Ng Keng Loong, Gideon
Address	:	989 Bukit Timah Road
	:	#08-13
	:	Singapore 589629
Telephone	:	HP +65 97244710
Type of Claim	:	Third Party Claim
Policy No.	:	SI19V05645/VPC/R00
Vehicle No	:	SLJ 2465 J
Model Code	:	Audi A6 1.8 TFSI S Tronic
Model / Year	:	30/11/2016
Engine No	:	CYG 015356
Chassis No	:	WAUZZZ4G1HN012131
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	6-Jul-19
Place of Accident	:	Ghim Moh Multi Storey Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 2465 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside tempeture sensor and headlight washer assy and front parking aid.	S/N \$ 480.00 /	
2	To dismantle and renew front bumper and rhs headlights. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,600.00 500	
3	To respray front bumper and rhs front fender. ^X	\$ 2,200.00 500 550	
4	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 4,472.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLJ 2465 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER star repair	\$	2,787.00
2	FRONT BUMPER FIXING PARTS ?	\$	491.00
3	FRONT BUMPER ADAPTER - RH ?	\$	34.00
4	FRONT BUMPER SPOILER X	\$	227.00
5	FRONT BUMPER AIR GUIDE GRILLE - RH ?	\$	452.00
6	FRONT BUMPER COVER - RH X	\$	46.00
7	FRONT WHEEL SPOILER - RH X	\$	242.00
8	FRONT HEADLIGHT WASHER COVER - LH / RH repair	\$	104.00
9	FRONT PARKING AID SENSOR - OUTER X	\$	231.00
10	SEAL RING X	4 \$	5.00
11	FRONT BUMPER GUIDE PIECE - RH ?	\$	34.00
12	FRONT BUMPER SUPPORT BRACKET - RH ?	\$	27.00
13	FRONT BUMPER REINFORCEMENT X	\$	754.00
14	FRONT BUMPER FOAM FILLER PIECE X	\$	215.00
15	FRONT HEADLIGHT MOUNTING - RH ?	\$	107.00
16	FRONT HEADLIGHT - RH X	\$	8,607.00
17	FRONT HEADLIGHT LIFT CYLINDER - RH ?	\$	216.00
18	STONE GUARD FILM - RH ?	S/N \$	110.00
19	SUNDRIES ?	\$	300.00
TOTAL SPARE PARTS		\$	14,989.00
TOTAL LABOUR CHARGES		\$	4,472.00
GRAND TOTAL		\$	19,461.00

. All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Panel - Hp 90020068
: 11/01/12 @ 1125
: 3 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant