

15/5/2010

INS. CASE OWNER:

CC 4 / AXA1901

LKK:
IDAC:

Surveyor:

STED MARINS

DOI:

ASSIGNMENT

11/7/19

Date / Time:

10/7/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 5515M

Claim No.:

SMD2165 / 12085

Name of Insured:

TRANS - M8 STANIES PUL

Policy No.:

Insured Tel No.:

HP:

Make / Model:

KAWAS

Excess Sec II :SS

D.O.A:

9/7/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Tan Kin Hock

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(VL: YES / NO)

Insured Liability: %

Final ? Yes / No

SHG 1585R

INSRS:
WSP:
Tel:
Liability:
RMKS:

Kah motor

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SHG 1585R - 2

SHC 5515M - 2

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: > 11/7/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 27.

If NO or B 28, Ass. Lia :

Repair Cost:

SS

10928.47

Loss of Rental (LOR):

SS

1070.00

(10 days)

x100 + GST

Loss of Use (LOU):

SS

(S x days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

11998.47.

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

11998.47.

Name 1:

Kah motor co. sdh. Bhd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

CORRECT
8/8/19

W

TOTAL



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

\$ 10213.52

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19003020	Page	1
	8 SHENTON WAY	Date	: 9. Jul 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: YOU PO SOON		
Registration No	: SMJ1585R	Engine No	: L13B14100261		
Chassis No	: JHMGK3850KS208068	Date Time	: 9. Jul 2019 3:38:45 PM		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Surveyor Name	:		
Owner's Name	: NIRMALA D/O K BALAKRISHNAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 9/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: NIRMALA D/O K BALAKRISHNAN						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 9/7/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE PTE LTD						
	TP VEH: SHC5515M						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	1	2.10	25	3.15	0.22	3.37
74890-T5A-A11	GARNISH ASSY,RR LICENCE	1	105.50	25	79.12	5.54	84.66
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	53.70	25	40.27	2.82	43.09
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.10	25	3.82	0.27	4.09
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE	1	78.90	25	59.17	4.14	63.31
75722-T5L-T01	EMBLEMRR	1	10.90	25	8.17	0.57	8.74
04715-T5A-J50ZZ	FACE,RR BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-J50	SPACER,R,RR BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L,RR BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71505-T5A-J50	GARNISH,RR BUMPER	1	38.30	25	28.72	2.01	30.73
71502-T5A-J60	COVER,R,RR BUMPER	1	20.70	25	15.52	1.09	16.61
71507-T5A-J60	COVER,L,RR BUMPER	1	20.70	25	15.52	1.09	16.61

Printed on 9/7/2019 5:33:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No. M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMJ1585R
Chassis No : JHMGK3850KS208068
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : NIRMALA D/O K BALAKRISHNAN
Ins Policy No. :
Date of Accident : 9/7/2019

Document No. : SQT19003020
Date : 9. Jul 2019
Customer No. : WZA006
Svc Advisor : YOU PO SOON
Engine No : L13B14100261
Date | Time : 9. Jul 2019 3:38:45 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71503-T5A-J50	COVER,RR EXPI FIN	1	9.30	25	6.97	0.49	7.46
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPRR	1	320.40	25	240.30	16.82	257.12
04655-TAS-310ZZ	PANEL SET,RR.FLOOR	1	697.00	25	522.75	36.59	559.34
63320-T5A-900ZZ	GUTTER COMP,R.RR.PILLAR	1	88.60	25	66.45	4.65	71.10
63720-T5A-900ZZ	GUTTER COMP,L.RR.PILLAR LOWER	1	88.60	25	66.45	4.65	71.10
84640-T5A-003ZA	LINING ASSYRR PANEL	1	60.80	25	45.60	3.19	48.79
84651-TAR-Z03ZA	LINING ASSYL TRUNK	1	169.00	25	126.75	8.87	135.62
84601-TAR-Z03ZA	LINING ASSYL TRUNK	1	169.00	25	126.75	8.87	135.62
33500-T5A-J02	TAILLIGHT ASSY,R.	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYL LID	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL LID	1	81.70	25	61.27	4.29	65.56
72841-SH3-315	OILSHEET	1	40.70	25	30.52	2.14	32.66
NMRS-4P-TM3040L	4PCS ACT RR SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					3381.17	236.69	3,617.86
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT	2	80.00		160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	220	250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00	130	150.00	10.50	160.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00	300	320.00	22.40	342.40
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	250.00		250.00	17.50	267.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00		350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50

Printed on 10/7/2019 2:13:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMJ1585R

Chassis No : JHMGK3850KS208068

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : NIRMALA D/O K BALAKRISHNAN

Ins Policy No. :

Date of Accident : 9/7/2019

Document No. : SQT19003020

Date : 9. Jul 2019

Customer No. : WZA006

Svc Advisor : YOU PO SOON

Engine No : L13B14100261

Date | Time : 9. Jul 2019 3:38:45 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl'd GST
BKRP02B	CUT & RENEW RR FLOOR PANEL STRAIGHTEN FENDERS ALIG <i>360</i>	1	4100.00	<i>3360</i>	4100.00	287.00	4387.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (7P) <i>450</i>	1	3300.00	<i>2650</i>	3300.00	231.00	3531.00
Sum Labor					9880.00	691.60	10,571.60

Survey By

Date & Time

Excess

Status

Signature

morris hkh
*11/7/19 @ 9.30**M.F. Abdul**Lim Ph. Subyong**gdy.*

Total Amount 13,261.17 928.29 14,189.46

Total (Inclusive of GST) 14,189.46

13356.04

Link Auto Consultants hence notify the Repairer of the following:

- To ensure full coverage spray painting
- To ensure damaged parts having recovery
- To ensure correct use of seal to confirmation
- Third party survey to be a "No Fault Prejudice" basis
- To ensure correct use of seal to confirmation
- To ensure correct use of seal to confirmation

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 9/7/2019 5:33:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual lines.

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMJ1585R
Chassis No : JHMGK3850KS208068
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : NIRMALA D/O K BALAKRISHNAN
Ins Policy No. :
Date of Accident : 9/7/2019

Document No. : SQT19003170
Date : 19. Jul 2019
Customer No. : WZA006
Svc Advisor : YOU PO SOON
Engine No : L13B14100261
Date | Time : 19. Jul 2019 9:11:09 AM
Surveyor Name : MARCUS CHUA
Survey Date : 11/7/2019
Authorisation Date : 11/7/2019

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
SUPPLEMENTARY PARTS AND LABOURS							
84550-T5A-J30	BOX ASSY, CARGO FLOOR GATE	1 To 1	117.40	25	88.05	6.16	94.21
83853-SA7-980	BOLTANCHOR	1 Best	9.10	25	6.82	0.48	7.30
Sum Item					94.87	6.64	101.51

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 94.87 6.64 101.51
Total (Inclusive of GST) 101.51

Printed on 19/7/2019 9:15:13 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.



20/7/2019
ATTN: Marcus Chua



Page 1/2

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD. WD: 9days

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE PTE
Chassis No: JHMGK3850KS208068
License No: SMJ1585R
Mileage: 5897
Engine No: L13B14100261

Document No: SVO19044358
Printed By: PSYOU
Order Date: 11. July 2019
Order Time: 9:43:35 AM
Service Advisor: YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:73030) OWNER: NIRMALA D/O K BALAKRISHNAN OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 9/7/2019 SURVEYED BY: MARCUS DATE: 11/7/2019 REF NO: TP INSURER: AXA INSURANCE PTE LTD TP VEH: SHC5515M						
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBER WINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPER STD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHER STRIP TAILGATE	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY, TAILGATE	1	78.90	25	59.17	4.14	63.31
75722-T5L-T01	EMBLEM RR.	1	10.90	25	8.17	0.57	8.74
04715-T5A-J50ZZ	FACE, RR. BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-J50	SPACER, R. RR. BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER, L. RR. BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71505-T5A-J50	GARNISH, RR. BUMPER	1	38.30	25	28.72	2.01	30.73
91505-TM8-003	CLIP, BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COM PR.	1	320.40	25	240.30	16.82	257.12
84640-T5A-003ZA	LINING ASSY RR. PANEL	1	60.80	25	45.60	3.19	48.79
33550-T5A-J02	TAILLIGHT ASSY.	1	223.90	25	167.92	11.75	179.67
NMRS-4P-TM3040L	4PCS ACT RR. SENSOR	1	320.00		320.00	22.40	342.40
84550-T5A-J30	BOX ASSY, CARGO FLOOR GATE	1	117.40	25	88.05	6.16	94.21
83853-SA7-980	BOLT ANCHOR	1	9.10	25	6.82	0.48	7.30
	SUM PARTS:				2,073.52	145.15	2,218.67
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	0760 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	100.00		100.00	7.00	107.00
BOBC	1864 BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	1864 BODY JOINT SEALANT.	1	80.00		160.00	11.20	171.20
BP00R	1864 APPLY BODY UNDERSIDE COATING (N).	1	220.00		220.00	15.40	235.40
BA02R	1864 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	300.00		300.00	21.00	321.00
BG02D	1864 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE PTE
Chassis No: JHMGK3850KS208068
License No: SMJ1585R
Mileage: 5897
Engine No: L13B14100261

Document No: SVO19044358
Printed By: PSYOU
Order Date: 11. July 2019
Order Time: 9:43:35 AM
Service Advisor: YOU PO SOON

BMI01D	1864 REMOVE & INSTALL ROOF LINING GARNISHES SEATS SPEAKER BOARD CARPET & ETC.(N)	1	350.00	350.00	24.50	374.50
BKTG02R	1864 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50
BKRP02B	1864 CUT & RENEW RR FLOOR PANEL. STRAIGHTEN FENDERS ALIG RR CHASSIS INCLUDING FIITTING ON ATTACHMENT ITEMS.	1	3,360.00	3,360.00	235.20	3,595.20
BP07R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(7P)	1	2,650.00	2,650.00	185.50	2,835.50

SUM LABOUR: 8,140.00 569.80 8,709.80

TOTAL SGD 10,213.52 714.95 10,928.47

Total Payable (SGD) 10,928.47

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19003020	Page	1
Registration No	: SMJ1585R	Date	: 9. Jul 2019		
Chassis No	: JHMGK3850KS208068	Customer No.	: WZA006		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Svc Advisor	: YOU PO SOON		
Owner's Name	: NIRMALA D/O K BALAKRISHNAN	Engine No	: L13B14100261		
Ins Policy No.	:	Date Time	: 9. Jul 2019 3:38:45 PM		
Date of Accident	: 9/7/2019	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NIRMALA D/O K BALAKRISHNAN OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 9/7/2019 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE PTE LTD TP VEH: SHC5515M						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
74890-T5A-A11	GARNISH ASSY,RR LICENCE	1	105.50	25	79.12	5.54	84.66
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	53.70	25	40.27	2.82	43.09
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.10	25	3.82	0.27	4.09
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE	1	78.90	25	59.17	4.14	63.31
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71505-T5A-J50	GARNISH,RR.BUMPER	1	38.30	25	28.72	2.01	30.73
71502-T5A-J60	COVER,R.RR.BUMPER	1	20.70	25	15.52	1.09	16.61
71507-T5A-J60	COVER,L.RR.BUMPER	1	20.70	25	15.52	1.09	16.61

Printed on 9/7/2019 5:33:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMJ1585R
Chassis No : JHMGK3850KS208068
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : NIRMALA D/O K BALAKRISHNAN
Ins Policy No :
Date of Accident : 9/7/2019

Document No. : SQT19003020
Date : 9. Jul 2019
Customer No. : WZA006
Svc Advisor : YOU PO SOON
Engine No : L13B14100261
Date | Time : 9. Jul 2019 3:38:45 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71503-T5A-J50	COVER,RR.EXPI FIN	1	9.30 ?	25	6.97	0.49	7.46
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPRR.	1	320.40	25	240.30	16.82	257.12
04655-TAS-310ZZ	PANEL SET,RR.FLOOR	1	697.00 ?	25	522.75	36.59	559.34
63320-T5A-900ZZ	GUTTER COMP,R.RR.PILLAR	1	88.60 ?	25	66.45	4.65	71.10
63720-T5A-900ZZ	GUTTER COMP,L.RR.PILLAR LOWER	1	88.60 ?	25	66.45	4.65	71.10
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1	169.00 ?	25	126.75	8.87	135.62
84601-TAR-Z03ZA	LINING ASSYL.TRUNK	1	169.00 ?	25	126.75	8.87	135.62
33500-T5A-J02	TAILLIGHT ASSY,R.	1	223.90 ?	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL.	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYL.LID	1	81.70 ?	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID	1	81.70 ?	25	61.27	4.29	65.56
72841-SH3-315	OILSHEET	1	40.70 ?	25	30.52	2.14	32.66
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					3381.17	236.69	3,617.86
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00	✓	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	2	80.00	✓	160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	220	250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00	130	150.00	10.50	160.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00	300	320.00	22.40	342.40
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00	✓	300.00	21.00	321.00
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	250.00	✓	250.00	17.50	267.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	✓	350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00	✓	450.00	31.50	481.50

Printed on 10/7/2019 2:13:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SMJ1585R

Chassis No : JHMGK3850KS208068

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : NIRMALA D/O K BALAKRISHNAN

Ins Policy No. :

Date of Accident : 9/7/2019

Document No. : SQT19003020 Page 3

Date : 9. Jul 2019

Customer No. : WZA006

Svc Advisor : YOU PO SOON

Engine No : L13B14100261

Date | Time : 9. Jul 2019 3:38:45 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKRP02B	CUT & RENEW RR FLOOR PANEL STRAIGHTEN FENDERS ALIG 360	1	4100.00	3360	4100.00	287.00	4387.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P) 450	1	3300.00	2650	3300.00	231.00	3531.00
Sum Labor					9880.00	691.60	10,571.60

Survey By

Date & Time

Excess

Status

Signature

MOROS ALI

11/7/19 @ 9:30

M. of Repair

Tan Ph. Behayah.

G. L.

Total Amount 13,261.17 928.29 14,189.46

Total (Inclusive of GST) 14,189.46

LKK Auto Consultants hence notify
the Reparer of the following:

- To remove the scratch/spray painting
- To display damaged parts during recovery
- Parts should be subject to confirmation
- The survey should be on a "No Fault Prejudice" basis
- No work should be done without approval
- Sign authority on behalf of Insured and
is subject to final approval from Insurance Company

Acknowledged by Reparer:

Signature:

Date:

Printed on 9/7/2019 5:33:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3214F

Vehicle Details

Vehicle No.: SMJ1585R
Vehicle to be Exported: No
Intended Deregistration Date: 11 Jul 2019
Vehicle Make: HONDA
Vehicle Model: JAZZ 1.3 CVT
Primary Colour: Orange
Manufacturing Year: 2019
Engine No.: L13B14100261
Chassis No.: JHMGK3850KS208068
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$15,963.00
Original Registration Date: 25 Feb 2019
First Registration Date: 25 Feb 2019
Transfer Count: 0
Actual ARF Paid: \$5,963.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Feb 2029
PARF Rebate Amount: \$4,472.00

Intended COE Rebate Details

COE Expiry Date: 24 Feb 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$28,199.00
COE Rebate Amount: \$27,133.00
Total Rebate Amount: \$31,605.00

The information contained herein is correct as at 11 Jul 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

KEEP YOUR BUSINESS FLOWING SMOOTH.
Cash flow solutions for growing businesses.
[Learn more ▶](#)



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

\$65800 \$65800! PROMO! Brand New Toyota Dyna 150 ...



1 Unit Only! Borneo Unit! GST Inclusive! No Hidden Cost! No Gimmicks! Call Us!
Net Link Partners StarAd

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 [View our cars](#)

Browse by Category

Sort by Date Posted

20 results/page

10 vehicles

jazz

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	jazz		Any	Any	2018	Any	Any	Any	Available
	Honda	Jazz 1.5A RS	\$78,988	\$7,740 /yr	20-Aug-2018	1,498 cc	8,000 km	Hatchback	Available
1 Owner. Agent Unit. Well Maintained, Very Low Mileage. Flexible Loan Scheme. Trade In Welcome. Call Now!									
Posted: 11-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.3A	\$65,800	\$7,270 /yr	19-Mar-2018	1,318 cc	12,224 km	Hatchback	Available
Agent Warranty Till March 2023 For Peace Of Mind! Most Popular Hot Hatch In Striking Blue! Extremely Spacious Cabin For A Hatchback!...									
Select By Performance Premium Selection									
Posted: 11-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.3A LX	\$65,800	\$7,210 /yr	09-Apr-2018	1,318 cc	26,000 km	Hatchback	Available
Low-Interest Rate, And In House Available. Well Maintained That Is As Good As Brand New And Smell Like Brand New! 4 Times Free Mai...									
Dickson Automobile									
Posted: 04-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.3A	\$62,800	\$7,050 /yr	18-Jan-2018	1,318 cc	16,000 km	Hatchback	Available
Well Maintained Unit Under 5 Year 's Agent Warranty. Pristine Condition. Buy And Enjoy With A Peace Of Mind, Trade In Welcome, High...									
Posted: 04-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Subaru	Forester e-Boxer							
Clean and green Subaru Forester e-Boxer									
The new Subaru Forester e-Boxer is a hybrid SUV that has left forced-induction behind, but it is a cleaner and greener option for buyers.									
Find out more!									
	Honda	Jazz 1.3A	\$64,800	\$7,140 /yr	23-Mar-2018	1,318 cc	29,137 km	Hatchback	Available
1 Owner! Maintained Only At Kah Motor With 5 Years Warranty! Immaculate Condition! High Trade In And In House Financing Available!...									
Posted: 03-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.3A	\$65,688	\$6,840 /yr	12-Sep-2018	1,318 cc	10,000 km	Hatchback	Available
High OMV At \$15803, High ARF \$5803, Price Negotiable, Lowest Depreciation, 3 Yr Servicing & 5 Yr Warranty! Pristine Condition 1 Owne...									
360 VR Cars									
Posted: 03-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda	Jazz 1.5A RS	\$73,500	\$7,400 /yr	26-Apr-2018	1,498 cc	32,000 km	Hatchback	Available
1 Owner & Agent Unit! Well Maintained By Owner, Warranty Till 2021. Full-Service History With Agent. Sparking Rouge Amethyst Metalli...									
Car Buyers Automotive Pte Ltd									

Compare

◀ Service Request Details

Claim

S9M01TG5

Reference

None 

Loss Date

July 9, 2019

Report Date

Jul 10, 2019 3:29:00 PM

Request Date

July 10, 2019

Due Date

July 17, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

p. PO soon

T: 3.44p.m

v: 1η

E: ✓

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SMJ1585R

Model

JAZZ-1.3 LX (GE6) (A)

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: You Po Soon <psyous@honda.com.sg>
Sent: Wednesday, 10 July, 2019 2:18 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Liew Thye Wui
Subject: DIRECT SETTLEMENT OF VEHICLE NO. SMJ1585R AGAINST SHC5515M (AXA)
Attachments: 3313_001.pdf

Categories: Raghav

To The Officer In Charge,

Please Refer The Above Attachment For Your Reference.

Kindly Help To Arrange Surveyor To Survey This Vehicle SMJ1585R. (Car In Workshop)

Your Insured vehicle number is SHC5515M, Accident Date 09/07/2019.

Thank You

Best Regards,

You Po Soon
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4
Singapore 408610
E-mail : psyous@honda.com.sg
DID : 6846 5672



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

 Re:TP MANDATE IA-S9M01TG5

Type

 Question

Message

please proceed. thanks.

[Reply](#)



Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
15 Ubi Road 4
Singapore 408610
Tel : +65 6841 3838
Fax : +65 6748 0770
www.honda.com.sg

M/s **AXA Insurance Pte Ltd**
C/o LKK Auto Consultants Pte Ltd
8 Shenton Way
#27-01
Singapore 068811

Date: 05/8/19

Your ref: Pls provide

Our ref: SMJ1585R

Attn: Motor Claims Department

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SMJ1585R AND SHC5515M ON 09.07.19

We refer to the items(s) marked (✓) below:

- (✓) We refer to LKK – Vivian's email dated 11.07.19
- (✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- (✓) Kindly forward the discharge voucher for our client's signature within 2 weeks via email to emillinliew@honda.com.sg or faeaz@honda.com.sg
- (✓) We return your discharge voucher duly completed.
- (✓) Kindly expedite settlement the following:-

Repair Cost	S\$10,928.47 payable to Kah Motor Co Sdn Bhd
Loss of Use	NIL
Rental	S\$1,070.00 payable to Kah Motor Co Sdn Bhd
TP Search Bill	NIL
LTA Search Bill	NIL
- (✓) Kindly let us have your cheque made in favour of the above mentioned names(s) for our transmission as soon as possible.
- (✓) Letter of Authority , Rental Bill

Thank you.

Yours faithfully,

You Po Soon



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19012244/Uwb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: JAS TAN			Date : 16-08-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5515M	Veh. Inspected	SMJ 1585R	
Policy No.	VPX/P1680520	Coverage (\$)	0.00	
Claim No.	S9M01TG5	Excess (\$)	0.00	
Assign From	JAS TAN	Assign Date	10/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ CVT (A)	c.c	1318	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JHMGK3850KS208068	Colour	ORANGE	
Odometer	005897	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	175/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	175/65 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	175/65 R15	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND ROOFTOP. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/07/2019	Inspection Date	11/07/2019	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 1585R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RUBBER CWINDOWSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	8.55	8.55
2	RUBBER WINDOWSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	9.75	9.75
1	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	6.37	6.37
1	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	TAIL GATE COMP (SN) (CONSISTENT)	BADLY DENTED	547.95	547.95
1	EMBLEMH (SN) (CONSISTENT)	NOT NECESSARY	8.02	-
1	NUTPUSH 3MM (SN) (CONSISTENT)	NOT NECESSARY	3.15	-
1	GARNISH ASSY,RR LICENCE (SN) (CONSISTENT)	NOT NECESSARY	79.12	-
1	LINING ASSY TAILGATE LOWER (SN) (CONSISTENT)	NOT NECESSARY	40.27	-
1	POCKET TAILGATE LINING PULL (SN) (CONSISTENT)	NOT NECESSARY	3.82	-
1	WEATHERSTRIP TAILGATE (SN) (CONSISTENT)	TWISTED	69.22	69.22
1	LOCK ASSY, TAILGATE (SN) (CONSISTENT)	TWISTED	59.17	59.17
1	EMBLEMRR. (SN) (CONSISTENT)	NECESSARY	8.17	8.17
1	FACE, RR.BUMPER (SN) (CONSISTENT)	DISTORTED	369.52	369.52
1	SPACER,R.RR.BUMPER SIDE (SN) (CONSISTENT)	BENT	12.67	12.67
1	SPACER,L.RR.BUMPER SIDE (SN) (CONSISTENT)	BENT	12.67	12.67
1	GARNISH,RR.BUMPER (SN) (CONSISTENT)	TWISTED	28.72	28.72
1	COVER,R.RR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	15.52	-
1	COVER,L.RR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	15.52	-
1	COVER,RR.EXPI FIN (SN) (CONSISTENT)	NOT NECESSARY	6.97	-
7	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	12.07	12.07
1	PANEL COMPRR. (SN) (CONSISTENT)	BADLY DENTED	240.30	240.30
1	PANEL SET,RR.FLOOR (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	522.75	-
1	GUTTER COMP,R.RR.PILLAR (SN) (CONSISTENT)	NOT NECESSARY	66.45	-
1	GUTTER COMP,L.RR.PILLAR LOWER (SN) (CONSISTENT)	NOT NECESSARY	66.45	-
1	LINING ASSYRR.PANEL (SN) (CONSISTENT)	TWISTED	45.60	45.60
1	LINING ASSYL.TRUNK (SN) (CONSISTENT)	NOT NECESSARY	126.75	-
1	LINING ASSYR.TRUNK (SN) (CONSISTENT)	NOT NECESSARY	126.75	-
1	TAILLIGHT ASSY,R. (SN) (CONSISTENT)	NOT NECESSARY	167.92	-
1	TAILLIGHT ASSYL. (SN) (CONSISTENT)	CRACKED	167.92	167.92

Report Ref No. CC4/ASM19012244/Uwb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LIGHT ASSY.R.LID (SN) (CONSISTENT)	NOT NECESSARY	61.27	-
1	LIGHT ASSY.L.LID (SN) (CONSISTENT)	NOT NECESSARY	61.27	-
1	OILSHEET (SN) (CONSISTENT)	NOT NECESSARY	30.52	-
4	ACT RR.SENSOR (SN) (CONSISTENT)	SHORTED	320.00	320.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	50.00	20.00
2	BODY JOINT SEALANT (SN) (CONSISTENT)	NECESSARY	160.00	160.00
1	BOX ASSY, CARGO FLOOR GATE (SN) (CONSISTENT) (ADDITIONAL)	TORN	88.05	88.05
1	BOLTANCHOR (SN) (CONSISTENT) (ADDITIONAL)	BENT	6.82	6.82
			3,686.04	2,253.52
	LABOUR			
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		100.00	100.00
	BODY UNDERSIDE COATING.		100.00	100.00
	APPLY BODY UNDERSIDE COATING.		250.00	220.00
	REMOVE & RENEW REVERSE SENSORS.		150.00	130.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		320.00	300.00
	REMOVE & INSTALL RR. WINDSCREEN.		300.00	300.00
	RREMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	250.00	-
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		350.00	350.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.		450.00	450.00
	CUT & RENEW RR FLOOR PANEL STRAIGHTEN FENDERS ALIG. INCLUSIVE OF THE REPAIR OF PANEL SET,RR.FLOOR.		4,100.00	3,360.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		3,300.00	2,650.00
			9,670.00	7,960.00
GRAND TOTAL			13,356.04	10,213.52

RECOMMENDED COST OF REPAIRS			10,213.52
------------------------------------	--	--	------------------

Report Ref No. CC4/ASM19012244/Uwb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.