



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 96203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

\$ 10213.52

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19003020	Page	1
	: 8 SHENTON WAY	Date	: 9. Jul 2019		
	: #27-01 AXA TOWER	Customer No.	: WZA006		
	: SINGAPORE 068811	Svc Advisor	: YOU PO SOON		
Registration No	: SMJ1585R	Engine No	: L13B14100261		
Chassis No	: JHMGK3850KS208068	Date Time	: 9. Jul 2019 3:38:45 PM		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Surveyor Name	:		
Owner's Name	: NIRMALA D/O K BALAKRISHNAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 9/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl'd GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: NIRMALA D/O K BALAKRISHNAN						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 9/7/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE PTE LTD						
	TP VEH: SHC5515M						
73127-TY0-000	RUBBER C/WINDSHIELD DAMPER	<i>1pc</i> 1	11.40	—	25	8.55	9.15
73214-T5A-013	RUBBER WINDSHIELD DAMPER	<i>1pc</i> 2	6.50	—	25	9.75	10.43
73226-S2W-000	DAMPER STD 5X5	<i>1pc</i> 1	8.50	—	25	6.37	6.82
BO-W5-SEALANT	WINDSCREEN SEALANT (N)	<i>1pc</i> 1	60.00	—		60.00	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	<i>1pc</i> 1	730.60	—	25	547.95	586.31
75701-T5A-000	EMBLEM H	<i>1pc</i> 1	10.70	X	25	8.02	8.58
90301-ST0-003	NUT PUSH 3MM	<i>1pc</i> 1	2.10	X	25	3.15	3.37
74890-T5A-A11	GARNISH ASSY RR LICENCE	<i>1pc</i> 1	105.50	X	25	79.12	84.66
84440-T5A-J02ZA	LINING ASSY TAILGATE LOWER	<i>1pc</i> 1	53.70	X	25	40.27	43.09
84441-T5A-003ZB	POCKET TAILGATE LINING PULL	<i>1pc</i> 1	5.10	X	25	3.82	4.09
74440-T5A-003	WEATHER STRIP TAILGATE	<i>1pc</i> 1	92.30	—	25	69.22	74.07
74801-T55-K01	LOCK ASSY TAILGATE	<i>1pc</i> 1	78.90	—	25	59.17	63.31
75722-T5L-T01	EMBLEM RR	<i>1pc</i> 1	10.90	—	25	8.17	8.74
04715-T5A-J50ZZ	FACE RR BUMPER	<i>1pc</i> 1	492.70	—	25	369.52	395.39
71593-T5A-J50	SPACER R RR BUMPER SIDE	<i>1pc</i> 1	16.90	—	25	12.67	13.56
71598-T5A-J50	SPACER L RR BUMPER SIDE	<i>1pc</i> 1	16.90	—	25	12.67	13.56
71505-T5A-J50	GARNISH RR BUMPER	<i>1pc</i> 1	38.30	—	25	28.72	30.73
71502-T5A-J50	COVER R RR BUMPER	<i>1pc</i> 1	20.70	X	25	15.52	16.61
71507-T5A-J50	COVER L RR BUMPER	<i>1pc</i> 1	20.70	X	25	15.52	16.61

Printed on 9/7/2019 5:33:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$13.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3638

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 96203636

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: 580FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19003020	Page	2
	: 8 SHENTON WAY	Date	: 9. Jul 2019		
	: #27-01 AXA TOWER	Customer No.	: WZA006		
	: SINGAPORE 068811	Svc Advisor	: YOU PO SOON		
Registration No	: SMJ1585R	Engine No	: L13B14100261		
Chassis No	: JHMGK3850KS208068	Date Time	: 9. Jul 2019 3:38:45 PM		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Surveyor Name	:		
Owner's Name	: NIRMALA D/O K BALAKRISHNAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 9/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71503-T5A-J50	COVER,RR EXPI FIN	1	9.30	25	6.97	0.49	7.46
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPR	1	320.40	25	240.30	16.82	257.12
04655-TAS-310ZZ	PANEL SET,RR FLOOR	1	697.00	25	522.75	36.59	559.34
63320-T5A-900ZZ	GUTTER COMP,RR,PILLAR	1	66.60	25	66.45	4.65	71.10
63720-T5A-900ZZ	GUTTER COMP,L,RR,PILLAR LOWER	1	66.60	25	66.45	4.65	71.10
84640-T5A-003ZA	LINING ASSY,RR,PANEL	1	60.80	25	45.60	3.19	48.79
84651-TAR-Z03ZA	LINING ASSYL TRUNK	1	169.00	25	126.75	8.87	135.62
84601-TAR-Z03ZA	LINING ASSYL TRUNK	1	169.00	25	126.75	8.87	135.62
33500-T5A-J02	TAILLIGHT ASSY,R	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYL,LID	1	61.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL,LID	1	61.70	25	61.27	4.29	65.56
72841-SH3-315	OILSHEET	1	40.70	25	30.52	2.14	32.66
NMRS-4P-TM3040L	4PCS ACT RR SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					3381.17	236.69	3,617.86

BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT	2	80.00		160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00	220	250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00	130	150.00	10.50	160.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00	300	320.00	22.40	342.40
BG02D	REMOVE & INSTALL RR WINDSCREEN (N)	1	300.00		300.00	21.00	321.00
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	250.00		250.00	17.50	267.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00		350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE, ADJUST &	1	450.00		450.00	31.50	481.50

Printed on 10/7/2019 2:13:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual items.

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203638

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S80FC1380G

Customer :	AXA INSURANCE PTE LTD	Document No. :	SQT19003020	Page	3
	8 SHENTON WAY	Date :	9. Jul 2019		
	#27-01 AXA TOWER	Customer No. :	WZA006		
	SINGAPORE 068811	Svc Advisor :	YOU PO SOON		
Registration No :	SMJ1585R	Engine No :	L13B14100261		
Chassis No :	JHMGK3850KS208068	Date Time :	9. Jul 2019 3:38:45 PM		
Model :	JAZZ 1.3LXR CVT 19YM (EURO 6)	Surveyor Name :			
Owner's Name :	NIRMALA D/O K BALAKRISHNAN	Survey Date :			
Ins Policy No. :		Authorisation Date :			
Date of Accident :	9/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKRP02B	CUT & RENEW RR FLOOR PANEL STRAIGHTEN FENDERS ALIG	1	4100.00	3360	4100.00	287.00	4387.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	3300.00	2650	3300.00	231.00	3531.00
Sum Labor					9880.00	691.60	10,571.60

Survey By: morris ahnDate & Time: 11/7/19 @ 9.30

Excess: _____

Status: not repairSignature: tan zhe. sekayou.9 Aug.

Total Amount 13,261.17 928.29 14,189.46

Total (Inclusive of GST) 14,189.46

LINK Auto Credit/Financing is hereby
the Receiver of the following:

- To receive the vehicle after spray painting
- To receive the damaged parts being replaced
- Parts to be used are subject to the Receiver
- These components are not "As New/Equivalent" basis
- The vehicle is to be used for normal driving
- Complete vehicle will not be re-inspected and
it is subject to the Receiver's final decision

Acknowledged by Receiver

Signature:

Date:

Printed on 9/7/2019 5:33:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$55.00 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1360G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : **SMJ1585R**
Chassis No : JHMGK3850KS208068
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : NIRMALA D/O K BALAKRISHNAN
Ins Policy No. :
Date of Accident : 9/7/2019

Document No. : SQT19003170
Date : 19. Jul 2019
Customer No. : WZA006
Svc Advisor : YOU PO SOON
Engine No : L13B14100261
Date | Time : 19. Jul 2019 9:11:09 AM
Surveyor Name : MARCUS CHUA
Survey Date : 11/7/2019
Authorisation Date : 11/7/2019

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
SUPPLEMENTARY PARTS AND LABOURS							
84550-T5A-J30	BOX ASSY, CARGO FLOOR GATE	1	117.40	25	88.05	6.16	94.21
83853-SA7-980	BOLT ANCHOR	1	9.10	25	6.82	0.48	7.30
Sum Item					94.87	6.64	101.51

Survey By : _____
Date & Time : _____
Excess : _____
Status : _____
Signature : _____

Total Amount 94.87 6.64 101.51
Total (Inclusive of GST) 101.51

Printed on 19/7/2019 9:15:13 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (net GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**HONDA**20/7/2019
ATTN: Marcus Chua

Page 1/2

SERVICE PRE-INVOICE**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE PTE
 Chassis No: JHMGK3850KS208068
 License No: SMJ1585R
 Mileage: 5897
 Engine No: L13B14100261

Document No: SVO19044358
 Printed By: PSYOU
 Order Date: 11. July 2019
 Order Time: 9:43:35 AM
 Service Advisor: YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	
						Amount	GST
	TP DIRECT SETTLEMENT (J/NO:73030)						
	OWNER: NIRMALA D/O K BALAKRISHNAN						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 9/7/2019						
	SURVEYED BY: MARCUS						
	DATE: 11/7/2019						
	REF NO:						
	TP INSURER: AXA INSURANCE PTE LTD						
	TP VEH: SHC5515M						
73127-TY0-000	RUBBER C/WINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY, TAILGATE	1	78.90	25	59.17	4.14	63.31
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
04715-T5A-J50ZZ	FACE, RR, BUMPER	1	482.70	25	369.52	25.87	395.39
71593-T5A-J50	SPACER, R, RR, BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71596-T5A-J50	SPACER, L, RR, BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71505-T5A-J50	GARNISH, RR, BUMPER	1	38.30	25	28.72	2.01	30.73
91505-TM8-003	CLIP, BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPRR.	1	320.40	25	240.30	16.82	257.12
84840-T5A-003ZA	LINING ASSYRR, PANEL	1	60.80	25	45.60	3.19	48.79
33550-T5A-J02	TAILLIGHT ASSYL.	1	223.90	25	167.92	11.75	179.67
NMRS-4P-TM3040L	4PCS ACT RR-SENSOR	1	320.00		320.00	22.40	342.40
84550-T5A-J30	BOX ASSY, CARGO FLOOR GATE	1	117.40	25	88.05	6.16	94.21
83853-SAT-980	BOLTANCHOR	1	9.10	25	6.82	0.48	7.30
	SUM PARTS:				2,073.52	145.15	2,218.67
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	0760	1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST (N)						
BOBC	1864	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BOJSE	1864	1	80.00		160.00	11.20	171.20
	BODY JOINT SEALANT.						
BP00R	1864	1	220.00		220.00	15.40	235.40
	APPLY BODY UNDERSIDE COATING (N).						
BA02R	1864	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BC011R	0760	1	300.00		300.00	21.00	321.00
	REMOVE INSTALL & CALIBRATE REAR						
	VIEW CAMERA						
BG02D	1864	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN.						
	(N)						

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZA006 / AXA INSURANCE PTE	Document No:	SVO19044358
Chassis No:	JHMGK3850KS208068	Printed By:	PSYOU
License No:	SMJ1585R	Order Date:	11. July 2019
Mileage:	5897	Order Time:	9:43:35 AM
Engine No:	L13B14100261	Service Advisor:	YOU PO SOON

BMI01D	1864 REMOVE & INSTALL ROOF LINING GARNISHES SEATS SPEAKER BOARD CARPET & ETC.(N)	1	350.00	350.00	24.50	374.50
BKTG02R	1864 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50
BKRP02B	1864 CUT & RENEW RR FLOOR PANEL. STRAIGHTEN FENDERS ALIG RR CHASSIS INCLUDING FITTING ON ATTACHMENT ITEMS.	1	3,360.00	3,360.00	235.20	3,595.20
BP07R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(7P)	1	2,650.00	2,650.00	185.50	2,835.50
			SUM LABOUR:	8,140.00	569.80	8,709.80
			TOTAL SGD	10,213.52	714.95	10,928.47
Total Payable (SGD)					10,928.47	

GST Amount is calculated from individual line(s)