



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19003020	Page	1
	8 SHENTON WAY	Date	: 9. Jul 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: YOU PO SOON		
Registration No	: SMJ1585R	Engine No	: L13B14100261		
Chassis No	: JHMGK3850KS208068	Date Time	: 9. Jul 2019 3:38:45 PM		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Surveyor Name	:		
Owner's Name	: NIRMALA D/O K BALAKRISHNAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 9/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: NIRMALA D/O K BALAKRISHNAN						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 9/7/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE PTE LTD						
	TP VEH: SHC5515M						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
74890-T5A-A11	GARNISH ASSY,RR LICENCE	1	105.50	25	79.12	5.54	84.66
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	53.70	25	40.27	2.82	43.09
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.10	25	3.82	0.27	4.09
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE	1	78.90	25	59.17	4.14	63.31
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71505-T5A-J50	GARNISH,RR.BUMPER	1	38.30	25	28.72	2.01	30.73
71502-T5A-J60	COVER,R.RR.BUMPER	1	20.70	25	15.52	1.09	16.61
71507-T5A-J60	COVER,L.RR.BUMPER	1	20.70	25	15.52	1.09	16.61

Printed on 9/7/2019 5:33:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SMJ1585R
Chassis No : JHMGK3850KS208068
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : NIRMALA D/O K BALAKRISHNAN
Ins Policy No. :
Date of Accident : 9/7/2019

Document No. : SQT19003020
Date : 9. Jul 2019
Customer No. : WZA006
Svc Advisor : YOU PO SOON
Engine No : L13B14100261
Date | Time : 9. Jul 2019 3:38:45 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71503-T5A-J50	COVER,RR.EXPI FIN	1	9.30	?	6.97	0.49	7.46
91505-TM8-003	CLIP,BUMPER	7	2.30	✓	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPRR.	1	320.40	✓	240.30	16.82	257.12
04655-TAS-310ZZ	PANEL SET,RR.FLOOR	1	697.00	?	522.75	36.59	559.34
63320-T5A-900ZZ	GUTTER COMP,R.RR.PILLAR	1	88.60	?	66.45	4.65	71.10
63720-T5A-900ZZ	GUTTER COMP,L.RR.PILLAR LOWER	1	88.60	?	66.45	4.65	71.10
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	✓	45.60	3.19	48.79
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1	169.00	?	126.75	8.87	135.62
84601-TAR-Z03ZA	LINING ASSYL.TRUNK	1	169.00	?	126.75	8.87	135.62
33500-T5A-J02	TAILLIGHT ASSY,R.	1	223.90	?	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL.	1	223.90	✓	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYL.LID	1	81.70	?	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID	1	81.70	?	61.27	4.29	65.56
72841-SH3-315	OILSHEET	1	40.70	?	30.52	2.14	32.66
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00	✓	320.00	22.40	342.40
Sum Item					3381.17	236.69	3,617.86
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00	✓	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	2	80.00	✓	160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	220	250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00	130	150.00	10.50	160.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00	300	320.00	22.40	342.40
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00	✓	300.00	21.00	321.00
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	250.00	✓	250.00	17.50	267.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	✓	350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00	✓	450.00	31.50	481.50

Printed on 10/7/2019 2:13:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

Registration No : SMJ1585R

Chassis No : JHMGK3850KS208068

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : NIRMALA D/O K BALAKRISHNAN

Ins Policy No. :

Date of Accident : 9/7/2019

Document No. : SQT19003020

Page 3

Date : 9. Jul 2019

Customer No. : WZA006

Svc Advisor : YOU PO SOON

Engine No : L13B14100261

Date | Time : 9. Jul 2019 3:38:45 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKRP02B	CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG	1	4100.00	3360	4100.00	287.00	4387.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	3300.00	2650	3300.00	231.00	3531.00
Sum Labor					9880.00	691.60	10,571.60

Survey By

Date & Time

Excess

Status

Signature

Total Amount	13,261.17	928.29	14,189.46
---------------------	------------------	---------------	------------------

Total (Inclusive of GST)	<u>14,189.46</u>
--------------------------	------------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 9/7/2019 5:33:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.