

TAN HUP SENG AUTO REPAIR WORKSHOP
 160 SIN MING DRIVE #01-03
 SIN MING AUTO CITY
 SINGAPORE 575722
 TEL : 64536069 Fax : 64536731
 Email: tonytong@singnet.com.sg

HP:98306069

Estimate cost of repair

FEA01BA415
 GBD 2857L

FEA01BA00415
 MIT CENTER

1	FRONT BUMPER ✓ BT	1 PC	\$	879.00	551
2	FRONT BUMPER BRACKET RH ✓ BT	1 PC	\$	118.00	67
3	FRONT BUMPER BRACKET LH ✓ BT	1 PC	\$	118.00	67
4	FRONT RH BUNMPER SIDE ✓ DE	1 PC	\$	298.00	✓
5	REAR NUMBER PLATE LAMP X NN	1 PC	\$	-	
6	FRONT PANEL ✓ BUC	1 PC	\$	990.00	540
7	FRONT PANEL CLIP ✓ NEC	8 PC	\$	52.00	15
8	FRONT WIPER PANEL X REPAIR	1 PC	\$	-	
9	FRONT GRILLE ✓ CRA	1 PC	\$	526.00	266
10	FRONT HEAD LAMP RH ✓ CRA	1 PC	\$	594.00	420
11	FRONT SIDE GARNISH RH ✓ MIS	1 PC	\$	85.00	✓
12	FRONT SIGNAL LAMP RH ✓ CRA	1 PC	\$	283.00	196
13	FRONT CORNER PANEL RH ✓ DE	1 PC	\$	486.00	303
14	FRONT WING MIRROR STAY TOP COVER X NN	1 PC	\$	-	
15	FRONT DOOR PILLAR RH X NN	1 PC	\$	-	
16	AIR CON CONSOLE CASING ✓ CRA	1 PC	\$	653.00	✓
17	STEERING AIR BAG ✓ ACT	1 PC	\$	2,979.41	1200 (SN)
18	STEERING SRS WIRE COIL ✓ ACT	1 PC	\$	285.00	✓
19	SRS CONTROL MODULE ECU ✓ ACT	1 PC	\$	1,699.00	✓
20	SRS SAFETY BELTS ✓	1 PC	\$	759.00	✓
21	FRONT GRILLE EMBLEM ✓	1 PC	\$	69.00	✓
				\$	10,873.41 6273
less 20%				\$	2,174.68
				\$	8,698.73 5018.4

FRONT NUMBER PLATE ✓	\$	25.00	15
RH DOOR ID STICKER ✓	\$	20.00	✓
			35
LABOUR CHARGES FOR REPLACE OF FRONT PANEL	\$	950.00	800
RESPRAY PAINTWORKS	\$	750.00	650
WIRING OF LIGHTING .	\$	80.00	30
REWIRING OF CCTV	\$	80.00	40
DISMENTLE DASH BOARD	\$	280.00	200
REPAIR OF AIR CON CONSOLE	\$	280.00	150
TOTAL	\$	11,163.73	1870

8123.4

-20%: 6500

TAN HUP SENG AUTO REPAIR WORKSHOP
 160 SIN MING DRIVE #01-03
 SIN MING AUTO CITY
 SINGAPORE 575722
 TEL : 64536069 Fax : 64536731
 Email: tonytong@singnet.com.sg

HP:98306069

FEA01BA415
 GBD 2857L

FEA01BA00415
 MIT CENTER

Estimate cost of repair

1	FRONT BUMPER / BT	1 PC
2	FRONT BUMPER BRACKET RH / 4BT.	1 PC
3	FRONT BUMPER BRACKET LH	1 PC
4	FRONT RH BUNMPER SIDE / re	1 PC
5	REAR NUMBER PLATE LAMP X	1 PC
6	FRONT PANEL / BUC	1 PC
7	FRONT PANEL CLIP / re	8 PC
8	FRONT WIPER PANEL X Repair.	1 PC
9	FRONT GRILLE / CRA	1 PC
10	FRONT HEAD LAMP RH - CRA	1 PC
11	FRONT SIDE GARNISH RH - mis	1 PC
12	FRONT SIGNAL LAMP RH - CRA	1 PC
13	FRONT CORNER PANEL RH - re	1 PC
14	FRONT WING MIRROR STAY TOP COVER X	1 PC
15	FRONT DOOR PILLAR RH X repair.	1 PC
16	AIR CON CONSOLE CASING X	1 PC

Air bag /
 " " stealing gone /
 " " less 20%
 " " ECU /
 Front Grille Emblem /
 FRONT NUMBER PLATE - BT.

8 Days.
 (unsum repair.
 After repair photo
 Cmo Biam.
 82 880282
 11/7/19.

LABOUR CHARGES FOR REPLACE OF FRONT PANEL
 RESPRAY PAINTWORKS
 WIRING OF LIGHTING .
 REWIRING OF CCTV
 DISMENTLE DASH BOARD
 REPAIR OF AIR CON CONSOLE

TOTAL

\$	950.00	500 800
\$	750.00	600
\$	80.00	30.
\$	80.00	40
\$	280.00	200
\$	280.00	150
\$	<u>2,420.00</u>	