

**Shu Fatt Auto Works**  
**Singapore**  
**159723**

Claim Reference:

Assessment number: SF089

Version: 1810

Date calculated: 10/07/2019 2:30 PM

Full Report

Registration: SLB4529S

Printed: 10/07/2019 2:30 PM

**Material Cost - Paint**

|                                     |
|-------------------------------------|
| New Part Painting                   |
| New Part Painting - Plastic K1R     |
| Repair Painting                     |
| Surface-/Blend Paint                |
| Material-constant Metal Preparation |
| Material-constant Plastic           |
| <b>Total</b>                        |

|                  |
|------------------|
| <b>Price SGD</b> |
| 122.81           |
| 56.09            |
| 40.30            |
| 39.10            |
| 28.60            |
| 9.00             |
| <b>295.90</b>    |

**Spare Parts**

| Code | Description          | Part Number   | Supplier       | prices as at 2015-06-01/01 |   |
|------|----------------------|---------------|----------------|----------------------------|---|
|      |                      |               |                | Price SGD                  |   |
| 0283 | FRONT BUMPER         | 71101T5LT10ZZ | 710R ✓         | 380.00                     | ✓ |
| 0317 | L/F OUT BUMPER BRKT  | 71198T5A000   | ne ✓           | 8.00                       | ✓ |
| 0318 | R/F OUT BUMPER BRKT  | 71193T5A000   | X SUC          | 8.00                       |   |
| 0319 | L/F UPP BUMPER BRKT  | 71190T5A000   | ne ✓           | 18.00                      | ✓ |
| 0340 | FRT BUMPER SUPPORT   | 71130T5LT00ZZ | ? X SUC        | 160.00                     |   |
| 0343 | FRONT BUMPER SPOILER | 71110T5A000   | X SUC          | 125.00                     |   |
| 0350 | FRT BUMPER CLAMP KIT | 91505TM8003   | ne ✓           | 30.00                      | ✓ |
| 0351 | FRT LWR BUMP GRILLE  | 71102T5A000   | X SUC          | 38.00                      |   |
| 0410 | GRILLE               | 71120T5AU00   | scr ✓          | 220.00                     | ✓ |
| 0471 | BONNET               | 60100T5LT00ZZ | bt ✓           | 260.00                     | ✓ |
| 0475 | L/BONNET HINGE       | 60170T5A000ZZ | ? X SUC        | 25.00                      |   |
| 0476 | R/BONNET HINGE       | 60120T5A000ZZ | X SUC          | 25.00                      |   |
| 0481 | BONNET INSULATION    | 74141T5LT00   | X SUC          | 70.00                      |   |
| 0501 | L/BONNET SEAL        | 74192T5A000   | ne X X AN      | 55.00                      |   |
| 0502 | R/BOONET SEAL        | 74142T5A000   | ne X X AN      | 55.00                      |   |
| 0503 | L/F BONNET GASKET    | 74122T5A000   | ? X SUC        | 55.00                      |   |
| 0504 | R/F BONNET GASKET    | 74121T5A000   | ? X SUC        | 55.00                      |   |
| 0561 | L/F HEADLAMP         | 33150T5AJ01   | BRG ✓          | 750.00                     | ✓ |
| 0637 | L/F FOG LAMP         | 33950TY0003   | ? CUC ✓        | 210.00                     | ✓ |
| 0639 | L/DAYT RUNNING LAMP  | 33250T5AG01   | 3C ✓           | 160.00                     | ✓ |
| 0643 | L/F BUMPER COVER     | 71108T5AJ00   | de ✓           | 35.00                      | ✓ |
| 0741 | L/F WING             | 60261T5HH10ZZ | buc ✓          | 155.00                     | ✓ |
| 0789 | L/F WING CLAMP KIT   | 934050601608  | ne ✓ 25        | 20.00                      | ✓ |
| 0841 | L/WHEELHOUSE SHELL   | 74150T5LT00   | repair cut ✓   | 85.00                      | ✓ |
| 1009 | FRONT PANEL CPL      | 60400T5LT01ZZ | repair ✓       | 310.00                     | ✓ |
| 1119 | L/F WHEELHOUSE REINF | 04684T5LT00ZZ | repair ✓ TO 14 | 230.00                     | ✓ |
| 1167 | L/F UP W-HOUSE REINF | 60710T5LP00ZZ | repair ✓ 60 bt | 180.00                     | ✓ |
| 1203 | L/F SIDE MEMBER      | 60911T5NM00ZZ | repair ✓       | 480.00                     | ✓ |
| 1305 | L/S-MEMB CLOSING PNL | 60946T5A300ZZ | ? X SUC        | 25.00                      |   |
| 1306 | R/S-MEMB CLOSING PNL | 60846T5A300ZZ | X SUC          | 25.00                      |   |
| 1398 | R/COWL PANEL TRIM    | 74147T5A000   | X SUC          | 200.00                     |   |