

FORM 100

ASS. REC. BY:

REP: CS/UOI19012263/U+P3ⁿ²

Special Instructions:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Felis

of

UOI

Date/Time:

5:23pm @ 10/7/19

Estimated Cost:

Bill to:

GD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 4321S

Insured:

GBH 9150A

at Workshop w/h

Think One Auto

Tel:

91288488

of

10-18104th Avenue 2

Policy No:

DHOM11016516/800

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A

9/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:11am @ 11/7/19

Person Contacted:

Keiren

Vehicle IN / OUT

Date/Time	Action/Instruction
	1. Shredded ✓
	PC 4321S-X
	GBH 9150A-X

JOB(11/13) waf
ASS. REC. BY: Marcus

REF:

401

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: PC 43215
at Workshop m/s: Think one
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 28228

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC 43215 Yr Regt: 12/15
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Toyota hiace commuter 2982
Colour: 5. her A/C: Insured / Std / NI / NA
Sp. Reading: 278025 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KDH2230026109
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195 R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>9/7/19</u>	D.O.I. <u>12/7/19</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
22/7/19 Continued L/S \$6300 with m. chn
(Red: 0029.60, 58%)

RECEIVED 22 JUL 2019

Date/Time, File Pass to?

1) 22/7/19 Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report

☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) S + RS \$ _____

) Photos 580

) Others 000

TOTAL

5X 25 = 125

250 + 125

60

80

86

601

Report Format: TP

Lump Sum / I.B.I: (\$ 6300)

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

SAVE \$5 ON UR CAR

INSURANCE RENEWAL



Compare 10+ Insurers

CLICK HERE

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Rare 2000 Mercedes Avantgarde E200 Kompressor On ...



Factory Options:- Sport Suspension,Avantgarde Rims,F/R Parking Assist,Xenon Light
Direct Owner - StarAd

P

PRIME MOTOR & LEASING

ICHONG HING CREDIT ENTERPRISES PTE.LTD. GROUP OF COMPANIES

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted






20 results/page

5 vehicles

toyota hiace commuter

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota hiace commuter		Any	Any	2015	Any	Any	Any	Available
	Toyota Hiace Commuter 3.0A GL		\$58,500	\$10,240 /yr	28-Mar-2015	2,982 cc	348,945 km	Bus	Available
Fuel Type: Diesel									
Think One Automobile & Trading									
Posted: 11-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace Commuter 3.0A GL		\$57,800	\$9,120 /yr	12-Nov-2015	2,982 cc	-	Bus	Available
Fuel Type: Diesel									
In House Finance Available, Quick Approval.									
Posted: 09-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace Commuter 3.0M		\$58,500	\$9,100 /yr	14-Dec-2015	2,982 cc	17,300 km	Bus	Available
Fuel Type: Diesel									
Think One Automobile & Trading									
Posted: 06-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace Commuter 3.0A		\$67,800	\$10,550 /yr	14-Dec-2015	2,982 cc	110,065 km	Bus	Available
Fuel Type: Diesel									
14 Seaters Passenger Mini Bus! Easy And Flexible In-House Financing Available, Keyless Entry/Start, Auto Power Siding Door, DVD/Bluet...									
Posted: 02-Jul-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Clean and green Subaru Forester e-Boxer								
The new Subaru Forester e-Boxer is a hybrid SUV that has left forced-induction behind, but it is a cleaner and greener option for buyers.									
Find out more!									
	Toyota Hiace Commuter 3.0A GL		\$57,800	\$9,690 /yr	29-Jun-2015	2,982 cc	-	Bus	Available
Fuel Type: Diesel									
Reliable Euro 5 Engine, Trade In/Finance/Insurance/Workshop! Full Loan At \$1211 Monthly, 85% Loan Of Car Price At \$998 Monthly. W...									
Think One Automobile & Trading									
Posted: 25-Jun-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace Commuter 3.0A GL		\$61,000	\$9,770 /yr	08-Oct-2015	2,982 cc	180,000 km	Bus	Available
Fuel Type: Diesel									
Car Register On Oct 2015, Accident-Free.									
Posted: 24-May-2019 Tags: 2015 Toyota Hiace, 2015 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									

Compare

CREDIT CHECK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8815Z
Vehicle Details	
Vehicle No.:	PC4321S
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 AT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2567438
Chassis No.:	KDH2230026109
Maximum Power Output:	-
Open Market Value:	\$39,945.00
Original Registration Date:	23 Dec 2015
First Registration Date:	23 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$1,998.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,809.00
COE Rebate Amount:	\$28,228.00
Total Rebate Amount:	\$28,228.00

The information contained herein is correct as at 12 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/07/2019 15:14
Date Of Accident	09/07/2019 10:05
Exact Location Of Accident	ALONG AYE TOWARDS MCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC4321S
Insured/Policyholder	
Name Of Registered Owner	TRANSASIA MARINE SERVICES PTE.LTD.
Co Reg No	201118815Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91452812
Alternative Phone No	OFFICE-91452812

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 COMMUTER GL (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5076639921-03
Cover Note Number	

Driver

Name of Driver	KARTHIGESAN S/O KRISHNAN
NRIC No	S7539607D
Date Of Birth	16/12/1975
Occupation	OUTDOOR
Date Of Driving Pass	26/02/2009
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91452812
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 97 COMMONWEALTH CRESCENT #02-34
Postcode	040097
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9150A
Vehicle Make/Model/Colour	TOYOTA DYNA PICKUP
Details Of Properties	FRONT DAMAGED
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Address	BLK 97 COMMONWEALTH CRESCENT #02-34
Postcode	040097
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9150A
Vehicle Make/Model/Colour	TOYOTA DYNA PICKUP
Details Of Properties	FRONT DAMAGED
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may affect insurance coverage or **expedite policy liability**.
4. THE ISSUE AND ACCEPTANCE OF THIS FORM BY INSURER COMPANIES IS NOT AN ADMISSION OF BASIC FACTS OR THE GUILT OF THE INSURANCE COMPANY.
5. **Any false reporting may be referred to the Police for investigation**.
6. This report will be forwarded by the Insurer to the Civil Flight Management Centre established by the Transport Ministry, Republic of Singapore (CFM) for archiving and that a copy of this report will for a fee be made available upon application to interested parties.
7. By this agreement of this report, I/We, Insurer, jointly and severally consent to the archiving of this report and the written consent of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' insurer(s) (if any), the Monetary Authority of Singapore and any relevant government agency/authority (such as the driver, for the purposes of):
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurer's insurer(s) (if any) are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes, and
- (c) the Personal Information may be disclosed under to the insurer and/or insurer's insurer(s) (if any) for purposes of administering their respective "claims" activities related to me in Singapore, for one or more of the above purposes.
- (d) My Personal Information will be collected and used to comply claims, "only" for the purpose of the 2-vehicle investigation and management is process and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that exist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Think One Autocare Pte Ltd
18 Defu Lane Avenue 2
Singapore 539522
Tel: 8844 3300 Fax: 6842 4988

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

9/1/2019 about 10:09 am I was driving towards MCE on lane 3 of A46 suddenly I felt a bump on road surface so I slight to the right and about the pickup bus in lane 4 CBH 915 MA rolled over and hit my car from the side. Body damaged.

DECLARATION

(/We declare the foregoing particulars are true in every respect)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Think One Autocare Pte Ltd
18 Defu Lane Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Not Affect
nln
a/r #6300/
Sdy.
12/7/19
Therese Affricage

PC4321S TOYOTA HIACE H/ROOF KDH223-0026109

DATE 9/10/2019

No	Qty	PARTICULAR	AMOUNT S\$
1	1	TAIL GATE	2,062.00
2	1	TAIL GATE PILLAR LH	425.00 X
3	1	TAIL GATE TRIM BOARD	428.00 ?
4	1	TAIL GATE LOCK	509.20
5	1	TAIL GATE LOCK MECHANISM	330.00
6	1	TAIL GATE INNER LOCK HANDLE	125.00
7	1	TAIL GATE LOCK CATCH	68.00 X
8	2	TAIL GATE DAMPER	539.60 X
9	1	TAIL GATE (HIACE) EMBLEM	125.00
10	1	TAIL GATE (LOGO) EMBLEM	165.00
11	1	TAIL GATE CHROME	322.00
12	4	TAIL GATE RUBBER STOPPER	80.00 X
13	1	REAR FLOOR PANEL	899.00 X
14	1	REAR END PANEL GARNISH	298.00
15	1	REAR END PANEL INNER	1,288.00
16	1	REAR END PANEL OUTER	1,288.00
17	1	REAR BUMPER	1,260.00
18	2	REAR BUMPER SIDE RETAINER	243.00 X
19	1	TAIL LAMP ASSY LH	786.00
20	1	REAR FENDER PANEL LH	1,988.00 X
			\$ 13,228.80
			\$ 3,307.20
			\$ 9,921.60

No	Qty	PARTICULAR	SPECAIL NETT	AMOUNT S\$
1	1	REAR WINDSCREEN GLASS SEALANT	rec	90.00
2	1	REAR WINDSCREEN GLASS INNER SEAL	rec	135.00
3	1	REAR SIDE PANEL GLASS SEALANT	11	90.00 X
4	1	TAIL GATE COMPANY STICKER	rec	480.00
5	1	70 KM/H STICKER	rec	25.00
6	1	REAR NUMBER PLATE (PAINT)	11	40.00
7	8	TAIL GATE TRIM BOARD CLIP	rec	48.00
8	1	REVERSE SENSOR	shld	250.00
				\$ 1,158.00

LABOUR & MISCELLANEOUS:

1	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,800.00
2	To spray paint replaced/repared body parts inclusive of preparatory works and painting materials	1,200.00
3	To transfer tail gate components with all necessary attachments	250.00

4	To remove,refix rear windscreen glass and water test	250.00	120
5	To remove,refix side panel glass and water test LH	17 250.00	X
6	To remove,refix rear interior garnishes upholstery	200.00	60
7	To install reverse sensor and test funtion	100.00	40
		<u>\$ 4,050.00</u>	

15129.60



P-5017.12
 s.w-728.00
 cabm-2160.00
 7905.12
 200
 6324.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI19012263/Uff3n2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date : 25-07-2019	
			Code : UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 9150A	Veh. Inspected	PC 4321S	
Policy No.	DHOM110165161800	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	FELIS	Assign Date	10/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KDH2230026109	Colour	SILVER	
Odometer	278025	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MICHELIN	6 mm	
L/H Front Tyre	195 R15	MICHELIN	6 mm	
R/H Rear Tyre	195 R15	MICHELIN	6 mm	
L/H Rear Tyre	195 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/07/2019	Inspection Date	12/07/2019	
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 4321S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAIL GATE	BADLY DENTED	2,062.00	2,062.00
1	TAIL GATE PILLAR LH	TO REPAIR SEE LABOUR	425.00	-
1	TAIL GATE TRIM BOARD	TORN	428.00	428.00
1	TAIL GATE LOCK	DENTED / JAMMED	509.20	359.00
1	TAIL GATE LOCK MECHANISM	BENT / JAMMED	330.00	330.00
1	TAIL GATE INNER LOCK HANDLE	CRACKED	125.00	125.00
1	TAIL GATE LOCK CATCH	NOT NECESSARY	68.00	-
2	TAIL GATE DAMPER @\$269.80	NOT NECESSARY	539.60	-
1	TAIL GATE (HIACE) EMBLEM	NECESSARY	125.00	65.00
1	TAIL GATE (LOGO) EMBLEM	NECESSARY	165.00	68.10
1	TAIL GATE CHROME	CRACKED	322.00	322.00
4	TAIL GATE RUBBER STOPPER @\$20.00	NOT NECESSARY	80.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	899.00	-
1	REAR END PANEL GARNISH	TWISTED	298.00	298.00
1	REAR END PANEL INNER	BADLY DENTED	1,288.00	936.20
1	REAR END PANEL OUTER	BADLY DENTED	1,288.00	866.10
1	REAR BUMPER	DISTORTED	1,260.00	465.00
2	REAR BUMPER SIDE RETAINER @\$121.50	NOT NECESSARY	243.00	-
1	TAIL LAMP ASSY LH	CRACKED	786.00	365.10
1	REAR FENDER PANEL LH	TO REPAIR SEE LABOUR	1,988.00	-
LESS 25% DISCOUNT			-3,307.20	-1,672.38
			9,921.60	5,017.12
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	90.00	40.00
1	REAR WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	135.00	30.00
1	REAR SIDE PANEL GLASS SEALANT (SN)	NOT NECESSARY	90.00	-
1	TAIL GATE COMPANY STICKER (SN)	NECESSARY	480.00	400.00
1	70 KM/H STICKER (SN)	NECESSARY	25.00	10.00
1	REAR NUMBER PLATE (PAINT) (SN)	NOT NECESSARY	40.00	-
8	TAIL GATE TRIM BOARD CLIP @\$6.00 (SN)	NECESSARY	48.00	48.00

Report Ref No. CS/UOI19012263/Utf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			1,158.00	728.00
	LABOUR			
	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR, RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS. INCLUSIVE OF THE REPAIR OF TAIL GATE PILLAR LH, REAR FLOOR PANEL AND REAR FENDER PANEL LH.		1,800.00	1,080.00
	TO SPRAY PAINT REPLACED / REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		1,200.00	800.00
	TO TRANSFER TAIL GATE COMPONENTS WITH ALL NECESSARY ATTACHMENTS.		250.00	60.00
	TO REMOVE, REFIX REAR WINDSCREEN GLASS AND WATER TEST.		250.00	120.00
	TO REMOVE, REFIX SIDE PANEL GLASS AND WATER TEST LH.	NOT NECESSARY	250.00	-
	TO REMOVE, REFIX REAR INTERIOR GARNISHES UPHOLSTERY.		200.00	60.00
	TO INSTALL REVERSE SENSOR AND TEST FUNCTION.		100.00	40.00
			4,050.00	2,160.00
GRAND TOTAL			15,129.60	7,905.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,300.00

Report Ref No. CS/UOI19012263/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.