

INS. CASE OWNER:

CC 4 / LPC 9012271

R1 ha3m

IDAC:

Surveyor:

RAGUL

DOI:

ASSIGNMENT

16/07/19

Date / Time:

11/07/2019

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

GIBE 2875D

Claim No.:

19/19/19 / VC05/022051

Name of Insured:

Heng Shm Butchus P/L

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

5/7/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability: % Final ? Yes / No

SME 2772L



INSRS:

WSP: Kah Motor

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

SME 2772L : X

GIBE 2875D : NA/LPC/000242/24; D.O.A: 5/7/19

15/07/19

- FILE REVIEWED. OIB INVOLVED IN A
3 VEH. C.C.; OIB 2ND CATE.
- EMAIL LIABILITY CLERK
- MINA REVIEWED

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

10/08/19

- TYPE REPORT WHILE HANDLING TP LOD
- REPORT DONE
- TP LOD IN BY EMAIL

05/10/19

- 900K WANDERER APPROVAL TO LPC

30/10/19

- LPC APPROVED WANDERER
- SEND ACCEPTANCE EMAIL TO TP.
- ON IN. ALL DOCS IN OK STATE.
- TO CLOSE.

PRELIMINARY ADVICE

Date/Time:

18/07/19

Sent By:

93

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

S\$ 6,269.04

(6 days)

Reduction:

A3

%

Email

Call

FINAL SETTLEMENT

Date/Time:

06/11/19

Confirm with:

P/S/00000

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

0%

Repair Cost:

(w/cost)

S\$ 6,707.86

Loss of Rental (LOR):

(w/cost)

S\$ 535.00

(5 days)

X \$100.00

Loss of Use (LOU):

S\$

-

(\$ x days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/Independent)

Legal Cost:

S\$

-

Total:

S\$

7,244.86

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7,244.86

Name 1:

KAH MOTOR CO. SDN. BHD.

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

Signature: *Rasul*

REF: LPC

12771/21(W)

71422

ASSIGNMENT

From: Date: 16.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SME 2772L

at Workshop in/s: Kan motor

of 255 Alexandra Road

Insured

Policy No.

Claims No.

Sum Insured


Excess:

(Client's Record)

Make of Veh: After 10-00 a.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SME 2772L Yr Regn: 2018 / SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HR-V 1.50X C.C. 1496

Colour: Red A/C Insured / Std / NI / NA

Sp. Reading: 016573 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JAMRU 18103X200489

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 05/07/19

Survey held at: KAH MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/D \$6,269.04
CRAB: \$4,877.34 (13%)

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee

Transportation

\$ + RSL \$

Photos

Others

TOTAL

Report Format :

Lump Sum / L.B.I: (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 19/19/19/VC05/022051
Our ref: CC4/LPC19012271/R1ha3

Date: 18/07/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SME 2772L


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/07/2019 at the premises of M/s Kah Motor Co Sdn Bhd and have the following to report:-

Workshop Estimate Amount	: S\$	10,397.32
Revised Estimate Amount	: S\$	5,755.63
"Check" Items Amount	: S\$	916.69
Total (Including Check Items)	: S\$	6,672.32
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5-6 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

VIC



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: TAN NGEE KHIAM	Document No.	: SQT19003008	Page	1
	130 CHOA CHU KANG AVENUE 1	Date	: 8. Jul 2019		
	#11-32	Customer No.	: ****7142Z		
	SINGAPORE 680130	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: SME2772L	Engine No	: L15B5670489		
Chassis No	: JHMRU1810JX200489	Date Time	: 8. Jul 2019 7:38:07 PM		
Model	: HRV DX-SIN CVT YM 2018	Surveyor Name	:		
Owner's Name	: TAN NGEE KHIAM	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 5/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN NGEE KHIAM OWNER INSURER: TOKIO MARINE ACC DATE: 05/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: GBE2875D						
68100-T7A-J20ZZ	TAIL GATE COMP <i>bl/</i>	1	855.70 ✓	25	641.77 ✓	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE <i>? xan</i>	1	98.70	25	74.02	5.18	79.20
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY <i>? xan</i>	1	163.20	25	122.40	8.57	130.97
75722-T7W-A01	EMBLEMRR <i>de</i>	1	13.30 ✓	25	9.97 ✓	0.70	10.67
75725-T8N-T00	EMBLEM, RR I-VTEC <i>de</i>	1	14.50 ✓	25	10.87 ✓	0.76	11.63
74890-T7A-013ZN	GARNISH ASSYRR, LICENSE <i>? xan</i>	1	132.20	25	99.15	6.94	106.09
75701-T4G-000	EMBLEM <i>? xan</i>	1	24.20	25	18.15	1.27	19.42
90301-ST0-003	NUTPUSH 3MM <i>? xan</i>	2	2.10	25	3.15	0.22	3.37
71501-T7B-000	FACE RR BUMPER <i>de</i>	1	777.90 <i>463.70</i>	25	583.42 <i>543.77</i>	40.84	624.26
91505-TM8-003	CLIP, BUMPER <i>an</i>	8	2.30 ✓	25	13.80 ✓	0.97	14.77
71593-T7A-J00	SPACER, R RR BUMPER SIDE <i>an</i>	1	17.20 ✓	25	12.90 ✓	0.90	13.80
71598-T7A-J00	SPACER, LRR, BPR S <i>an</i>	1	17.20 ✓	25	12.90 ✓	0.90	13.80
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>xan</i>	1	45.00		45.00	3.15	48.15
66100-T7A-300ZZ	PANEL COMPRR <i>? xan</i>	1	373.10	25	279.82	19.59	299.41
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>? xan</i>	1	320.00		320.00	22.40	342.40
Sum Item					2247.32	167.31	2404.63
BOSUN	SUNDRIES	1	100.00 <i>50</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00 <i>50</i>		100.00	7.00	107.00

Printed on 16/7/2019 8:57:42 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (net GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : TAN NGEE KHAM
130 CHOA CHU KANG AVENUE 1
#11-32
SINGAPORE 680130
Registration No : SME2772L
Chassis No : JHMRU1810JX200489
Model : HRV DX-SIN CVT YM 2018
Owner's Name : TAN NGEE KHAM
Ins Policy No. :
Date of Accident : 5/7/2019

Document No. : SQT19003008
Date : 8. Jul 2019
Customer No. : ****7142Z
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B5670489
Date | Time : 8. Jul 2019 7:38:07 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST	
BOBC	BODY UNDERSIDE COATING (N)	1	350.00 280		350.00	24.50	374.50	
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 150		180.00	12.60	192.60	
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	480.00 450		480.00	33.60	513.60	
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	480.00 450		480.00	33.60	513.60	
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00 280		560.00	39.20	599.20	
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 150		180.00	12.60	192.60	
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20	
BKRP21M	CUT OFF & RENEW RR PANEL AND DAMAGE PARTS	1	3360.00 1120		3360.00	235.20	3595.20	
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	1800.00 900		1800.00	126.00	1926.00	
+ 9000					Sum Labor	8150.00	570.50	8,720.50

Survey By : Rasul - Hp 9000068
Date & Time : 16/07/19 @ 1200
Excess : 5-6 days
Status :
Signature : Refusing before paid

Total Amount 10,397.32 727.81 11,125.13
Total (Inclusive of GST) 11,125.13

11,146.39

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- New modification(s) is allowed
- Supplementary work must be resurveyed and is subject to cost from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

email: rasul@lkkauto.com

Printed on 16/7/2019 8:57:42 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$51.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



KAH MOTOR CO. SDN. BHD.

Supplementary

GST Reg No.: M200050223
Company Ref. No.: S80FC1380G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: WZL009 / LONPAC INSURANCE
Chassis No: JHMRU1810JX200489
License No: SME2772L
Mileage: 11064
Engine No: L15B5670489

Document No: SVO19045521
Printed By: IVANTEO
Order Date: 16. July 2019
Order Time: 12:09:17 PM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN NGEE KHAM OWNER INSURER: TOKIO MARINE ACC DATE: 05/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: GBE2875D SUPPLEMENTARY PART						
73215-T7A-003	RUBBER CR.WINDSHIELD DAM	1.	19.70	25.	14.77 ✓	1.03	15.80
73226-SZW-000	DAMPERSTD 5X5	1.	8.50	25.	6.37 ✓	0.45	6.82
73265-T7A-003	RUBBER,L.WINDSHIELD DAM	1.	19.70	25.	14.77 ✓	1.03	15.80
76711-T6A-003	CAPPVOT	1.	4.80	25.	3.60 ✓	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4.	5.30	25.	15.90 ✓	1.11	17.01
91502-S70-003	FASTENER B	2.	5.30	25.	7.95 ✓	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2.	3.80	25.	5.70 ✓	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2.	60.00		120.00 ✓	8.40	128.40
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00 ✓	39.20	599.20

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZL009 / LONPAC INSURANCE
 Chassis No: JHMRU1810JX200489
 License No: SME2772L
 Mileage: 11064
 Engine No: L15B5670489

Document No: SVO19045521
 Printed By: IVANTEO
 Order Date: 16. July 2019
 Order Time: 12:09:17 PM
 Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN NGEE KHAM OWNER INSURER: TOKIO MARINE ACC DATE: 05/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: GBE2675D						
68100-T7A-J20ZZ	TAIL GATE COMP	1	855.70 ✓	25	641.77	44.92	686.69
75722-T7W-A01	EMBLEMRR.	1	13.30 ✓	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50 ✓	25	10.87	0.76	11.63
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70 ✓	25	347.77	24.34	372.11
91505-TM8-003	CLIP,BUMPER	8	2.30 ✓	25	13.80	0.97	14.77
71593-T7A-J00	SPACER,R.RR.BUMPER SIDE	1	17.20 ✓	25	12.90	0.90	13.80
71598-T7A-J00	SPACER,L.RR.BPR S	1	17.20 ✓	25	12.90	0.90	13.80
73215-T7A-003	RUBBER CR.WINDSHIELD DAM	1	19.70	25	14.77	1.03	15.80
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73265-T7A-003	RUBBER,L.WINDSHIELD DAM	1	19.70	25	14.77	1.03	15.80
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
	SUM PARTS:				1,239.04	86.72	1,325.76
BOSUN	SUNDRIES	1	50.00 ✓		50.00	3.50	53.50
BOJSE	1610	1	80.00 ✓		80.00	5.60	85.60
BOBC	BODY JOINT SEALANT TAILGATE	1	280.00 ✓		280.00	19.60	299.60
BA02R	0669	1	150.00 ✓		150.00	10.50	160.50
BC011R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	450.00 ✓		450.00	31.50	481.50
BC012R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00 ✓		450.00	31.50	481.50
BMI03D	RESET VEHICLE SMART ENTRY SYSTEM	1	280.00 ✓		280.00	19.60	299.60
BML02I	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES (N)	1	150.00 ✓		150.00	10.50	160.50
	1757	1	150.00 ✓		150.00	10.50	160.50
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer:	WZL009 / LONPAC INSURANCE	Document No:	SVO19045521
Chassis No:	JHMRU1810JX200489	Printed By:	IVANTEO
License No:	SME2772L	Order Date:	16. July 2019
Mileage:	11064	Order Time:	12:09:17 PM
Engine No:	L15B5670489	Service Advisor:	IVAN TEO BOON KIAT

BKTG02R	1757 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00 ✓	560.00	39.20	599.20
BKRP21M	0669 CUT OFF & RENEW RR PANEL AND DAMAGE PARTS ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM	1	1,120.00 ✓	1,120.00	78.40	1,198.40
BP04R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)	1	900.00 ✓	900.00	63.00	963.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00 (S)	560.00	39.20	599.20
SUM LABOUR:				5,030.00	352.10	5,382.10
TOTAL SGD				6,269.04	438.82	6,707.86
Total Payable (SGD)						6,707.86

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: TAN NGEE KHIAM	Document No.	: SQT19003008	Page	1
	130 CHOA CHU KANG AVENUE 1	Date	: 8. Jul 2019		
	#11-32	Customer No.	: ****7142Z		
	SINGAPORE 680130	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: SME2772L	Engine No	: L15B5670489		
Chassis No	: JHMRU1810JX200489	Date Time	: 8. Jul 2019 7:38:07 PM		
Model	: HRV DX-SIN CVT YM 2018	Surveyor Name	:		
Owner's Name	: TAN NGEE KHIAM	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 5/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TAN NGEE KHIAM						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 05/07/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: LONPAC						
	TP VEH: GBE2875D						
68100-T7A-J20ZZ	TAIL GATE COMP <i>bt</i>	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE <i>??</i>	1	98.70	25	74.02	5.18	79.20
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY <i>?</i>	1	163.20	25	122.40	8.57	130.97
75722-T7W-A01	EMBLEMRR <i>re</i>	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM, RR, I-VTEC <i>m</i>	1	14.50	25	10.87	0.76	11.63
74890-T7A-013ZN	GARNISH ASSYRR, LICENSE <i>?</i>	1	132.20	25	99.15	6.94	106.09
75701-T4G-000	EMBLEM <i>?</i>	1	24.20	25	18.15	1.27	19.42
90301-ST0-003	NUTPUSH 3MM <i>?</i>	2	2.10	25	3.15	0.22	3.37
71501-T7B-000	FACE RR, BUMPER <i>de</i>	1	777.90	25	583.42	40.84	624.26
91505-TM8-003	CLIP, BUMPER <i>m</i>	8	2.30	25	13.80	0.97	14.77
71593-T7A-J00	SPACER, R, RR, BUMPER SIDE <i>m</i>	1	17.20	25	12.90	0.90	13.80
71598-T7A-J00	SPACER, L, RR, BPR S <i>m</i>	1	17.20	25	12.90	0.90	13.80
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>X</i>	1	45.00		45.00	3.15	48.15
66100-T7A-300ZZ	PANEL COMPRR <i>?</i>	1	373.10	25	279.82	19.59	299.41
NMRS-4P-TM3040L	4PCS ACT RR SENSOR <i>?</i>	1	320.00		320.00	22.40	342.40
Sum Item					2247.32	157.31	2,404.63
BOSUN	SUNDRIES	1	100.00 <i>50</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00 <i>50</i>		100.00	7.00	107.00

Printed on 16/7/2019 8:57:42 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : TAN NGEE KHIAM
130 CHOA CHU KANG AVENUE 1
#11-32
SINGAPORE 680130
Registration No : SME2772L
Chassis No : JHMRU1810JX200489
Model : HRV DX-SIN CVT YM 2018
Owner's Name : TAN NGEE KHIAM
Ins Policy No. :
Date of Accident : 5/7/2019

Document No. : SQT19003008
Date : 8. Jul 2019
Customer No. : ****7142Z
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B5670489
Date | Time : 8. Jul 2019 7:38:07 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOBC	BODY UNDERSIDE COATING (N)	1	350.00 280		350.00	24.50	374.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 150		180.00	12.60	192.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	480.00 450		480.00	33.60	513.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	480.00 450		480.00	33.60	513.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00 280		560.00	39.20	599.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 150		180.00	12.60	192.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BKRP21M	CUT OFF & RENEW RR PANEL AND DAMAGE PARTS	1	3360.00 1120		3360.00	235.20	3595.20
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	1800.00 900		1800.00	126.00	1926.00
Sum Labor					8150.00	570.50	8,720.50

Survey By

Date & Time

Excess

Status

Signature

Total Amount 10,397.32 727.81 11,125.13

Total (Inclusive of GST) **11,125.13**

5-6 days

Resurvey before paid

email: rasul@lkkauto.com

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Insurance notification(s) is allowed
- Supplies must be resurveyed and is subject to insurance company

Acknowledged by Repairer
Signature:
Date:

Printed on 16/7/2019 8:57:42 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 11 July 2019 8:56 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: CHECK LIABILITY SME2772L AGAINST GBE2875D (LONPAC) DOA 05/07/2019 [External Confidential]
Attachments: SAS2630043.pdf; Service Quote.pdf; GIA REPORT.pdf

10:40am 11/7/19
Person @ Ivan
VNI

Lonpac External - Confidential

Our Ref : 19/19/19/VC05/022051

Dear Nivitha,

Kindly proceed to survey and revert on Direct Settlement.

Attached copy of insured's report for your attention.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Ivan Teo [mailto:ivanteo@honda.com.sg]
Sent: Tuesday, 9 July, 2019 9:02 AM
To: MT_Claim_SG
Subject: CHECK LIABILITY SME2772L AGAINST GBE2875D (LONPAC) DOA 05/07/2019

Dear Motor Claims,

Kindly advise on 3rd party direct settlement liability.

My client : SME2772L

Your insured : GBE2875D

DOA : 05/07/2019

Thank you

Warmest Regards

Ivan Teo

Kah Motor Co. Sdn Bhd

6A Mandai Estate

Singapore 729903

DID : 86680608

Email: ivanteo@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19012271/R1ha3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 14-11-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	GBE 2875D	Veh. Inspected
			SME 2772L
	Policy No.	Z19VC05002691	Coverage (\$)
			0.00
	Claim No.	19/19/19/VC05/022051	Excess (\$)
			0.00
	Assign From	GERALD	Assign Date
			11/07/2019
2. Vehicle Particulars & Condition			
	Make & Model	HONDA HRV 1.5 DX	c.c
			1496
	Engine No.	HIDDEN	Year of Reg.
			2018
	Chassis No.	JHMRU1810JX200489	Colour
			RED
	Odometer	16573	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			SPORTS RIM
	General	FAIR	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	215/60 R16	DUNLOP
			6 mm
	L/H Front Tyre	215/60 R16	DUNLOP
			6 mm
	R/H Rear Tyre	215/60 R16	DUNLOP
			6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP
			6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
	DAMAGES SEE DETAILS.		
5. General Information			
	Accident Date	05/07/2019	Inspection Date
			16/07/2019
	Survey held at	255 ALEXANDRA ROAD	
	Repairer	KAH MOTOR.CO.SDN.BHD	
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.		
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 2772L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE COMP (SN)	BENT	641.77	641.77
1	WEATHERSTRIP TAILGATE (SN)	NOT NECESSARY	74.02	-
1	LOCK ASSY, TAILGATE ASSY (SN)	SERVICEABLE	122.40	-
1	EMBLEM RR (SN)	NECESSARY	9.97	9.97
1	EMBLEM, RR. I-VTEC (SN)	NECESSARY	10.87	10.87
1	GARNISH ASSY RR. LICENSE (SN)	NOT NECESSARY	99.15	-
1	EMBLEM (SN)	NOT NECESSARY	18.15	-
2	NUTPUSH 3MM (SN)	NOT NECESSARY	3.15	-
1	FACE RR. BUMPER (SN)	DEFORMED	583.42	347.77
8	CLIP, BUMPER (SN)	NECESSARY	13.80	13.80
1	SPACER, R.RR.BUMPER SIDE (SN)	NECESSARY	12.90	12.90
1	SPACER, L.RR.BPR S (SN)	NECESSARY	12.90	12.90
1	NUMBER PLATE WITH CASING - L (SN)	NOT NECESSARY	45.00	-
1	PANEL COMPRR (SN)	SERVICEABLE	279.82	-
1	4PCS ACT RR. SENSOR (SN)	SERVICEABLE	320.00	-
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	RUBBER CR. WINDSHIELD DAM (ADDITIONAL) (SN)	NECESSARY	14.77	14.77
1	DAMPERSTD 5X5 (ADDITIONAL) (SN)	NECESSARY	6.37	6.37
1	RUBBER L. WINDSHIELD DAM (ADDITIONAL) (SN)	NECESSARY	14.77	14.77
1	CAPPIVOT (ADDITIONAL) (SN)	NECESSARY	3.60	3.60
4	FASTENER BW/SHIELD (ADDITIONAL) (SN)	NECESSARY	15.90	15.90
2	FASTENER B (ADDITIONAL) (SN)	NECESSARY	7.95	7.95
2	FASTENER AW/SHIELD (ADDITIONAL) (SN)	NECESSARY	5.70	5.70
2	WINDSCREEN SEALANT (ADDITIONAL) (SN)	NECESSARY	120.00	120.00
			2,536.38	1,289.04
LABOUR				
	BODY JOINT SEALANT TAILGATE.		100.00	80.00
	BODY UNDERSIDE COATING.		350.00	280.00
	REMOVE & RENEW REVERSE SENSOR - 4PCS.		180.00	150.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		480.00	450.00

Report Ref No. CC4/LPC19012271/R1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESET VEHICLE SMART ENTRY SYSTEM.		480.00	450.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		560.00	280.00
	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER.		180.00	150.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &		560.00	560.00
	CUT OFF & RENEW RR PANEL AND DAMAGE PARTS.		3,360.00	1,120.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,800.00	900.00
	REPLACE RR. WINDSCREEN (ADDITIONAL)		560.00	560.00
			8,610.00	4,980.00
GRAND TOTAL			11,146.38	6,269.04
RECOMMENDED COST OF REPAIRS				6,269.04

Report Ref No. CC4/LPC19012271/R1ha3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.