



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

For 24-hours Roadside Assistance, Call 98203838

Website: www.honda.com.sg

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: TAN NGEE KHIAM 130 CHO A CHU KANG AVENUE 1 #11-32 SINGAPORE 680130	Document No.	: SQT19003008	Page	1
Registration No	: SME2772L	Date	: 8. Jul 2019		
Chassis No	: JHMRU1810JX200489	Customer No.	: ****7142Z		
Model	: HRV DX-SIN CVT YM 2018	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: TAN NGEE KHIAM	Engine No	: L15B5670489		
Ins Policy No.	:	Date Time	: 8. Jul 2019 7:38:07 PM		
Date of Accident	: 5/7/2019	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN NGEE KHIAM OWNER INSURER: TOKIO MARINE ACC DATE: 05/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC TP VEH: GBE2875D						
68100-T7A-J20ZZ	TAIL GATE COMP <i>bf</i>	1	855.70	25	641.77	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE <i>??</i>	1	98.70	25	74.02	5.18	79.20
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY <i>?</i>	1	163.20	25	122.40	8.57	130.97
75722-T7W-A01	EMBLEMRR. <i>ne</i>	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM, RR. I-VTEC <i>ne</i>	1	14.50	25	10.87	0.76	11.63
74890-T7A-013ZN	GARNISH ASSYRR.LICENSE <i>?</i>	1	132.20	25	99.15	6.94	106.09
75701-T4G-000	EMBLEM <i>?</i>	1	24.20	25	18.15	1.27	19.42
90301-ST0-003	NUTPUSH 3MM <i>?</i>	2	2.10	25	3.15	0.22	3.37
71501-T7B-000	FACE RR.BUMPER <i>de</i>	1	777.90	25	583.42	40.84	624.26
91505-TM8-003	CLIP, BUMPER <i>ne</i>	8	2.30	25	13.80	0.97	14.77
71593-T7A-J00	SPACER, R.RR.BUMPER SIDE <i>ne</i>	1	17.20	25	12.90	0.90	13.80
71598-T7A-J00	SPACER, L.RR.BPR S <i>ne</i>	1	17.20	25	12.90	0.90	13.80
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>X</i>	1	45.00		45.00	3.15	48.15
66100-T7A-300ZZ	PANEL COMPRR. <i>?</i>	1	373.10	25	279.82	19.59	299.41
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>?</i>	1	320.00		320.00	22.40	342.40
				Sum Item	2247.32	157.31	2,404.63
BOSUN	SUNDRIES	1	100.00 <i>50</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00 <i>50</i>		100.00	7.00	107.00

Printed on 16/7/2019 8:57:42 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : TAN NGEE KHIAM
130 CHOACHU KANG AVENUE 1
#11-32
SINGAPORE 680130
Registration No : SME2772L
Chassis No : JHMRU1810JX200489
Model : HRV DX-SIN CVT YM 2018
Owner's Name : TAN NGEE KHIAM
Ins Policy No. :
Date of Accident : 5/7/2019

Document No. : SQT19003008 Page 2
Date : 8. Jul 2019
Customer No. : ****7142Z
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B5670489
Date | Time : 8. Jul 2019 7:38:07 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOBC	BODY UNDERSIDE COATING (N)	1	350.00	280	350.00	24.50	374.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	150	180.00	12.60	192.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	480.00	450	480.00	33.60	513.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	480.00	450	480.00	33.60	513.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00	280	560.00	39.20	599.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	150	180.00	12.60	192.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BKRP21M	CUT OFF & RENEW RR PANEL AND DAMAGE PARTS	1	3360.00	1120	3360.00	235.20	3595.20
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	1800.00	900	1800.00	126.00	1926.00
Sum Labor					8150.00	570.50	8,720.50

Survey By Rasul - Hp 90010068

Date & Time 16/07/19 @ 1200

Excess _____

Status _____

Signature _____

Total Amount 10,397.32 727.81 11,125.13

Total (Inclusive of GST) 11,125.13

5-6 days

Resurvey before paid

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

email: rasul@lkkauto.com

Printed on 16/7/2019 8:57:42 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.