

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5492U**AAD1907-101**

Not Attached
Lump \$4000

Vehicle No.:

Chassis No.:

10 JUL 2019

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5492U

VF1ABL15AUC278814

RENAULT

LATITUDE

8.7.19

AIG

11/7/2014

PART**LIST**

1	1	BUMPER COVER FRT
2	1	BUMPER SPOILER FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT LH
5	1	BUMPER SUPPORT FRT
6	1	BUMPER RETAINER FRT RH
7	1	BUMPER SUPPORT FRT
8	1	BUMPER UNDERTRAY FRT
9	1	BUMPER GRILLE LOWER FRT
10	1	BUMPER FOG LAMP GRILLE LH
11	1	BUMPER FOG LAMP GRILLE RH
12	1	BUMPER BEAM FRT
13	1	TOW COVER FRT
14	1	FRONT BRACE PANEL
15	1	RADIATOR GRILLE
16	1	RADIATOR GRILLE BADGE 'RENAULT'
17	1	RADIATOR GRILLE FRAME
18	1	FRAME FULL SUPPORT PANEL
19	1	FRAME FULL SUPPORT BRACKET
20	1	HEADLAMP LH
21	1	HEADLAMP RH
22	1	HEADLAMP PANEL FRT LH
23	1	HEADLAMP PANEL FRT RH
24	1	BONNET
25	1	BONNET INSULATOR
26	1	BONNET STRUT LH
27	1	BONNET STRUT RH
28	1	BONNET HINGE LH
29	1	BONNET HINGE RH

\$	<i>Bu</i>	1,259.42	X
\$	<i>SL</i>	181.75	X
\$	<i>CNT</i>	394.68	<i>2</i>
\$	<i>SL</i>	151.41	X
\$	<i>SL</i>	123.88	X
\$	<i>SL</i>	150.77	X
\$	<i>SL</i>	123.88	X
\$	<i>SL</i>	472.83	X
\$	<i>CNT</i>	266.80	<i>✓</i>
\$	<i>SL</i>	207.21	X
\$	<i>SL</i>	207.21	X
\$	<i>R</i>	914.08	X
\$	<i>SL</i>	28.61	X
\$	<i>R</i>	177.22	X
\$	<i>myem</i>	1,707.78	<i>2</i>
\$	<i>ebu</i>	225.36	<i>2</i>
\$	<i>CNT</i>	1,353.75	<i>✓</i>
\$	<i>CNT</i>	615.90	<i>✓</i>
\$	<i>R</i>	89.79	<i>✓</i>
\$	<i>SL</i>	1,184.43	<i>✓</i>
\$	<i>SL</i>	1,184.43	<i>✓</i>
\$	<i>R</i>	152.15	<i>✓</i>
\$	<i>R</i>	152.15	<i>✓</i>
\$	<i>R</i>	1,941.63	<i>✓</i>
\$	<i>SL</i>	405.73	<i>✓</i>
\$	<i>SL</i>	88.61	<i>✓</i>
\$	<i>SL</i>	88.61	<i>✓</i>
\$	<i>R</i>	348.31	<i>✓</i>
\$	<i>R</i>	348.31	<i>✓</i>

Trans-cab Auto Services Pte Ltd**AAD1907-101**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5492U

30	1	BONNET CABLE COVER	\$	161.03
31	1	BONNET SEAL OUTER	\$	92.36
32	1	BONNET SEAL INNER	\$	157.28
33	1	BONNET LOCK	\$	305.48
34	1	BONNET CABLE	\$	119.19
35	1	FENDER PANEL FRT LH	\$	783.83
36	1	WHEELARCH FRT LH	\$	278.84
37	1	FENDER BRACKET LOWER LH	\$	15.79
38	1	FENDER INSULATOR LH	\$	130.84
39	1	FENDER PANEL FRT RH	\$	783.83
40	1	WHEELARCH FRT RH	\$	278.84
41	1	FENDER BRACKET LOWER RH	\$	15.79
42	1	FENDER INSULATOR RH	\$	130.84
43	1	WIPER RESERVOIR	\$	348.25
44	1	WIPER RESERVOIR NECK	\$	136.11
45	1	WIPER RESERVOIR MOTOR	\$	270.06
46	1	AIR CLEANER BOX	\$	464.20
47	1	AIR CLEANER HOSE	\$	175.85
48	1	AIR CLEANER LOWER	\$	271.26

TOTAL	\$	19,466.36
10%	\$	1,946.64
	\$	17,519.72

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na 52.00	2
2	1SET	BUMPER CLIP FRT	\$	na 66.00	✓
3	1SET	BUMPER BRACKET CLIP FRT LH	\$	na 12.00	}
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na 10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	na 12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na 10.50	
7	1	TOW COVER FRT	\$	na 14.50	
8	1	RADIATOR GRILLE SCREW	\$	na 16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na 69.00	}
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00	
11	1SET	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00	
13	1	Windscreen moulding	\$	na 120.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-101**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5492U

14	1	FRONT WINDSCREEN SEALANT	\$	<i>na</i>	253.80	X
15	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	X
16	1	Front licence plate with holder	\$	<i>By By</i>	80.00	<i>85500</i>
17	1SET	WHEELARCH CLIP FRT LH	\$	<i>na</i>	30.50	X
18	1SET	WHEELARCH CLIP FRT RH	\$	<i>na</i>	30.50	
19	6	BONNET INSULATOR CLIP L70Y	\$	<i>na</i>	7.30	
20	2	BONNET STRUT L70Y	\$	<i>IL</i>	88.61	
21	2	BONNET CABLE CLIP L70Y	\$	<i>na</i>	6.31	
22	2	BONNET CABLE COVER SCREW L70Y	\$	<i>na</i>	10.85	
TOTAL			\$		1,110.38	

TOTAL PARTS	\$	18,630.10
--------------------	-----------	------------------

Labour

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		<i>5000</i> 4,500.00	
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i>	380.00	X
To rust-proofing of the affected areas.	\$	<i>na</i>	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-101**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5492U

To Transfer Of Front Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	15/
Putty and spray painting of the affected portion.	\$		4,500.00	220/
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of front windscreen fittings and conduct water seepage test	\$	na	200.00	X
TOTAL	\$		12,000.00	
Over All Total	\$		30,630.10	

(LUMP SUM) Repair Days**15 DAYS**
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: