

ASS. REC. BY:

REF: CS/FCI19012281/Kgd3

n2

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

CWS

From (Person): Eileen Lee

of FCI

Date/Time: 5:25pm 10/7/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 9864E

Insured:

SH 8558M

at Workshop m/s

Wei Lee Motor

Tel:

6456 9830

of

Blk 9 Sin Ming Ind. Est #0132

Policy No:

Claim No:

D19004510MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 8/7/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9:34am 11/7/19

Person Contacted:

Karen

Vehicle IN / OUT

Date/Time

Action/Instruction Estimated (✓)

GBB 9864E X

SH8558M NS/INC12010209/H19n

12/7/19 @ 10.15am revised to Eileen Lee by email.

12/8/19 @ 11.56am checked with Karen, the vehicle will arrange in for repair by next week.

Kenneth confirmed 1/27/19, 4 days (red \$780.00, 42%)

FCI

ASSIGNMENT

From

Date

11/7/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GBB 9864E

at Workshop n/s

Wei Lee Motor

of Bldg 9 Sin Ming Ind. Est #01-32

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

1:30pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8511c

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

12/20

(DS)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBB 9864E

Regn:

12, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200

C.C.

1461

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

270909

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1YBAM20U0003275

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

7

mm

L/Bal.

mm

L/Bal.

7

mm

D.O.A.

8/7/19

D.O.I.

11/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 AUG 2019

MV : \$51K - LTA : 4068 - Net : 46932

Date/Time, File Pass to?



Preli. Report

12/20/19



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Mastering (\$

Survey Fee:

140

Transportation:

50

S + PS, \$

50

Fines:

15

Other:

Total

255

Report Form(s):

7P

Temp. Summ. Fee:

2950



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004510MFSH

Date: 12 July 2019

Our Ref: CS/FCI19012281/Kqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBB 9864E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/07/2019 at the premises of M/s WEI LEE MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,130.09</u> .
Revised Estimate Amount	: S\$ <u>3,821.36</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	09-07-2019	Our Ref No. D19004510MFSH
Accident Date	08-07-2019	Claim Type. Third Party
Insured Vehicle	SH8558M	Third Party Vehicle. GBB9864E
Survey Location	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32	
Contact Person.	KAREN SEAH	
Contact No.	64569830/ 0	Fax No. 64580128
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEI LEE MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 12 July 2019 10:15 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004510MFSH/1
Attachments: CSFCI19012281Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of GBB 9864E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 11 July 2019 9:39 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004510MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 10 July 2019 5:25 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004510MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	047D
Vehicle Details	
Vehicle No.:	GBB9864E
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Aug 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	K9KF276D098113
Chassis No.:	JN1YBAM20U0003275
Maximum Power Output:	-
Open Market Value:	\$22,941.00
Original Registration Date:	22 Dec 2010
First Registration Date:	22 Dec 2010
Transfer Count:	2
Actual ARF Paid:	\$1,148.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,511.00
COE Rebate Amount:	\$4,068.00
Total Rebate Amount:	\$4,068.00

The information contained herein is correct as at 21 Aug 2019

OK

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

10, July 2019

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
S 068877

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SH8558M
Accident involving vehicle no: GBB9864E/SH8558M
DOA: 08/07/2019 AT Tampines Ave 9 twds Ave 7

Dear officer incharge
Re: Estimate cost of repair for vehicle no: GBB9864E
To supply--

Description	Qty	Amount
Rear door, Lh	1 <i>1281.10 R</i>	1,404.90 N ✓
Taillamp, Lh	1	<i>pu</i> 236.50 N X
Rear door hinge @86.60	2	<i>u</i> 173.20 N X
Rear door, RH	1	<i>R</i> 960.90 N ✓
NV200 emblem	1	<i>u</i> 75.50 N ✓
Nissan logo	1	<i>u</i> 68.00 N ✓
Rear bumper	1 <i>Red Bm</i>	481.10 N ✓
Parts		3,400.10 N
Nett parts less 10%		340.01
		3,060.09

Reverse sensor
Company sticker
To remove damaged parts and attachments.
Repair/reshape damaged panel/dented areas.
Replace/align all parts into position.
To spray paint.

5km/5km 220.00 *200km*
250.00 *80km*

850.00 *4501*
750.00 *4001*

5,130.09

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

D19004510MPSH
Eileen lee *Not when*
11 Aug 87
Survey the paint
4 days
Direct settle

威利摩嘜 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

10, July 2019

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
S 068877

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SH8558M
Accident involving vehicle no: GBB9864E/SH8558M
DOA: 08/07/2019 AT Tampines Ave 9 twds Ave 7

Dear officer incharge

Re: Estimate cost of repair for vehicle no: GBB9864E

To supply--

Description	Qty	Amount
Rear door, Lh 1281.10	1	1,404.90 N ✓
Taillamp, Lh	1	236.50 N X
Rear door hinge @86.60	2	173.20 N X
Rear door, RH	1	960.90 N ✓
NV200 emblem	1	75.50 N ✓
Nissan logo	1	68.00 N ✓
Rear bumper	1	481.10 N ✓
Parts		3,400.10 N
Nett parts less 10%		340.01
		3,060.09

Reverse sensor
Company sticker
To remove damaged parts and attachments.
Repair/reshape damaged panel/dented areas.
Replace/align all parts into position.
To spray paint.

Shay/Sex 220.00 200.00
net 250.00 80.00

850.00 450.00
750.00 400.00

5,130.09

10% - 2490.10
10% - 299.04
10% - 2691.36
10% - 1130
10% - 3821.36
10% - 764.27
10% - 3057.09

3050
+ 400
= 3450

D19004510MFSH
Eileen Lee @ MFSH
Not when
U/Lm 82950h
Paying the claim
Today
Direct settle



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19012281/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8558M	Veh. Inspected	GBB 9864E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004510MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	10/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1YBAM20U0003275	Colour	WHITE	
Odometer	270909	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	BRIDGESTONE	8 mm	
L/H Front Tyre	175/70 R14	BRIDGESTONE	8 mm	
R/H Rear Tyre	175/70 R14	BRIDGESTONE	7 mm	
L/H Rear Tyre	175/70 R14	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/07/2019	Inspection Date	11/07/2019	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 9864E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR,LH (N)	BENT	1,404.90	1,281.10
1	TAILLAMP,LH (N)	SERVICEABLE	236.50	-
2	REAR DOOR HINGE @\$86.60 (N)	TO REPAIR SEE LABOUR	173.20	-
1	REAR DOOR,RH (N)	BENT	960.90	960.90
1	NV200 EMBLEM (N)	NECESSARY	75.50	75.50
1	NISSAN LOGO (N)	NECESSARY	68.00	68.00
1	REAR BUMPER (N)	DENTED / BUCKLED	481.10	481.10
	LESS 10% DISCOUNT		-340.01	-286.66
			3,060.09	2,579.94
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SHORTED / SCRATCHED	220.00	200.00
1	COMPANY STICKER (SN)	NECESSARY	250.00	80.00
			470.00	280.00
LABOUR				
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR/RESHAPE DAMAGED PANEL/DENTED AREAS.REPLACE/ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF REAR DOOR HINGE.		850.00	450.00
	TO SPRAY PAINT.		750.00	400.00
			1,600.00	850.00
GRAND TOTAL			5,130.09	3,709.94
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,950.00

Report Ref No. CS/FC119012281/Kqd3n2

MARKET VALUE: \$51,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$4,068.00=NETT VALUE: \$46,932.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.