

Cecilia



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

ONG KIM BENG
BLK 519A TAMPINES CENTRAL 8 #08-09
SINGAPORE 521519

Attention : Motor Claim Department
Contact : 82002838

Estimate : ES003490

Date : 10/07/2019
Vehicle Num. : SLS981B
Make/Model : MAZDA 3 SKYACTIV
Chassis/Eng# : JM6BN22A8H0167625
Accident Date : 09/07/2019
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		1,048.00
2.	1	REAR BUMPER <i>de</i>		18.50
		REAR BUMPER TOW COVER <i>ms</i>		
		List Total S\$:		1,066.50
		20.00% Discount S\$:		213.30
				853.20
		LABOUR :		
		TO REMOVE/REFIX REVERSE SENSOR & CHECK WIRING		20.00 60
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		400.00 200
		TO REPAIR INNER PANEL INCLUDES KNOCKING & REPLACEMENT OF PARTS		300.00 200
		Labour Total S\$:		780.00

SingDollars : One Thousand Six Hundred Thirty-Three & Cents Twenty Only

E. & O.E.

Total S\$: 1,633.20

for FALCON AIR AUTO SERVICES PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Acknowledged by Repairer

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines 99 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Rasul
Hp 90010068
2 days
P/P.
29/07/19 @ 1055
Resurvey before
paint

