

15/5/2010

INS. CASE OWNER:

Stacey

CC 4 ^{ASM} 1901

2292, K 96352

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

15/7/19

Date / Time:

11/7/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 5325U

Name of Insured:

TRANS-CAB SERVICES PTE LTD

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

9/7/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S9M02TmP(12688

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHC 5325U

SME 8613t

SMH 582R



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SME 8613t - NGA (MSG 1902116/4 210-9710)
SHC 5325U - t

17/7/19 - Email to. Reg. AVF from TP to B1.
OI reported as B27. TP reported as B28.
27/7/19 - TP AVF m. Upload in smartclaim.
(Pending finalized).
5/8/19 - REC LOR to TP (Pending LOR m).
15/8 - LOR m (TO seek mandate).
20/8 - Pending mandate approval. (approved)
20/8 - Offer of \$10,010.00 (pending acceptance)
20/8 - Settle @ \$10,010.00. DR send pending DR.
7/9 - DR m (file pass Admin to close).

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Kenneth

Repair Cost:

P/P

SS 8402.01

(6 days)

Reduction:

5054.36 %

60%

Email

Call

FINAL SETTLEMENT

Date/Time:

28/8/19/10.50am

Confirm with:

Jim Siew

Email

Cal

Final Liability:

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost:

(W/ GST)

SS 9095.42

Loss of Rental (LOR):

SS 963.00

(9 days)

x \$107

Loss of Use (LOU):

SS -

(S x days)

Loss of Income (LOI):

SS -

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 10012.42

Global Sum SS:

\$10,010.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

SS 10,010.00

Name 1:

MBM

Wheelpower Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350/-

Agent Name: Kenneth

Ref: ASM(CAXA)

ASSIGNMENT

From:

Date:

15/7/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SME 86132

at Workshop in/s:

MBM Wheelpower

of

160 Sin Ming Drive #06-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

896k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

1. B. / %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

(up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SME 86132

Yr Regn:

10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

1496

Colour:

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

010162

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GBF

1076020

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

9/7/19

D.O.I.

15/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

6 / 10

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P \$2463.01

(Red = \$12549.36/60%)

* 6 repair days + 1 Sunday + 3 PRS = 10 days.

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Material (\$)

Survey Fee:

Transportation:

3 + RS. \$

Notes

Other:

4/2/1

Report Formed:

Emp. Sign / F.R. /

Kp

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SHC 5325 U

OUR REF.: SME 8613 Z

TO: AXA

CC: MOTOR CLAIMS DEPARTMENT

FAX:

8 8463.01

FINALISED ESTIMATE FOR VEHICLE NO.: SME 8613 Z



DATE: 11/7/2019
FROM: CASSANDRA
FAX: 6452 5333
CONTACT: 8686 5188
MAKE & MODEL: HONDA FREED
CHASSIS NO.: GB71076020
ENGINE NO.: LEB5611343
YEAR MADE: 2018
ACCIDENT DATE: 9 July 2019

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	HEADLAMP BRACKET RH		1	\$ 103.80
2	HEADLAMP BRACKET LH		1	\$ 103.80
3	FRONT RADIATOR GRILLE ASSY 630.60		1	\$ 968.00
4	FRONT BUMPER 1050.70		1	\$ 1,390.00
5	FRONT BUMPER CLIP		10	\$ 80.00
6	FRONT BUMPER REINFORCEMENT 295.80		1	\$ 484.00
7	TAILGATE 1417.30		1	\$ 1,490.00
8	TAILGATE WEATHERSTRIP 165.91		1	\$ 251.60
9	TAILGATE HONDA "H" EMBLEM 51.00		1	\$ 109.00
10	TAILGATE MODEL "FREED" EMBLEM 65.00		1	\$ 126.00
11	TAILGATE "HYBRID" EMBLEM 50.40		1	\$ 150.00
12	REAR BUMPER 590.30		1	\$ 1,280.00
13	REAR BUMPER CLIP		1	\$ 80.00
14	END PANEL 623.70		1	\$ 858.44
SUPP.	FRONT BUMPER SUPPORT PANEL 752.60		1	\$ 910.80 ✓
SUPP.	CONDENSOR 985.10		1	\$ 1,066.80 ✓
SUPP.	REAR END PANEL TOP GARNISH 115.60		1	\$ 156.40 ✓
SUPP.	TAILGATE DOOR HANDLE 23.40		1	\$ 82.40 ✓
TOTAL: \$				9,691.04
LESS 20%: \$				(1,938.21)
PARTS TOTAL: \$				7,752.83

<u>SPECIAL NETT</u>			
BODY SEALANT	1	\$	80.00 30
FRONT NUMBER PLATE	1	\$	80.00 25
REVERSE SENSOR (1 SET)	1	\$	200.00
SUPP. WINDSCREEN SEALANT	1	\$	40.00

<u>LABOUR</u>			
TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS		\$	1,800.00 1000
TO CHECK & RECONNECT ALL NECESSARY WIRING		\$	40.00
TO APPLY ANTI RUST COATING		\$	60.00
TO CONDUCT CHASSIS ALIGNMENT		\$	80.00 X
TO SPRAY PAINT ON THE AFFECTED AREAS		\$	1,100.00
SUPP. TO REMOVE & INSTALL AIRCON COMPONENT, INCLUDING TOP UP GAS		\$	100.00
SUPP. TO REMOVE & REPAIR REAR WINDSCREEN		\$	120.00
TOTAL:		\$	11,232.83
7% GST:		\$	786.30
GRAND TOTAL:		\$	12,019.13


PART BY PART: \$ 11,232.83

BEFORE GST
08 REPAIR DAYS

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SHC 5325 U

OUR REF.: SME 8613 Z



TO: AXA

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.:

SME 8613 Z

DATE: 11/7/2019
FROM: CASSANDRA
FAX: 6452 5333
CONTACT: 8686 5188
MAKE & MODEL: HONDA FREED
CHASSIS NO.: GB71076020
ENGINE NO.: LEB5611343
YEAR MADE: 2018
ACCIDENT DATE: 9 July 2019

Not Authorised

Resurvey B4 paint

Kennerth

6-8 days

Kennerth.Kong@lkkauto.com

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BONNET		1	\$ 944.00 X
2	BONNET HINGE RH		1	\$ 134.72 X
3	BONNET HINGE LH		1	\$ 134.72 X
4	HEADLAMP RH		1	\$ 2,496.00 X
5	HEADLAMP LH		1	\$ 2,496.00 X
6	HEADLAMP BRACKET RH		1	\$ 103.80 X
7	HEADLAMP BRACKET LH		1	\$ 103.80 X
8	FRONT RADIATOR GRILLE ASSY	630-60	1	\$ 968.00
9	FRONT BUMPER	1050-70	1	\$ 1,390.00
10	FRONT BUMPER CLIP		10	\$ 80.00
11	FRONT BUMPER REINFORCEMENT	295-80	1	\$ 484.00
12	FRONT FENDER RH		1	\$ 658.00 X
13	FRONT FENDER LH		1	\$ 658.00 X
14	TAILGATE	1417-30	1	\$ 1,490.00
15	TAILGATE WEATHERSTRIP	165-91	1	\$ 251.60
16	TAILGATE RH		1	\$ 756.00 X
17	TAILGATE LH		1	\$ 756.00 X
18	TAILGATE LAMP RH		1	\$ 512.00 X
19	TAILGATE LAMP LH		1	\$ 512.00 X
20	TAILGATE HONDA "H" EMBLEM	51-00	1	\$ 109.00
21	TAILGATE HANDLE CHROME		1	\$ 454.48 X
22	TAILGATE MODEL "FREED" EMBLEM	65-00	1	\$ 126.00
23	TAILGATE HYBRID EMBLEM	50-40	1	\$ 150.00
24	REAR BUMPER	590-30	1	\$ 1,280.00
25	REAR BUMPER CLIP		1	\$ 80.00
26	END PANEL	623-70	1	\$ 858.44

TOTAL: \$ 17,986.56

LESS 20%: \$ (3,597.31)

PARTS TOTAL: \$ 14,389.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature:

SPECIAL NETT

BODY SEALANT
FRONT NUMBER PLATE
REAR NUMBER PLATE
REVERSE SENSOR (1 SET)

1	ALL	\$	80.00	3052
1	FOR 2552	\$	80.00	
1	FOR 52	\$	80.00	X
1	FOR 20052	\$	300.00	

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT,
WELD & STRAIGHTEN ON THE AFFECTED PARTS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO APPLY ANTI RUST COATING
TO CONDUCT CHASSIS ALIGNMENT
TO SPRAY PAINT ON THE AFFECTED AREAS

\$	?	1,800.00	1002
\$	402	120.00	
\$	602	250.00	
\$	22	80.00	X
\$	11002	1,800.00	

TOTAL:	\$	18,979.25
7% GST:	\$	1,328.55
GRAND TOTAL:	\$	20,307.80

#21012-37 *

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SHC 5325 U

OUR REF.: SME 8613 Z

mbm wheelpower

TO: AXA

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.:

SME 8613 Z

DATE: 11/7/2019

FROM: CASSANDRA

FAX: 6452 5333

CONTACT: 8686 5188

MAKE & MODEL: HONDA FREED

CHASSIS NO.: GB71076020

ENGINE NO.: LEB5611343

YEAR MADE: 2018

ACCIDENT DATE: 9 July 2019

Not Authorised

Resurvey By paint

Kenneth

6-8 days

Kenneth.Kong@lkkauto.com

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BONNET		1	\$ 944.00 X
2	BONNET HINGE RH		1	\$ 134.72 X
3	BONNET HINGE LH		1	\$ 134.72 X
4	HEADLAMP RH		1	\$ 2,496.00 ?
5	HEADLAMP LH		1	\$ 2,496.00 ?
6	HEADLAMP BRACKET RH		1	\$ 103.80 ?
7	HEADLAMP BRACKET LH		1	\$ 103.80 ?
8	FRONT RADIATOR GRILLE ASSY		1	\$ 968.00 CM
9	FRONT BUMPER		1	\$ 1,390.00 R
10	FRONT BUMPER CLIP		10	\$ 80.00 R
11	FRONT BUMPER REINFORCEMENT		1	\$ 484.00 ?
12	FRONT FENDER RH		1	\$ 658.00 X
13	FRONT FENDER LH		1	\$ 658.00 X
14	TAILGATE		1	\$ 1,490.00 R
15	TAILGATE WEATHERSTRIP		1	\$ 251.60 Dis/In
16	TAILGATE RH		1	\$ 756.00 S
17	TAILGATE LH		1	\$ 756.00 S
18	TAILGATE LAMP RH		1	\$ 512.00 S
19	TAILGATE LAMP LH		1	\$ 512.00 S
20	TAILGATE HONDA "H" EMBLEM		1	\$ 109.00 R
21	TAILGATE HANDLE CHROME		1	\$ 454.48 S
22	TAILGATE MODEL "FREED" EMBLEM		1	\$ 126.00 R
23	TAILGATE HYBRID EMBLEM		1	\$ 150.00 R
24	REAR BUMPER		1	\$ 1,280.00 R
25	REAR BUMPER CLIP		1	\$ 80.00 R
26	END PANEL		1	\$ 858.44 ?

TOTAL: \$ 17,986.56

LESS 20%: \$ (3,597.31)

PARTS TOTAL: \$ 14,389.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

BODY SEALANT	1	\$	80.00	7
FRONT NUMBER PLATE	1	\$	25.00	80.00
REAR NUMBER PLATE	1	\$	80.00	X
REVERSE SENSOR (1 SET)	1	\$	200.00	300.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	?	1,800.00	
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	40.00	120.00	
TO APPLY ANTI RUST COATING	\$	60.00	250.00	
TO CONDUCT CHASSIS ALIGNMENT	\$		80.00	7
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	1100.00	1,800.00	
TOTAL:	\$		18,979.25	
7% GST:	\$		1,328.55	
GRAND TOTAL:	\$		20,307.80	

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

t:6262 8888 f:6452 5333

COMPANY REG. NO.: 200204110W



Service Request Details

Claim

S9M01TMP

Reference

None 

Loss Date

July 9, 2019

Report Date

Jul 11, 2019 9:17:22 AM

Request Date

July 11, 2019

Due Date

July 18, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Cassandra

T: 10.30am

V: Out

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SME8613Z

Model

FREED HYBRID-1.5 G (A)

Service Address

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: cassandra.chua@mbmwheelpower.com.sg
Sent: Wednesday, 10 July, 2019 4:36 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: 'Danny Ong '
Subject: Liability Status - Accident involving SME 8613 Z & SHC 5325 U (AXA) DOA 09/07/2019
Attachments: GIA Report SME 8613 Z.PDF
Categories: Mateen

Dear All,

Refer to attached.

Kindly advise liability status for my client's vehicle, SME 8613 Z.

Thank you.

Best Regards,
Cassandra Chua | Claims Advisor



T 6262 8888 | F 6250 9015 | M 8686 5188
Email: cassandra.chua@mbmwheelpower.com.sg
MBM Wheelpower PTE. LTD.
160 Sin Ming Drive • #06-02
Sin Ming Autocity • Singapore 575722
www.mbmwheelpower.com.sg



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/08/2019

Survey Details:

Date of loss	9-Jul-19
Date of appointment	11-Jul-19
Date of survey	15-Jul-19
Location of survey	MBM WHEELPOWER PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SME 8613Z
Make and Model	HONDA FREED HYBRID 1.5G AUTO
Date of registration	19/10/2018
Excess	
Market Value	\$96,000
Parf Rebate	\$41,993
Nett Loss	\$54,007

Repair details:

Initial Estimate	\$ 18,979.25
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 6,043.01
Check items (estimate)	\$ -
Labour	\$ 2,420.00
Total	\$ 8,463.01
Lump Sum(if applicable)	\$ -
Number of days for repair	6



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

06 RECOMMENDED REPAIR DAYS + 1 SUNDAY + 3PRS = 10 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 9,055.45	W/GST
Loss of use	\$ -	
Loss of rental (W/GST)	\$ 1,070.00	10days x \$107
Loss of income	\$ -	
LTA search fees	\$ -	
Others	\$ -	
Proposed Total	\$ 10,125.42	



<MANDATE IA> - S9,01TMP {ACCIDENT INVOLVING
SHC 5325U (OI) / SME 8613Z (TP) / OTHERS ON
09/07/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S28(OI LAST VEH): INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$10125.42 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED INTO SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION.
THANKS - CECILIA

Reply



**Re:<MANDATE IA> - S9,01TMP {ACCIDENT INVOLVING
SHC 5325U (OI) / SME 8613Z (TP) / OTHERS ON
09/07/2019}**

Type

🔍 Question

Message

Please proceed

Reply



mbm wheelpower
DARE TO BE

Your ref : SHC5325U
Our ref : SME8613Z

13rd August 2019

AXA Insurance (Singapore) Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

TEL: 6338 7288

Attn: Motor Claims Dept

WITHOUT PREJUDICE

Dear Sir / Mdm,

Accident involving SME8613Z and SHC5325U along ECP (MCE) on 09/07/2019 at 08:15hrs

We refer to the above said accident.

Our investigation reveals that you are the insurers of the vehicle SHC5325U at the material time of the accident and that the said accident was caused solely by the negligence of the driver insured by your company. We hereby propose a direct settlement for our client's claim.

We enclosed herewith copy of

- 1 Final repair invoice
- 2 Authorisation Letter
- 3 Car rental invoice

We are instructed to claim the following

1 Costs of Repair - Part by part - (\$8,463.01 + 7% gst)	\$ 9,055.42
2 Loss of rental (\$128.40 x 10 days)	\$ 1,284.00

Grand Total: \$ 10,339.42

Please kindly let us know whether you are prepared to settle our client's claim.

Thanks & Warmest Regards,



Yin Siew
HP: 8588 3198
yinsiew.kon@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd
160 Sin Ming Drive #06-02
Sin Ming Autocity Singapore 575722
Customer Service Hotline 6262 8888
www.mbmwheelpower.com.sg
Company Registration Number: 200204110W
GST Registration Number: M90368446L



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19012292/Kgb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: STACEY NG

Date : 10-09-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5325U	Veh. Inspected	SME 8613Z
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01TMP	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	11/07/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA FREED (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GB71076020	Colour	METALLIC GREY
Odometer	010162	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	YOKOHAMA	9 mm
L/H Front Tyre	185/65 R15	YOKOHAMA	9 mm
R/H Rear Tyre	185/65 R15	YOKOHAMA	9 mm
L/H Rear Tyre	185/65 R15	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/07/2019	Inspection Date	15/07/2019
Survey held at	160 SIN MING DRIVE #06-02		
Repairer	MBM WHEELPOWER PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 8613Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	944.00	-
1	BONNET HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	134.72	-
1	BONNET HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	134.72	-
1	HEADLAMP RH (CONSISTENT)	SERVICEABLE	2,496.00	-
1	HEADLAMP LH (CONSISTENT)	SERVICEABLE	2,496.00	-
1	HEADLAMP BRACKET RH (CONSISTENT)	CRACKED	103.80	103.80
1	HEADLAMP BRACKET LH (CONSISTENT)	CRACKED	103.80	103.80
1	FRONT RADIATOR GRILLE ASSY (CONSISTENT)	CRACKED	968.00	630.60
1	FRONT BUMPER (CONSISTENT)	BENT	1,390.00	1,050.70
10	FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	80.00	80.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	484.00	295.80
1	FRONT FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	658.00	-
1	FRONT FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	658.00	-
1	TAILGATE (CONSISTENT)	BENT	1,490.00	1,417.30
1	TAILGATE WEATHERSTRIP (CONSISTENT)	DISTORTED / CUT	251.60	165.91
1	TAILLAMP RH (CONSISTENT)	SERVICEABLE	756.00	-
1	TAILLAMP LH (CONSISTENT)	SERVICEABLE	756.00	-
1	TAILGATE LAMP RH (CONSISTENT)	SERVICEABLE	512.00	-
1	TAILGATE LAMP LH (CONSISTENT)	SERVICEABLE	512.00	-
1	TAILGATE HONDA "H" EMBLEM (CONSISTENT)	NECESSARY	109.00	51.00
1	TAILGATE HANDLE CHROME (CONSISTENT)	SERVICEABLE	454.48	-
1	TAILGATE MODEL "FREED" EMBLEM (CONSISTENT)	NECESSARY	126.00	65.00
1	TAILGATE HYBRID EMBLEM (CONSISTENT)	NECESSARY	150.00	50.40
1	REAR BUMPER (CONSISTENT)	BENT	1,280.00	590.30
1	REAR BUMPER CLIP (CONSISTENT)	NECESSARY	80.00	80.00
1	END PANEL (CONSISTENT)	BENT	858.44	623.70
1	FRONT BUMPER SUPPORT PANEL (CONSISTENT) (ADDITIONAL)	BENT	910.80	752.60

Report Ref No. CC4/ASM19012292/Kgb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CONDENSER (CONSISTENT) (ADDITIONAL)	BENT / PUNCTURE	1,066.80	985.10
1	REAR END PANEL TOP GARNISH (CONSISTENT) (ADDITIONAL)	DENTED	156.40	115.60
1	TAILGATE DOOR HANDLE (CONSISTENT) (ADDITIONAL)	DENTED	82.40	23.40
	LESS 20% DISCOUNT		-4,040.59	-1,437.00
			16,162.37	5,748.01
	<u>SPECIAL NETT ITEMS</u>			
1	BODY SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	30.00
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	SCRATCHED	80.00	25.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	SERVICEABLE	80.00	-
1	SET REVERSE SENSOR (SN) (CONSISTENT)	DENTED	300.00	200.00
1	WINDSCREEN SEALANT (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	40.00	40.00
			580.00	295.00
	<u>LABOUR</u>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF BONNET, BONNET HINGE RH, BONNET HINGE LH, FRONT FENDER RH AND FRONT FENDER LH.		1,800.00	1,000.00
	TO CHECK & RECONNECT ALL NEECESSARY WIRING.		120.00	40.00
	TO APPLY ANTI RUST COATING.		250.00	60.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	80.00	-
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,800.00	1,100.00
	TO REMOVE & INSTALL AIRCON COMPONENT, INCLUDING TOP UP GAS. (ADDITIONAL)		100.00	100.00
	TO REMOVE & REFIT REAR WINDSCREEN. (ADDITIONAL)		120.00	120.00
			4,270.00	2,420.00
	GRAND TOTAL		21,012.37	8,463.01
	RECOMMENDED COST OF REPAIRS			8,463.01

Report Ref No. CC4/ASM19012292/Kgb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.