

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9453B**AAD1907-097***Not Authored
Resurvey By paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

10 JUL 2019

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9453B

JTDKB3FU603080787

RENAULT

LATITUDE

8.7.19

AXA

31/5/2019

		PART		LIST	
1	1	FRONT BUMPER	\$	<i>Tn</i> 509.10	✓
2	1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>n</i> 101.20	X
3	1	REINFORCEMENT, FRONT BUMPER	\$	<i>Bz</i> 708.10	✓
4	1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	<i>n</i> 242.80	X
5	1	COVER, FRONT BUMPER HOLE, RH	\$	<i>sn</i> 29.00	X
6	1	ABSORBER, FRONT BUMPER, LOWER	\$	<i>cm</i> 130.20	✓
7	1	ABSORBER, FRONT BUMPER ENERGY	\$	<i>cm</i> 78.10	✓
8	1	FRONT BUMPER SIDE RETAINER RH	\$	<i>mir</i> 112.70	✓
9	1	FRONT BUMPER SUPPORT	\$	<i>sn</i> 81.70	X
10	1	COVER SUB-ASSY, ENGINE, NO.1	\$	<i>sn</i> 466.00	X
11	1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	<i>sn</i> 238.70	X
12	1	EXTENSION, FRONT BUMPER, RH	\$	<i>n</i> 118.50	X
13	1	EXTENSION, FRONT BUMPER, LH	\$	<i>n</i> 118.50	X
14	1	FRONT LED LAMP (LOWER) RH	\$	<i>mir</i> 907.75	✓
15	1	FRONT HEADLAMP RH	\$	<i>Bro</i> 2,909.04	✓
16	1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	492.30	?
17	1	MOTOR, HEADLAMP LEVELING, RH	\$	413.10	?
18	1	FRONT FENDER RH	\$	<i>Bz</i> 963.80	✓
19	1	EXTENSION, FRONT FENDER, RH	\$	<i>mir</i> 48.80	✓
20	1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	<i>max</i> 98.30	?
21	1	LINER, FRONT FENDER, RH	\$	<i>Tn</i> 200.70	✓
22	1	FRONT FENDER EMBLEM RH	\$	<i>Re</i> 86.50	✓
23	1	SEAL, FENDER APRON MUDGUARD, RH	\$	<i>sn</i> 50.90	X
24	1	PROTECTOR, FRONT FENDER SIDE PANEL, RH	\$	<i>n</i> 92.30	X
25	1	GRILLE SUB-ASSY, RADIATOR	\$	<i>sn</i> 341.60	X
26	1	GRILLE, RADIATOR, LOWER NO.1	\$	<i>sn</i> 167.90	X
27	1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	<i>sn</i> 241.60	X
28	1	FRONT BONNET	\$	<i>n</i> 969.00	X
29	1	HINGE ASSY, HOOD, LH	\$	<i>n</i> 58.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9453B

30	1	HINGE ASSY, HOOD, RH	\$	<i>11</i>	58.00	X
31	1	SHAFT ASSY, FRONT DRIVE, RH	\$	<i>11</i>	1,186.20	X
32	1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$		637.50	?
33	1	KNUCKLE, STEERING, RH	\$		562.30	?
34	1	LINK ASSY, FRONT STABILIZER, RH	\$		199.00	?
35	1	BAR, STABILIZER, FRONT	\$	<i>12</i>	360.30	X
36	1	FRONT LOWER ARM	\$		631.90	?
37	1	FRONT SHOCK ABSORBER	\$		401.80	?
38	1	SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$		200.60	?
39	1	GEAR ASSY, STEERING	\$		1,666.30	?
40	1	COCK ASSY, RESERVE TANK	\$	<i>12</i>	117.80	X
41	1	PANEL, FRONT DOOR, OUTER RH	\$	<i>12</i>	361.00	X
42	1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	<i>12</i>	1,264.00	✓
43	1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	<i>12</i>	316.90	X
44	1	CHECK ASSY, FRONT DOOR	\$	<i>11</i>	156.60	X
45	1	WEATHERSTRIP, FRONT DOOR FIX WINDOW, RH	\$	<i>12</i>	75.50	X
46	1	RUN, FRONT DOOR GLASS, RH	\$		151.20	?
47	1	WEATHERSTRIP, FRONT DOOR, RH	\$	<i>12</i>	228.10	X
48	1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	<i>11</i>	592.70	X
49	1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$		383.40	?
50	1	FRONT DOOR OUTER MOULDING RH	\$	<i>12</i>	188.60	X
51	1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$	<i>12</i>	38.10	X
52	1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	<i>11</i>	94.10	X
53	1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	<i>11</i>	83.40	X
54	1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$		791.50	?
55	1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$		235.10	?
56	1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	<i>12</i>	583.30	X
57	1	REINFORCE SUB-ASSY, ROCKER, OUTER RH	\$	<i>11</i>	572.10	X
58	1	REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH	\$	<i>11</i>	336.60	X
59	1	RIGHT SIDE VIEW MIRROR	\$	<i>12</i>	1,275.52	X
60	1	WIRE, FRONT DOOR, RH	\$	<i>12</i>	454.10	X
61	1	JAR ASSY, WINDSHIELD WASHER	\$	<i>12</i>	186.90	✓
62	1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$		249.40	?
TOTAL			\$		25,616.01	
25%			\$		6,404.00	
			\$		19,212.01	

Trans-cab Auto Services Pte Ltd**AAD1907-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9453B**Special Nett**

1	1	FRONT WHEEL RIM	\$	<i>na</i>	1,570.55	<i>✓</i>
2	1	FRONT WHEEL RIM COVER	\$	<i>na</i>	175.80	<i>X</i>
3	1	CLIP, FRONT FENDER LINER	\$	<i>na</i>	22.00	<i>✓</i>
4	1	FRONT DOOR STICKER 'TRANS-CAB'	\$	<i>na</i>	80.00	<i>60na</i>
5	1	FRONT NUMBER PLATE WITH MOULDING	\$	<i>na</i>	200.00	<i>X</i>
6	1	BUMPER CLIP FRT	\$	<i>na</i>	66.00	<i>✓</i>
7	1	WINDSCREEN SEALANT	\$	<i>na</i>	253.80	<i>X</i>
8	1	FRONT WINDSCREEN MOULDING	\$	<i>na</i>	120.00	<i>X</i>
9	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	<i>X</i>

TOTAL \$ 2,588.15**TOTAL PARTS \$ 21,800.16****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>1100</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>600</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>60</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>20</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1907-097**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9453B

To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	60/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	?
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	60/
Towing Fees	\$	150.00	50/
To transfer of front windscreen fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	nn 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn 380.00	X
TOTAL	\$	16,110.00	
Over All Total	\$	37,910.16	

(PART-BY-PART) Repair Days**20 days**

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: