

ASS. REC. BY:

REF:

CS/INC/9012300/UT4302

Special Instruction:

Surveyor: MariusASSIGNMENT (Office)From (Person): Theresa Vimula of INC Date/Time: 10/7/19 @ 10:10am

Estimated Cost: _____ Bill to: _____

OD TP WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SDJ 5667T Insured: SJM 2942Gat Workshop m/s Kah Motor Tel: _____of 15 Ubi Road 4Policy No: _____ Claim No: MT/1052671-001

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/7/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10:30am @ 10/7/19 Person Contacted: Puben Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Inspected</u> ✓
	<u>SDJ 5667T - X</u>
	<u>SJM 2942G - X</u>

08/11/13 wef

REF:

ASS. REC. BY: *marcus*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA61522

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDJ 56677 Yr Regn: 7/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda Odyssey c.c 2356

Colour:

Purple

A/G: Insured / Std / NI / NA

Sp. Reading:

45111

T/Radio: Insured / Std / NI / NA

Eng/No:

JHMRC1890FC202436

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

7/7/19

D.O.I.

10/7/19 1052am

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/8/19 Car had fire by a 5984.55 with Rieber.
(Red: 1355.98, 18%)

RECEIVED 26 AUG 2019

26/8/2019

Date/Time, File Pass to?

☐

Preli. Report

1) 268 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

290

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

) TOTAL

Report Format :

TP

Lump Sum / I.B.I: (\$ 5984.55)

290

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Thursday, 11 July 2019 10:11 AM
To: Admin-D (LKKAuto); assignments; SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/7/2019

Hi Nivitha

Attached is the case nbr , OIC, DOA. details

Thank you

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 10 July 2019 10:43 AM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Clarence Richard Anthony <clarence.anthony@income.com.sg>; Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/7/2019

Dear Theresa,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]

Sent: Wednesday, 10 July 2019 10:10 AM

To: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Clarence Richard Anthony <clarence.anthony@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 10/7/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Chryllis quah	MT/1052408-002	10/7/2019	SMH5896C	KAN FOOK SING MOTOR WORKSHOP	61 DEFU LANE 12 DEFU INDUSTRIAL PARK E SINGAPORE 539147	Tan / 67479560		CB6801U	9/7	
2	SERENE TAN	MT/1052595-001	10/7/2019	FBM7833A	BAN HOCK HIN COMPANY PRIVATE LIMITED	6 DEFU LANE 4 SINGAPORE 539410	Raymond / 62816520		SGX6347B	2/7	

3	Eng huey huey	MT/1052417- 002	10/7/2019	SMD6491B	KAH MOTOR CO SDN BHD	15 UBI ROAD 4 SINGAPORE 408610	Yu Po Soon / 6846 5672		SJC1910H	6/7	
4	HELENA TAN	MT/1052671- 001	10/7/2019	SDJ5667T	KAH MOTOR CO SDN BHD	15 UBI ROAD 4 SINGAPORE 408610	Jeshuruben Rao Thomas (Rueben) / 90721766	10:00- 12:00	SJM2942G	7/7	
5	JEFF LIN	MT/1052004- 002	10/7/2019	SLJ4436E	RICO 60 AUTO SERVICES PTE LTD	8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875	Jin Hai / 6286 6060		GBE410A	4/7	
6	THIO TSE KIAT	MT/1052260- 002	10/7/2019	SLX3225E	RICO 60 AUTO SERVICES PTE LTD	8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875	Shanelle Lim / 9187 8064		FBG4266M	8/7	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different




At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 08:58
Date Of Accident	07/07/2019 19:00
Exact Location Of Accident	SLIP ROAD OF CTE TO BRADDELL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDJ5667T
Insured/Policyholder	
Name Of Registered Owner	CHAN EE PIN EDWIN
NRIC No	S7041754E
Email Address	EDCHAN@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-97671477
Alternative Phone No	OFFICE-97671477
Vehicle Particulars	
Manufacturer	HONDA
Model	ODYSSEY-2.4 EXV-S (A)
Exact Purpose for which vehicle was being used at time of accident	FAMILY OUTING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V05159/VPC2/R00
Cover Note Number	
Driver	
Name of Driver	CHAN JIE SHENG JENSEN
NRIC No	S9839304H
Date Of Birth	29/11/1998
Occupation	INDOOR
Date Of Driving Pass	04/12/2018
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91190613
Fax Number	
Contact Number	OFFICE-91190613
Email Address	CHANJSJ@GMAIL.COM

Address	APT BLK 22 TELOK BLANGAH CRESCENT #10-59
Postcode	090022
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : CHAN EE PIN EDWIN GENDER: : MALE
Passenger 2	NAME: : JOASH CHAN GENDER: : MALE
Passenger 3	NAME: : ADELENE YAP GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM2942G
Vehicle Make/Model/Colour	HYUNDAI/BLUE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	FOO JIN WEI JUSTIN
NRIC/Passport Number	S8531350I

Contact Number	88205954
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

Vehicle Number: S0J S67T

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

8 Jul 19
0811



Driver's Signature

(If driver is not the policyholder)

Date & Time: 08 July 2019
08:19



Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

Vehicle Number: SDJ 5667T

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07 July 2019 at 1853 hrs, I was driving car SDJ 5667T and stopped at the CTE sliproad at the junction with Bratdell Road (Larne Road). After edging forward and then braking to a complete stop to give way to a car on the major road, the car from behind crashed into my vehicle from behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

8 Jul 19
08:12

Driver's Signature

(If driver is not the policyholder)

Date & Time: 08 July 2019
08:12

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	1754E

Vehicle Details

Vehicle No.:	SDJ5667T
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Purple
Manufacturing Year:	2015
Engine No.:	K24W71011144
Chassis No.:	JHMRC1890FC202436
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$26,576.00
Original Registration Date:	29 Jul 2015
First Registration Date:	29 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$29,207.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2025
PARF Rebate Amount:	\$21,905.00

Intended COE Rebate Details

COE Expiry Date:	28 Jul 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,501.00
COE Rebate Amount:	\$39,617.00
Total Rebate Amount:	\$61,522.00

The information contained herein is correct as at 10 Jul 2019

OK

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : NTUC INCOME INS CO-OPERATIVE LTD
1 MARITIME SQUARE
HARBOURFRONT CENTRE
SINGAPORE 099253

Registration No : SDJ5667T

Chassis No : JHMRC1890FC202436

Model : ODYSSEY 2.4 EXV-S 15YM

Owner's Name : CHAN EE PIN EDWIN

Ins Policy No. :

Date of Accident : 7/7/2019

Document No. : SQT19003001

Date : 8. Jul 2019

Customer No. : WZN008

Svc Advisor : RUEBEN THOMAS

Engine No : K24W71011144

Date | Time : 8. Jul 2019 5:32:54 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHAN EE PIN EDWIN						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 07/07/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: NTUC INCOME INS CO-OPERATIVE LTD						
	TP VEH: SJM2942G						
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE <i>rel</i>	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGRR.WINDSHIELD CORNER <i>rel</i>	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER <i>rel</i>	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD <i>rel</i>	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM <i>rel</i>	1	3.70	25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5 <i>rel</i>	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPVOT <i>rel</i>	1	4.80	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>rel</i>	1	60.00		60.00	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP <i>Body</i>	1	1070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE <i>svc</i>	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE <i>svc</i>	1	185.40	25	139.05	9.73	148.78
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN <i>svc</i>	1	175.50	25	131.62	9.21	140.83
04715-T6A-900ZZ	FACERR.BUMPER <i>rel</i>	1	568.30	25	426.22	29.84	456.06
91505-TM8-003	CLIP,BUMPER <i>rel</i>	7	2.30	25	12.07	0.84	12.91
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>11</i>	1	19.10	25	14.32	1.00	15.32
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>11</i>	1	19.10	25	14.32	1.00	15.32
33555-SLJ-013	REFLECTOR ASSYL.RR. <i>11</i>	1	45.40	25	34.05	2.38	36.43
33505-SLJ-013	REFLECTOR ASSYR.RR. <i>11</i>	1	45.40	25	34.05	2.38	36.43
74940-TR0-003	BUZZER ASSYSMART <i>11</i>	1	60.10	25	45.07	3.15	48.22

Printed on 8/7/2019 6:04:38 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : NTUC INCOME INS CO-OPERATIVE LTD
1 MARITIME SQUARE
HARBOURFRONT CENTRE
SINGAPORE 099253
Registration No : SDJ5667T
Chassis No : JHMRC1890FC202436
Model : ODYSSEY 2.4 EXV-S 15YM
Owner's Name : CHAN EE PIN EDWIN
Ins Policy No. :
Date of Accident : 7/7/2019

Document No. : SQT19003001
Date : 8. Jul 2019
Customer No. : WZN008
Svc Advisor : RUEBEN THOMAS
Engine No : K24W71011144
Date | Time : 8. Jul 2019 5:32:54 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
38387-SLE-003	ANTENNA ASSY,L.RR.	111	60.60	25	45.45	3.18	48.63
Sum Item					1930.53	135.11	2,065.64
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	111	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00		150.00	10.50	160.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	320.00		320.00	22.40	342.40
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	320.00		320.00	22.40	342.40
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00		320.00	22.40	342.40
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1800.00		1800.00	126.00	1926.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1500.00		1500.00	105.00	1605.00
Sum Labor					5410.00	378.70	5,788.70

Survey By

Date & Time

Excess

Status

Signature

Total Amount 7,340.53 513.81 7,854.34

Total (Inclusive of GST) 7,854.34

Printed on 8/7/2019 6:04:38 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKJ is to ensure you are notified the following:

- Repairs to be done after spray painting
- To ensure you are notified after survey
- Repairs to be done after confirmation
- To ensure you are notified after "prejudice" basis
- To ensure you are notified after "prejudice" basis
- To ensure you are notified after "prejudice" basis

is subject to approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

23/8/2019.

PAGE 1/2



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

ATTN: MARCUS.

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

WD: 5 DAYS.

Customer: CU0080171 / NTUC INCOME INS
Chassis No: JHMRC1890FC202436
License No: SDJ5667T
Mileage: 46163
Engine No: K24W71011144

Document No: SVO19051464
Printed By: JESHURUEBEN
Order Date: 13. August 2019
Order Time: 8:22:14 AM
Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO: 73220)						
	OWNER: CHAN EE PIN EDWIN						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 07/07/2019						
	SURVEYED BY: MARCUS (LKK)						
	DATE: 10/07/2019						
	REF NO: MT/1052671-001						
	TP INSURER: NTUC INCOME INS CO-OPERATIVE LTD						
	TP VEH: SJM2942G						
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGRR.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.70	25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,070.80	25	803.10	56.22	859.32
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84	456.06
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
	SUM PARTS:				1,384.55	96.92	1,481.47
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	0760	1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BA02R	1863	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BG02D	1863	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN.						
	(N)						
BMI03D	1863	1	250.00		250.00	17.50	267.50
	REMOVE & INSTALL REAR						
	COMPARTMENT LININGS						
	GARNISHES.(N)						
BC012R	0760	1	300.00		300.00	21.00	321.00
	RESET VEHICLE SMART ENTRY						
	SYSTEM						
BC011R	0760	1	300.00		300.00	21.00	321.00
	REMOVE INSTALL & CALIBRATE REAR						
	VIEW CAMERA						
BKTG02R	1863	1	450.00		450.00	31.50	481.50
	REMOVE & TRANSFER ITEMS TO NEW						
	TAILGATE. ADJUST &						
	ALIGN TAILGATE.(N)						
BKRP02S	1863	1	1,400.00		1,400.00	98.00	1,498.00
	STRAIGHTEN ALIGN RR PANEL &						
	RENEW DAMAGE PARTS.						
BP03R	1865	1	1,350.00		1,350.00	94.50	1,444.50



SERVICE PRE-INVOICE

PAGE 2/2.

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0080171 / NTUC INCOME INS
Chassis No: JHMRC1890FC202436
License No: SDJ5667T
Mileage: 46163
Engine No: K24W71011144

Document No: SVO19051464
Printed By: JESHURUEBEN
Order Date: 13. August 2019
Order Time: 8:22:14 AM
Service Advisor: RUEBEN THOMAS

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS.(3P)

SUM LABOUR:	4,600.00	322.00	4,922.00
TOTAL SGD	5,984.55	418.92	6,403.47

Total Payable (SGD) 6,403.47

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19012300/Utd3e2

73 BRAS BASAH ROAD

Date: 29-08-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 2942G	Veh. Inspected	SDJ 5667T
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1052671-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	10/07/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY (A)	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JHMRC1890FC202436	Colour	PURPLE
Odometer	45111 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	CONTINENTAL	7 mm
L/H Front Tyre	215/55 R17	CONTINENTAL	7 mm
R/H Rear Tyre	215/55 R17	CONTINENTAL	7 mm
L/H Rear Tyre	215/55 R17	CONTINENTAL	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/07/2019	Inspect Date / Time	10/07/2019 (10:52 AM)
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDJ 5667T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	MOLDINGRR.WINDSHIELD SIDE (SN)	NECESSARY	27.00	27.00
1	MOLDINGR.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.67	12.67
1	MOLDINGL.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.67	12.67
4	SPACERRR.W/SHIELD (SN)	NECESSARY	11.70	11.70
1	RUBBER AWINDSHIELD DAM (SN)	NECESSARY	2.77	2.77
2	DAMPERSTD 5X5 (SN)	NECESSARY	12.75	12.75
1	CAPPIVOT (SN)	NECESSARY	3.60	3.60
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	TAILGATE COMP (SN)	BADLY DENTED	803.10	803.10
1	WEATHERSTRIPTAILGATE (SN)	SERVICEABLE	88.05	-
1	LOCKTAILGATE (SN)	SERVICEABLE	139.05	-
1	MOLDING ASSYRR.LICENSE GARN (SN)	SERVICEABLE	131.62	-
1	FACERR.BUMPER (SN)	DEFORMED	426.22	426.22
7	CLIP, BUMPER (SN)	NECESSARY	12.07	12.07
1	SPACERL.RR.BUMPER SIDE (SN)	NOT NECESSARY	14.32	-
1	SPACERR.RR.BUMPER SIDE (SN)	NOT NECESSARY	14.32	-
1	REFLECTOR ASSYL.RR. (SN)	NOT NECESSARY	34.05	-
1	REFLECTOR ASSYR.RR. (SN)	NOT NECESSARY	34.05	-
1	BUZZER ASSYSMART (SN)	NOT NECESSARY	45.07	-
1	ANTENNA ASSY,L.RR. (SN)	NOT NECESSARY	45.45	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			1,980.53	1,404.55
LABOUR				
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		100.00	100.00
	BODY JOINT SEALANT.	NOT NECESSARY	100.00	-
	REMOVE & RENEW REVERSE SENSORS - 4PCS.		150.00	130.00
	REMOVE & INSTALL RR.WINDSCREEN.		300.00	300.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		320.00	250.00
	RESET VEHICLE SMART ENTRY SYSTEM.		320.00	300.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		320.00	300.00

Report Ref No. CS/INC19012300/Utd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST&		450.00	450.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.		1,800.00	1,400.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)		1,500.00	1,350.00
			5,360.00	4,580.00
GRAND TOTAL			7,340.53	5,984.55

RECOMMENDED COST OF REPAIRS (CONFIRMED)			5,984.55
---	--	--	----------

Report Ref No. CS/INC19012300/Utd3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.