

ASS. REC. BY:

REF:

C/INC19012301/UT302

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Theresa Vimela

of

INC

Date/Time: 10/7/19 @ 10:10am

Estimated Cost:

Bill to:

OD-TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 6491B

Insured:

SJC 19104

at Workshop m/s

Kah motor

Tel:

90721766

of

15 Ubi Road 4

Policy No:

Claim No:

MT/1052417-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/7/19

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 10:38am @ 11/7/19

Person Contacted:

Rueben

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Ismael

SMD 6491B-X

SJC 19104-X

(68/11/13) wef
ASS. REC. BY: *Marcus*

REF:

rac

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SMD 6491B*
at Workshop m/s *beh nra*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *60*
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: *2* Consistent?: Yes or No
Est. Repairs: *7* days Res.: Yes or No
Lum Sum: *131* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 35366

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SMD 6491B* Yr Regn: *8 118*
Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA*
Make: *Honda Jazz* c.c. *1318*
Colour: *Grey* A/C: Insured / Std / NI / NA
Sp. Reading: *5070* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *JHMGK380J X 226695*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *175/65 R15*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front *8* Rear *2*
R/Bal. _____ mm R/Bal. _____ mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. *6/7/19* D.O.I. *10/7/19 1040*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
2/8/19 *confirmed find by #810442 with MR Yee. (Red: 2446.91123%)*

RECEIVED 02 AUG 2019

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) *218 Typist*
Date/Time, File Return to?

2)

Days Of Repair: *7*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) ☐ S + RS ☐ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) *8104.42*

<i>790</i>
<i>290</i>

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Thursday, 11 July 2019 10:11 AM
To: Admin-D (LKKAuto); assignments; SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/7/2019

Hi Nivitha

Attached is the case nbr , OIC, DOA. details

Thank you

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 10 July 2019 10:43 AM
To: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Clarence Richard Anthony <clarence.anthony@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/7/2019

Dear Theresa,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Theresa Vimala D/O Balagangadharan [mailto:thrsvim.bala@income.com.sg]

Sent: Wednesday, 10 July 2019 10:10 AM

To: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Clarence Richard Anthony <clarence.anthony@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 10/7/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Chryllis quah	MT/1052408-002	10/7/2019	SMH5896C	KAN FOOK SING MOTOR WORKSHOP	61 DEFU LANE 12 DEFU INDUSTRIAL PARK E SINGAPORE 539147	Tan / 67479560		CB6801U	9/7	
2	SERENE TAN	MT/1052595-001	10/7/2019	FBM7833A	BAN HOCK COMPANY PRIVATE LIMITED	6 DEFU LANE 4 SINGAPORE 539410	Raymond / 62816520		SGX6347B	2/7	

3	Eng huey huey	MT/1052417- 002	10/7/2019	SMD6491B	KAH MOTOR CO SDN BHD	15 UBI ROAD 4 SINGAPORE 408610	Yu Po Soon / 6846 5672	SJC1910H	6/7	
4	HELENA TAN	MT/1052671- 001	10/7/2019	SDJ5667T	KAH MOTOR CO SDN BHD	15 UBI ROAD 4 SINGAPORE 408610	Jeshuruben Rao Thomas (Rueben) / 90721766	SJM2942G	7/7	
5	JEFF LIN	MT/1052004- 002	10/7/2019	SLJ4436E	RICO 60 AUTO SERVICES PTE LTD	8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875	Jin Hai / 6286 6060	GBE410A	4/7	
6	THIO TSE KIAT	MT/1052260- 002	10/7/2019	SLX3225E	RICO 60 AUTO SERVICES PTE LTD	8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875	Shanelle Lim / 9187 8064	FBG4266M	8/7	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different




in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	3090A

Vehicle Details

Vehicle No.:	SMD6491B
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	L13B11031044
Chassis No.:	JHMGK3850JX226695
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,625.00
Original Registration Date:	29 Aug 2018
First Registration Date:	29 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$5,625.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2028
PARF Rebate Amount:	\$4,218.00

Intended COE Rebate Details

COE Expiry Date:	28 Aug 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,110.00
COE Rebate Amount:	\$31,148.00
Total Rebate Amount:	\$35,366.00

The information contained herein is correct as at 10 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 17:32
Date Of Accident	06/07/2019 12:50
Exact Location Of Accident	CAUSEWAY TO JOHOR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD6491B
Insured/Policyholder	
Name Of Registered Owner	TAN HU JUN
NRIC No	S2513090A
Email Address	CTINTERIOR80@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81115444
Alternative Phone No	OTHERS-81115444

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.3 LX (GE6) (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MT105704-R00
Cover Note Number	

Driver

Name of Driver	TAN HU JUN
NRIC No	S2513090A
Date Of Birth	01/08/1964
Occupation	INDOOR
Date Of Driving Pass	26/04/1974
Driving Experience	45 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81115444
Fax Number	
Contact Number	OTHERS-81115444
Email Address	CTINTERIOR80@GMAIL.COM

Address	APT BLK 229 BISHAN STREET 23 #18-47 SINGAPORE
Postcode	570229
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MDM HELEN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SJC1910H
Vehicle Make/Model/Colour	TOYOTA / ALTIS/ BLUE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ABDUL MUHAJIB BIN SHAMSUDDIN
NRIC/Passport Number	S88103281
Contact Number	98761969
Address	APT BLK 226A COMPASALE WALK #02-307 SINGAPORE
Postcode	541226
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

Vehicle Number: SMD6491B

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 6/7/2019 around 1250HR, I was drive a long causeway link to Johor. At traffic Jam, I drive slowly follow the front vehicle, suddenly the vehicle SJC 1910H hit against my vehicle back portion. My vehicle was damage on back portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 8/7/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: You Po Soon

NRIC/FIN No.:

Vehicle Number: SMD6491BSKETCH PLANIMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 8/7/2019

Driver's Signature

(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: You Po Soon
NRIC/FIN No.:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : NTUC INCOME INS CO-OPERATIVE LTD
1 MARITIME SQUARE
HARBOURFRONT CENTRE
SINGAPORE 099253

Registration No : SMD6491B

Chassis No : JHMGK3850JX226695

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : TAN HU JUN

Ins Policy No. :

Date of Accident : 6/7/2019

Document No. : SQT19003010

Date : 9. Jul 2019

Customer No. : WZN008

Svc Advisor : YOU PO SOON

Engine No : L13B11031044

Date | Time : 9. Jul 2019 8:27:54 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TAN HU JUN						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 06/07/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: NTUC INCOME INS CO-OPERATIVE LTD						
	TP VEH: SJC1910H						
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
74801-T5S-K01	LOCK ASSY,TAILGATE	1	78.90	25	59.17	4.14	63.31
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74890-T5A-A11	GARNISH ASSY,RR LICENCE	1	105.50	25	79.12	5.54	84.66
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
33500-T5A-J02	TAILLIGHT ASSY,R.	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL.	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID	1	81.70	25	61.27	4.29	65.56
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71505-T5A-J50	GARNISH,RR.BUMPER	1	38.30	25	28.72	2.01	30.73

Printed on 9/7/2019 9:28:19 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : NTUC INCOME INS CO-OPERATIVE LTD
1 MARITIME SQUARE
HARBOURFRONT CENTRE
SINGAPORE 099253
Registration No : SMD6491B
Chassis No : JHMGK3850JX226695
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : TAN HU JUN
Ins Policy No. :
Date of Accident : 6/7/2019

Document No. : SQT19003010
Date : 9. Jul 2019
Customer No. : WZN008
Svc Advisor : YOU PO SOON
Engine No : L13B11031044
Date | Time : 9. Jul 2019 8:27:54 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91505-TM8-003	CLIP,BUMPER	1	2.30	25	12.07	0.84	12.91
71502-T5A-J60	COVER,R.RR.BUMPER	1	20.70	25	15.52	1.09	16.61
71507-T5A-J60	COVER,L.RR.BUMPER	1	20.70	25	15.52	1.09	16.61
66100-TAR-T00ZZ	PANEL COMPR.	1	320.40	25	240.30	16.82	257.12
63320-T5A-900ZZ	GUTTER COMP,R.RR.PILLAR	1	88.60	25	66.45	4.65	71.10
63720-T5A-900ZZ	GUTTER COMP,L.RR.PILLAR LOWER	1	88.60	25	66.45	4.65	71.10
84521-T5A-901ZA	LID ASSYSARE TIRE	1	189.80	25	142.35	9.96	152.31
84550-T5A-J30	BOX ASSY,CARGO FLOOR GATE	1	117.40	25	88.05	6.16	94.21
84601-TAR-Z03ZA	LINING ASSYR.TRUNK	1	169.00	25	126.75	8.87	135.62
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1	169.00	25	126.75	8.87	135.62
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	53.70	25	40.27	2.82	43.09
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.10	25	3.82	0.27	4.09
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					3051.33	213.59	3,264.92
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00		150.00	10.50	160.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	320.00		320.00	22.40	342.40
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50
BKRP21M	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN	1	2400.00		2400.00	168.00	2568.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	3300.00		3300.00	231.00	3531.00
Sum Labor					7500.00	525.00	8,025.00

Printed on 9/7/2019 9:25:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : NTUC INCOME INS CO-OPERATIVE LTD
1 MARITIME SQUARE
HARBOURFRONT CENTRE
SINGAPORE 099253

Registration No : SMD6491B

Chassis No : JHMGK3850JX226695

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : TAN HU JUN

Ins Policy No. :

Date of Accident : 6/7/2019

Document No. : SQT19003010

Date : 9. Jul 2019

Customer No. : WZN008

Svc Advisor : YOU PO SOON

Engine No : L13B11031044

Date | Time : 9. Jul 2019 8:27:54 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	<i>marcus nhor</i>						
Date & Time	<i>10/7/19 @ 11am</i>						
Excess	<i>✓</i>						
Status	<i>not at fault</i>						
Signature	<i>Tan Hu Jun</i>						

Total Amount 10,551.33 738.59 11,289.92

Total (Inclusive of GST) 11,289.92

Let's As to Consur's insurance notify the following of the following:

- Notify the insurance company of the accident
- Notify the insurance company of the damage
- Notify the insurance company of the loss
- Notify the insurance company of the claim
- Notify the insurance company of the settlement

Authorised by Repairer

Signature

Date

Printed on 9/7/2019 9:25:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**HONDA**1/8/2019
Attn: Marcus Chua

C

Page 1/2

SERVICE PRE-INVOICE**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD = 7 days

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZN008 / NTUC INCOME INS	Document No:	SVO19046046
Chassis No:	JHMGK3850JX226695	Printed By:	PSYOU
License No:	SMD6491B	Order Date:	18. July 2019
Mileage:	8332	Order Time:	10:23:42 AM
Engine No:	L13B11031044	Service Advisor:	YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 73072)						
	OWNER: TAN HU JUN						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 06/07/2019						
	SURVEYED BY: MARCUS CHUA						
	DATE: 10/07/2019						
	REF NO:						
	TP INSURER: NTUC INCOME INS CO-OPERATIVE LTD						
	TP VEH: SJC1910H						
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBER WINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPER STD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIP TAILGATE	1	92.30	25	69.22	4.85	74.07
75722-T5L-T01	EMBLEM RR.	1	10.90	25	8.17	0.57	8.74
33500-T5A-J02	TAILLIGHT ASSY, R.	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSY, L.	1	223.90	25	167.92	11.75	179.67
04715-T5A-J50ZZ	FACE, RR. BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-J50	SPACER, R. RR. BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER, L. RR. BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71505-T5A-J50	GARNISH, RR. BUMPER	1	38.30	25	28.72	2.01	30.73
91505-TM8-003	CLIP, BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPR.	1	320.40	25	240.30	16.82	257.12
84601-TAR-Z03ZA	LINING ASSY, TRUNK	1	169.00	25	126.75	8.87	135.62
84640-T5A-003ZA	LINING ASSY, RR. PANEL	1	60.80	25	45.60	3.19	48.79
84440-T5A-J02ZA	LINING ASSY, TAILGATE LOWER	1	53.70	25	40.27	2.82	43.09
NMRS-4P-TM3040L	4PCS ACT RR. SENSOR	1	320.00		320.00	22.40	342.40
	SUM PARTS:				2,254.42	157.81	2,412.23
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML01I	EXT-YJ	1	100.00		100.00	7.00	107.00
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS (N)						
BOBC	EXT-YBH	1	80.00		80.00	5.60	85.60
	BODY UNDERSIDE COATING (N)						
BOJSE	EXT-YJ	1	80.00		80.00	5.60	85.60
	BODY JOINT SEALANT.						
BP00R	EXT-YBH	1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BA02R	EXT-YJ	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BG02D	EXT-YJ	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN. (N)						
BC011R	0760	1	300.00		300.00	21.00	321.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZN008 / NTUC INCOME INS	Document No:	SVO19046046
Chassis No:	JHMGK3850JX226695	Printed By:	PSYOU
License No:	SMD6491B	Order Date:	18. July 2019
Mileage:	8332	Order Time:	10:23:42 AM
Engine No:	L13B11031044	Service Advisor:	YOU PO SOON

BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50
BKRP21M	EXT-YJ CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM	1	1,960.00	1,960.00	137.20	2,097.20
BP07R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(7P)	1	2,250.00	2,250.00	157.50	2,407.50
			SUM LABOUR:	5,850.00	409.50	6,259.50
			TOTAL SGD	8,104.42	567.31	8,671.73
Total Payable (SGD)						8,671.73

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19012301/Utf3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 05-08-2019



ATTN : ENG HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJC 1910H	Veh. Inspected	SMD 6491B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1052417-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	10/07/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ (A)	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMGK3850JX226695	Colour	GREY
Odometer	8070 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	YOKOHAMA	8 mm
L/H Front Tyre	175/65 R15	YOKOHAMA	8 mm
R/H Rear Tyre	175/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre	175/65 R15	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/07/2019	Inspect Date / Time	10/07/2019 (10:40 AM)
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 6491B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER CWINDSHIELD DAMPER (SN)	NECESSARY	8.55	8.55
2	RUBBERWINDSHIELD DAMPER (SN)	NECESSARY	9.75	9.75
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.37	6.37
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	TAIL GATE COMP (SN)	BADLY DENTED	547.95	547.95
1	LOCK ASSY, TAILGATE (SN)	NOT NECESSARY	59.17	-
1	WEATHERSTRIP TAILGATE (SN)	TORN	69.22	69.22
1	GARNISH ASSY, RR LICENCE (SN)	NOT NECESSARY	79.12	-
1	EMBLEMH (SN)	NOT NECESSARY	8.02	-
2	NUTPUSH 3MM (SN)	NOT NECESSARY	3.15	-
1	EMBLEMRR. (SN)	NECESSARY	8.17	8.17
1	TAILLIGHT ASSY,R. (SN)	CUT	167.92	167.92
1	TAILLIGHT ASSYL. (SN)	CUT	167.92	167.92
1	LIGHT ASSYR.LID (SN)	NOT NECESSARY	61.27	-
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	61.27	-
1	FACE, RR.BUMPER (SN)	DISTORTED	369.52	369.52
1	SPACER,R.RR.BUMPER SIDE (SN)	BENT	12.67	12.67
1	SPACER,L.RR.BUMPER SIDE (SN)	BENT	12.67	12.67
1	GARNISH, RR.BUMPER (SN)	TWISTED	28.72	28.72
7	CLIP, BUMPER (SN)	NECESSARY	12.07	12.07
1	COVER,R. RR.BUMPER (SN)	NOT NECESSARY	15.52	-
1	COVER,L.RR.BUMPER (SN)	NOT NECESSARY	15.52	-
1	PANEL COMPRR. (SN)	BADLY DENTED	240.30	240.30
1	GUTTER COMP,R.RR.PILLAR (SN)	NOT NECESSARY	66.45	-
1	GUTTER COMP,L.RR.PILLAR LOWER (SN)	NOT NECESSARY	66.45	-
1	LID ASSYSPARE TIRE (SN)	NOT NECESSARY	142.35	-
1	BOX ASSY, CARGO FLOOR GATE (SN)	NOT NECESSARY	88.05	-
1	LINING ASSYR.TRUNK (SN)	TWISTED	126.75	126.75
1	LINING ASSYL.TRUNK (SN)	REPEATED	126.75	-
1	LINING ASSYRR.PANEL (SN)	TWISTED	45.60	45.60
1	LINING ASSYTAILGATE LOWER (SN)	CUT	40.27	40.27

Report Ref No. CS/INC19012301/Utf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	POCKETTAILGATE LINING PULL (SN)	NOT NECESSARY	3.82	-
4	ACT RR.SENSOR (SN)	SHORTED	320.00	320.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			3,101.33	2,274.42
	LABOUR			
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		100.00	100.00
	BODY UNDERSIDE COATING.		100.00	80.00
	BODY JOINT SEALANT.		80.00	80.00
	APPLY BODY UNDERSIDE COATING.		250.00	180.00
	REMOVE & RENEW REVERSE SENSORS - 4 PCS.		150.00	130.00
	REMOVE & INSTALL RR.WINDSCREEN.		300.00	300.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		320.00	300.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.		450.00	450.00
	CUT OFF & RENEW RR PANEL . STRAIGHTEN RR FENDERS AN.		2,400.00	1,960.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (7P).		3,300.00	2,250.00
			7,450.00	5,830.00
GRAND TOTAL			10,551.33	8,104.42
RECOMMENDED COST OF REPAIRS (CONFIRMED)				8,104.42

Report Ref No. CS/INC19012301/Utf3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.