



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34394

- Rev. 1

NTUC Income Insurance Co-Operative Limited
75 BRAS BASAH ROAD
NTUC INCOME CENTRE
SINGAPORE 189557

DATE : 08/07/2019

CLAIM NO. : 11378

POLICY NO. :

MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBM7833A
MAKE/MODEL : BMW / G310R

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER	REPLACE	1.00	\$38.00	34.20
				Disc %: 10.00	
2	BAR HANDLE	REPLACE	1.00	\$245.00	220.50
				Disc %: 10.00	
3	BODY SCREW W/O SHOULDER	REPLACE	1.00	\$5.00	4.50
				Disc %: 10.00	
4	BOX REAR (KAPPA) K-VENTURE 42L P/N: 57761	REPLACE <i>ADD</i>	1.00	\$650.00 <i>cut/ps</i>	585.00
				Disc %: 10.00	
5	BRAKE CALIPER	REPLACE	1.00	\$805.00	724.50
				Disc %: 10.00	
6	BRAKE DISC REAR	REPLACE	1.00	\$406.00	365.40
				Disc %: 10.00	
7	DRIVER FOOTREST RH	REPLACE	1.00	\$84.00	75.60
				Disc %: 10.00	
8	ENGINE GUARD SET	REPLACE	1.00	\$595.00	535.50
				Disc %: 10.00	
9	FOIL RH	REPLACE	1.00	\$52.00	46.80
				Disc %: 10.00	
10	FOOTPEG PLATE RH	REPLACE	1.00	\$203.00	182.70
				Disc %: 10.00	
11	INSCRIPTION RADIATOR COWL RH	REPLACE	1.00	\$45.00	40.50
				Disc %: 10.00	
12	KIT REPAIR	REPLACE	1.00	\$40.00	36.00
				Disc %: 10.00	
13	LABEL NOTICE	REPLACE	1.00	\$34.00	30.60
				Disc %: 10.00	



bizSAFE₃



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 200214081
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$380.00	380.00
15	LEVER BRAKE P/N: 61597	REPLACE	1.00	\$77.00 Disc %: 10.00	69.30
16	MIRROR RH P/N: 61596	REPLACE	1.00	\$75.00 Disc %: 10.00	67.50
17	MOUNT SADDLE	REPLACE	1.00	\$130.00 Disc %: 10.00	117.00
18	MUFFLER SYSTEM	REPLACE	1.00	\$1,904.00 Disc %: 10.00	1,713.60
19	PAD TANK TRACTION GRIP (R&G) P/N: 63260	REPLACE	1.00	\$95.00 Disc %: 10.00	85.50
20	PEDAL BRAKE	REPLACE	1.00	\$112.00 Disc %: 10.00	100.80
21	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$10.00	10.00
22	PROTECTOR EXHAUST P/N: 61598	REPLACE	1.00	\$230.00 Disc %: 10.00	207.00
23	PROTECTOR FORK (R&G) P/N: 63261	REPLACE	1.00	\$135.00 Disc %: 10.00	121.50
24	RADIATOR COWL RH	REPLACE	1.00	\$69.00 Disc %: 10.00	62.10
25	SEALS PISTON	REPLACE	1.00	\$56.00 Disc %: 10.00	50.40
26	STOPPER	REPLACE	1.00	\$6.00 Disc %: 10.00	5.40
27	SWING ARM	REPLACE	1.00	\$895.00 Disc %: 10.00	805.50
28	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835	Cancelled	1.00	\$0.00	0.00

SUB TOTAL

\$6,677.40

GST @ 7 %

\$467.42

GRAND TOTAL

\$7,144.82

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0303
ISO 9001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

bizSAFE₃



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19012303/Ust3s2

73 BRAS BASAH ROAD

Date: 05-09-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: SERENE TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGX 6347B	Veh. Inspected	FBM 7833A
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1052595-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	10/07/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. G310R	c.c	313
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WB30G0106HR832688	Colour	BLACK
Odometer	18169 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/70 R17	MICHELIN	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/60 R17	MICHELIN	7 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/07/2019	Inspect Date / Time	10/07/2019 (06:08 PM)
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 7833A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BALANCER	SCRATCHED	38.00	38.00
1	BAR HANDLE	BENT	245.00	245.00
1	BODY SCREW W/O SHOULDER	NECESSARY	5.00	5.00
1	BOX REAR (KAPPA) K-VENTURE 42L	CUT / DENTED	742.00	650.00
1	BRAKE CALIPER	DAMAGED / CUT	805.00	805.00
1	BRAKE DISC REAR	BENT	406.00	406.00
1	COVER TANK RH	TO REPAIR SEE LABOUR	322.00	-
1	DRIVER FOOTREST RH	CUT	84.00	84.00
1	SET ENGINE GUARD	CUT	595.00	595.00
1	FOIL RH	DAMAGED	52.00	52.00
1	FOOTPEG PLATE RH	BENT	203.00	203.00
1	INSCRIPTION RADIATOR COWL RH	CUT	45.00	45.00
1	KIT REPAIR	NECESSARY	40.00	40.00
1	LABEL NOTICE	NECESSARY	34.00	34.00
1	LEVER BRAKE	SCRATCHED	77.00	77.00
1	MIRROR RH	CUT	75.00	75.00
1	MOUNT SADDLE	CUT	130.00	130.00
1	MUFFLER SYSTEM	DENTED / BENT	1,904.00	1,904.00
1	PAD TANK TRACTION GRIP (R&G)	NECESSARY	95.00	95.00
1	PEDAL BRAKE	CUT	112.00	112.00
1	PROTECTOR EXHAUST	SCRATCHED	230.00	230.00
1	PROTECTOR FORK (R&G)	CUT	135.00	135.00
1	RADIATOR COWL RH	CUT	69.00	69.00
1	SEALS PISTON	NECESSARY	56.00	56.00
1	STOPPER	NECESSARY	6.00	6.00
1	SWING ARM	DENTED / BENT	895.00	895.00
1	TYRE 150/60-17 (MICHELIN)	SERVICEABLE	252.00	-
	LESS 10% DISCOUNT		-	-698.60
			7,652.00	6,287.40

Report Ref No. CS/INC19012303/Usf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPECIAL NETT ITEMS	BENT		
	PLATE NUMBER REAR (6.5 INCH X 9 INCH) (SN)		16.00	10.00
			16.00	10.00
	LABOUR	NOT AVAILABLE		
	LABOUR - FOR DISMANTLE AND ASSEMBLING PF PARTS QUOTED. INCLUSIVE OF THE REPAIR OF COVER TANK RH.		480.00	380.00
	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A.		45.00	-
			525.00	380.00
GRAND TOTAL			8,193.00	6,677.40
RECOMMENDED COST OF REPAIRS (CONFIRMED)				6,677.40

Report Ref No. CS/INC19012303/Usf3s2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.