

AlGAsia Insured's Veh No : SJS7241G Date of Accident : 09 July 2019

1 Defu Lane 6 Singapore 539365 Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No.: M2-8922054-2

Mr Thng Eng Kwee

Date: 11 July 2019

## Estimate To Repair SJJ1253J - Toyota Vios 1.5E A

Chassis No: MR053HY9305078432

1 pc 1 pc 1 pc	LIST ITEMS bootlid Vios badge		
1 pc 1 pc		i	
1 pc	[	\$	48.0
•	bootlid Sports badge	\$	50.0
	bootlid centre logo	\$	55.0
1 pc	bootlid E badge	\$	45.0
1 pc	rear bumper	\$	455.0
2 ps	rear bumper side retainers @ \$100.00	\$	200.0
2 ps	rear bumper side holders @ \$35.00	\$	70.0
2 ps	rear bumper reflectors @ \$90.00	\$	180.0
8 ps	rear bumper fastener clips @ \$4.30	\$	34.4
2 ps	rear bumper splashield cover @ \$50.00	\$	100.0
1 pc	rear end panel	\$	605.0
1 pc	rear end panel inner trim	\$	80.70
13 3 ps	rear end panel inner trim clips @ \$4.50	\$	13.5
		\$	1,936.6
	Less 25 %	\$	484.1
		\$	1,452.4
	SPECIAL NETT ITEMS		
1 set	rear bumper parking sensor	\$	400.0
15   1 pc	rear bumper lower spoiler (after market accessory)	\$	800.0
		\$	1,200.0
		***************************************	
	***************************************		420 O
	~	1	120.00
			60.0
		Þ	150.0
	Panel beating, knocking and straighten the necessary portion,	\$	800.0
	Putty and spray painting of the affected portion.	\$	800.0
****		\$	1,930.0
		*	**
	2 ps 2 ps 3 ps 2 ps 1 pc 1 pc 3 ps	rear bumper side holders @ \$35.00 rear bumper reflectors @ \$90.00 rear bumper fastener clips @ \$4.30 rear bumper splashield cover @ \$50.00 rear end panel rear end panel inner trim rear end panel inner trim clips @ \$4.50  Less 25 %  SPECIAL NETT ITEMS rear bumper parking sensor rear bumper lower spoiler (after market accessory)  LABOUR & MISC. CHARGES To reinstall of rear bumper parking sensor. To check electrical lighting concerned. To remove and refit interior fittings, trimmings, garnish and other, to enable repair. Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	rear bumper side holders @ \$35.00  rear bumper reflectors @ \$90.00  rear bumper fastener clips @ \$4.30  rear bumper splashield cover @ \$50.00  rear end panel  rear end panel inner trim  rear end panel inner trim clips @ \$4.50  Less 25 %  SPECIAL NETT ITEMS  rear bumper parking sensor  rear bumper lower spoiler (after market accessory)  LABOUR & MISC. CHARGES  To reinstall of rear bumper parking sensor.  To check electrical lighting concerned.  To remove and refit interior fittings, trimmings, garnish and other, to enable repair.  Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.

## > Back to OneMotoring

## **Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2369H

Vehicle Details

Vehicle No.: SJJ1253J Vehicle to be Exported: No

Intended Deregistration Date: 11 Jul 2019

Vehicle Make: TOYOTA
Vehicle Model: VIOSE AUTO

Primary Colour: Black
Manufacturing Year: 2008

Engine No.: 1NZX794597

 Chassis No.:
 MR053HY9305078432

 Maximum Power Output:
 80.0 kW (107 bhp)

 Open Market Value:
 \$11,834.00

 Original Registration Date:
 02 Sep 2008

 First Registration Date:
 02 Sep 2008

Transfer Count: 0

Actual ARF Paid: \$11,834.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: PARF Rebate Amount: \$0.00

**Intended COE Rebate Details** 

COE Expiry Date: 01 Sep 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

 PQP Paid:
 \$16,170.00

 COE Rebate Amount:
 \$13,388.00

 Total Rebate Amount:
 \$13,388.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Jul 2019

ОК