



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SJS7241G
Date of Accident : 09 July 2019

Mr Thng Eng Kwee

Date : 11 July 2019

Estimate To Repair SJJ1253J - Toyota Vios 1.5E A
Chassis No : MR053HY9305078432

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid Vios badge	\$ 48.00
02	1 pc	bootlid Sports badge	\$ 50.00
03	1 pc	bootlid centre logo	\$ 55.00
04	1 pc	bootlid E badge	\$ 45.00
05	1 pc	rear bumper	\$ 455.00
06	2 ps	rear bumper side retainers @ \$100.00	\$ 200.00
07	2 ps	rear bumper side holders @ \$35.00	\$ 70.00
08	2 ps	rear bumper reflectors @ \$90.00	\$ 180.00
09	8 ps	rear bumper fastener clips @ \$4.30	\$ 34.40
10	2 ps	rear bumper splashshield cover @ \$50.00	\$ 100.00
11	1 pc	rear end panel	\$ 605.00
12	1 pc	rear end panel inner trim	\$ 80.70
13	3 ps	rear end panel inner trim clips @ \$4.50	\$ 13.50
Less 25 %			\$ 1,936.60
			\$ 484.15
			\$ 1,452.45
<u>SPECIAL NETT ITEMS</u>			
14	1 set	rear bumper parking sensor	\$ 400.00
15	1 pc	rear bumper lower spoiler (after market accessory)	\$ 800.00
			\$ 1,200.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To check electrical lighting concerned.	\$ 60.00
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00
05		Putty and spray painting of the affected portion.	\$ 800.00
Total			\$ 1,930.00
			\$ 4,582.45

Acknowledged by Repairer
Signature:
Date: