

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Azlan, Syazairdina

Date: 12 Jul 2019

**Preliminary Advice**

Vehicle No	: SLF1109R	Accident Date	: 04/07/2019
Make	: MERCEDES-BENZ GLA180 URBAN (R18 LED)	Policy No.	: 0999994159
Assignment Date	: 11/07/2019	Excess	: S\$1,200.00
Date of Inspection	: 12/07/2019	Est. Duration of Repair	: 4.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,851.10
Revised Amount	:S\$	3,040.50
Check Items (Estimated)	:S\$	1,343.00
Total	:S\$	4,383.50

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	53,427.00
Salvage Value	:S\$	
Margin for Repair	:S\$	41,573.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :