

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SMG7912G	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:INS/IC/CHI/301/2019	YEAR: 31-DEC-2018
ENGINE NO: FB20YE54917	CHASSIS NO: JF1SJ5KC5JG112815
DOA: 08/07/2019	TOA: 1600HRS
TYPE OF CLAIM: 3 RD PARTY	INS COMPANY: AXA

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRONT BUMPER,FRONT PANEL & LH FRT FENDER	\$2800.00 <i>1120/</i>
2.	RESPRAY FRONT BUMPER,FRONT PANEL & LH FRT FENDER	\$2100.00 <i>840/</i>
3.	REMOVE & REFIX AIRCON CONDENSER & RADIATOR TO FACILITATE REPAIR <i>nn</i>	\$220.00 <i>X</i>
4.	FAULT DIAGNOSTIC <i>NN</i>	\$280.00 <i>X?</i>
5.	TO CONDUCT FRONT LIGHTING TEST	\$50.00 <i>30/</i>
6.	SUNDRIES <i>NN</i>	\$100.00 <i>X</i>
7.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	\$150.00 <i>120/</i>
8.		
9.		
10.		
	Total Labour	\$5500.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	<i>Kennerth (CLK)</i>
HP / EMAIL:	<i>96910663 1</i>
BEFORE PAINT:	<i>Yes</i>
DAYS GIVEN:	

Not Notified
Recovery B4 paint
4 days

Estimate

Date 07 / 09 / 2019

001 / 002

Name	QUOTATION FOR SMG7912G	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG112815

Part Number	Part Code Name	Part Code	Q'ty	Price	
57709SG030A	BUMPER FACE-FRONT	FIG-590 57704	1	<i>Pr</i> 594.00	✓
57711SG0009P	BACK BEAM COMPLETE-FRONT	FIG-590 57711	1	288.00	✗ NN
57722SG020	ENERGY ABSORBER-FRONT BUMPER	FIG-590 57705	1	126.00	✗ NN
57731SG220	COVER-FRONT BUMPER	FIG-590 57731	1	4.40	✗ NN
57780SG010	PACKING-BUMPER,RIGHT	FIG-590 57780B	1	<i>mis for</i> 9.00	✗? SVC
57780SG020	PACKING-BUMPER,LEFT	FIG-590 57780C	1	<i>mis</i> 9.00	✓
57707SG000	BRACKET-FRONT BUMPER CORNER,RIGHT	FIG-590 57707AF	1	<i>Pr</i> 36.00	✗
57707SG010	BRACKET-FRONT BUMPER CORNER,LEFT	FIG-590 57707AG	1	<i>mis</i> 36.00	✓
57707SG020	BRACKET-FRONT BUMPER SIDE,RIGHT	FIG-590 57707F	1	<i>Pr</i> 12.60	✗
57707SG030	BRACKET-FRONT BUMPER SIDE,LEFT	FIG-590 57707G	1	<i>mis</i> 12.60	✓
57708SG010A	MOLDING-FRONT BUMPER LEFT	FIG-590 57708E	1	43.20	✗ SVC
J1010SG101	FRT SPORT GRILLE	FIG-911 91121F	1	<i>Pr</i> 1,200.00	✗
84002SG232	LAMP ASSEMBLY-HEAD LEFT	FIG-840 84001B	1	<i>mis</i> 2,380.00	✓
84501AJ060	FOG LIGHT ASSEMBLY-FRONT	FIG-845 84501B	1	272.00	✗ SVC
84927SG030A	BRACKET-FOG LIGHT FRONT LEFT	FIG-845 84927O	1	19.80	✗ SVC
86636SG380A	COVER ASSEMBLY-LAMP WASHER NOZZLE,RIGHT	FIG-877 86636NA	1	<i>mis</i> 54.00	✓
		Page-Total		5,096.60	

Memo

Grand Total
5,665.40

--

Tel

Estimate

Date 07 / 09 / 2019

002 / 002

Name	QUOTATION FOR SMG7912G	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG112815

Part Number	Part Code Name	Part Code	Q'ty	Price
86636SG390A	COVER ASSEMBLY-LAMP WASHER NOZ ZLE,LEFT	FIG-877 86636OA	1	54.00
86636SG361	NOZZLE-LAMP WASHER,RIGHT	FIG-877 86636N	1	79.20
86636SG371	NOZZLE-LAMP WASHER,LEFT	FIG-877 86636O	1	79.20
57120SG0309P	FENDER COMPLETE-FRONT,LEFT	FIG-540 57110A	1	270.00
59110SG031	MUD GUARD,FRONT LEFT	FIG-541 59110C	1	86.40
		Page-Total		568.80
		Sub-Total		5,665.40
		Total		5,665.40
		Tax		0.00
		Grand Total		5,665.40

X SVC

X

X SVC

X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Memo

Grand Total
5,665.40

11,365.40#

--

Tel
