



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SMG7912G	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:INS/IC/CHI/301/2019	YEAR: 31-DEC-2018
ENGINE NO: FB20YE54917	CHASSIS NO: JF1SJ5KC5JG112815
DOA: 08/07/2019	TOA: 1600HRS
TYPE OF CLAIM: 3RD PARTY	INS COMPANY: AXA

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRONT BUMPER,FRONT PANEL & LH FRT FENDER	\$2800.00
2.	RESPRAY FRONT BUMPER,FRONT PANEL & LH FRT FENDER	\$2100.00
3.	REMOVE & REFIX AIRCON CONDENSER & RADIATOR TO FACILITATE REPAIR	\$220.00
4.	FAULT DIAGNOSTIC	\$280.00
5.	TO CONDUCT FRONT LIGHTING TEST	\$50.00
6.	SUNDRIES	\$100.00
7.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	\$150.00
8.		
9.		
10.		
	Total Labour	\$5500.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	
HP / EMAIL:	/
BEFORE PAINT:	
DAYS GIVEN:	

Estimate

Date 07 / 09 / 2019

001 / 002

Name	QUOTATION FOR SMG7912G	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG112815

Part Number	Part Code Name	Part Code	Q'ty	Price
57709SG030A	BUMPER FACE-FRONT	FIG-590 57704	1	594.00
57711SG0009P	BACK BEAM COMPLETE-FRONT	FIG-590 57711	1	288.00
57722SG020	ENERGY ABSORBER-FRONT BUMPER	FIG-590 57705	1	126.00
57731SG220	COVER-FRONT BUMPER	FIG-590 57731	1	4.40
57780SG010	PACKING-BUMPER,RIGHT	FIG-590 57780B	1	9.00
57780SG020	PACKING-BUMPER,LEFT	FIG-590 57780C	1	9.00
57707SG000	BRACKET-FRONT BUMPER CORNER,RIGHT	FIG-590 57707AF	1	36.00
57707SG010	BRACKET-FRONT BUMPER CORNER,LEFT	FIG-590 57707AG	1	36.00
57707SG020	BRACKET-FRONT BUMPER SIDE,RIGHT	FIG-590 57707F	1	12.60
57707SG030	BRACKET-FRONT BUMPER SIDE,LEFT	FIG-590 57707G	1	12.60
57708SG010A	MOLDING-FRONT BUMPER LEFT	FIG-590 57708E	1	43.20
J1010SG101	FRT SPORT GRILLE	FIG-911 91121F	1	1,200.00
84002SG232	LAMP ASSEMBLY-HEAD LEFT	FIG-840 84001B	1	2,380.00
84501AJ060	FOG LIGHT ASSEMBLY-FRONT	FIG-845 84501B	1	272.00
84927SG030A	BRACKET-FOG LIGHT FRONT LEFT	FIG-845 84927O	1	19.80
86636SG380A	COVER ASSEMBLY-LAMP WASHER NOZZLE,RIGHT	FIG-877 86636NA	1	54.00
		Page-Total		5,096.60

Memo

Grand Total
5,665.40

--

Tel

Estimate

Date 07 / 09 / 2019

002 / 002

Name	QUOTATION FOR SMG7912G	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG112815

Part Number	Part Code Name	Part Code	Q'ty	Price
86636SG390A	COVER ASSEMBLY-LAMP WASHER NOZZLE,LEFT	FIG-877 86636OA	1	54.00
86636SG361	NOZZLE-LAMP WASHER,RIGHT	FIG-877 86636N	1	79.20
86636SG371	NOZZLE-LAMP WASHER,LEFT	FIG-877 86636O	1	79.20
57120SG0309P	FENDER COMPLETE-FRONT,LEFT	FIG-540 57110A	1	270.00
59110SG031	MUD GUARD,FRONT LEFT	FIG-541 59110C	1	86.40
		Page-Total		568.80
		Sub-Total		5,665.40
		Total		5,665.40
		Tax		0.00
		Grand Total		5,665.40

Memo

Grand Total
5,665.40

--

Tel
