



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 1

Vehicle No. SLV1136C TOYOTA CHR

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT FENDER RH		733. 980.00	bt✓
1	FRONT FENDER SPLASH SHEILD RH		121.50 253.00	de✓
1	FRONT FENDER ARCH RH		220.00	de✓
1	FRONT BONNET		2550.00	Rx
1	FRONT BONNET HINGE LH & RH @\$110.00		220.00	X NN
1	FRONT BUMPER		1236.70 1850.00	de✓
2	FRONT BUMPER SIDE RETAINER LH & RH @\$120.00		240.00	LH-X RH de✓ 120
1	FRONT BUMPER FOG LAMP GRILLE RH		125.00	de X NN
1	FRONT BUMPER FOG LAMP RH		540.00	de X NN
1	FRONT BUMPER CENTRE CHROME GRILLE		315.00	X NN
1	FRONT BUMPER LOWER MOULDING		318.00	cut✓
1	FRONT BUMPER LOWER SPOILER		600 980.00	de✓
1	FRONT BUMPER SIDE LAMP		240.00	cut✓
1	FRONT WASHER TANK W/MOTOR		342.00	X NN
1	FRONT HEADLAMP RH		1310.00	cut✓
1	FRONT DOOR RH		1320.00	X NN
1	FRONT INNER DOOR BOARD RH		590.00	X NN
1	FRONT DOOR LOWER MOULDING RH		242.00	X NN
1	FRONT DOOR UPPER MOULDING RH		211.00	X NN
1	FRONT DOOR GLASS RUN CHANNEL RH		142.00	X NN
1	FRONT DOOR LOWER TRIM COVER		342.00	X NN
1	FRONT DOOR BLACK TAPE		25.00	X NN
1	FRONT DOOR LOCK RH		520.00	X NN
1	FRONT DOOR POWER WINDOW REGULATOR RH		585.00	X NN
1	REAR DOOR RH		1420.00	X NN
1	REAR INNER DOOR BOARD RH		490.00	X NN
1	REAR DOOR GLASS RUN CHANNEL RH		142.00	X NN
1	REAR DOOR LOWER MOULDING RH		242.00	X NN
1	REAR DOOR UPPER MOULDING RH		211.00	X NN
1	REAR DOOR LOWER TRIM COVER RH		342.00	X NN
1	REAR DOOR BLACK TAPE RH		25.00	X NN
1	REAR DOOR POWER WINDOW REGULATOR RH		585.00	X NN
1	REAR FENDER ARCH RH		210.00	X NN
1	FRONT ROCKER PANEL RH		645.00	X NN
1	FRONT SHOCK ABSORBER RH		456 592.00	bt✓
1	FRONT LOWER ARM RH		298.00	bt✓
1	FRONT TIE ROD RH		145.00	X NN
1	FRONT WHEEL BEARING RH		278.00	bt✓
1	FRONT KNUCKLE ARM RH		398.00	bt✓
			20483.00	
		less 25%	5120.75	25%
			15362.25	

6329.20

4746.90

SPECIAL NETT ITEMS			
1 SET	FRONT FENDER INNER SHEILD CLIPS	80.00	20 new ✓
1 SET	FRONT BUMPER CLIPS	120.00	30 new ✓
1	FRONT FENDER " HYBRID " EMBLEM	85.00	new ✓
5	FRONT DOOR SMALL STICKER @\$35.00	175.00	100 new X NN
1	FRONT BODY BIG STICKER	300.00	X NN
1	FRONT FENDER GRILLE RH	310.00	cut ✓
1 SET	DOOR VISOR	280.00	X NN
1	FRONT 18' TYRE RH	350.00	X NN
1	FRONT SPORT RIM RH	980.00	500 NEC
Total Parts		18042.25	

945



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SLV1136C TOYOTA CHR

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	2200.00	700.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1800.00	700.
3	To remove, refix wiring system at accident damage areas and check for proper function	150.00	30.
4	To perform anti-rust treatment on affected areas	180.00	40.
5	To check wiring and focus headlamp beam	150.00	30.
6	To clear fault code with diagnostic computer and reset to specification.	250.00	100.
7	To remove and replace / refix front & rear door inner parts fitting etc rhs	150.00	X
8	To conduct computerised wheel alignment test	120.00	80.
9	To remove and replace front undercarriage parts rhs	350.00	150.
	Labour Total :	5350.00	1830.
	TOTAL (PARTS & LABOUR):	23392.25	

Tanfik 97495749
 WP

12/7/19

06 days

Lumpsum

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

4746.90

945

1830

7521.90.

4/5 / 6000

6 days