

ASS. REC. BY:

REF: CS/MSG/19012324/AGV 13

N2

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

11.7.19 16.20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EU 61884

Insured:

SLV 31334

at Workshop in/s

Hua Ming Spray

Tel:

67478064 / 67465519

of NO 1 Kaki Bukit Ave 6, #01-61

Policy No:

29067050@mx

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A

9.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.7.19 9.40am

Person Contacted:

Jing Yu

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	EU 61884 - NM/IN/19012324/114
	SLV 31334 - NM/IN/19012324/114
12/7/19	Informed Katherine pending workshop est via merimen
17/9/19	Adrian confirmed LS \$6500 (Red 10,879, 63%)
17/9/19	Send preli revised via merimen

REF: MS16

ASSIGNMENT

From: Date: 12.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: EU 6188H

at Workshop m/s: Hua Mung Spray
of NO1 Faki Bukit Ave 6 # 01-61

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS.

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: EU 6188H. Yr Bgn: 2006 / Sept

Type: ~~M.Cycle~~ / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Airwave. CC: 1496

Colour: White. AC: Insured / Std / NI / NA

Sp. Reading: 85487. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GJ11029793

Gen. Cond: ~~Good~~ / Fair / Poor / BurntSteering: ~~Inorder~~ / Jammed / Leaked / Burnt orBrake: ~~Inorder~~ / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size F: 155/60R15

R: 195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Doublestar.

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I. 12/07/19.

Survey held at: Hua Mung

Des. of Damages: Frt / ~~Rear~~ / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MS16.

COE Expiry: 31/08/26.

MV: 43.5K
TV: 36.8K
Nett: 6.7K.

RECEIVED 18 SEP 2019

17/9/2019

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 7

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 18/9- typist

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: merimen

Lump Sum / I.B.I.: (\$ 6500/2

Survey Fee:

Transportation:

G + RS: 200

Photos: 11

Others:

TOTAL:

211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 17 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLV3133Y	Accident Date	: 09/07/2019
TP Vehicle No	: EU6188H	Assignment Date	: 11/07/2019
Make	: HONDA AIRWAVE	Est. Duration of Repair	: 7
Date of Inspection	: 12/7/2019		
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,379.00
Revised Amount	:S\$	6,500.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,500.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2019 09:08		11 Jul 2019 16:20 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	ZHANG YAN, ID: S7384666H		[Created by insurer]
Main Claimant:	LIM PHAIK FANG, ID: S2554579F		
Vehicle Reg. No.:	EU6188H	Date of Loss:	09/07/2019 16:00 - :59 [153 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29067050QMX (Comprehensive) Coverage: 27/12/2018 - 26/12/2019
Vehicle Reg. No. (Insured):	SLV3133Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/07/2019]		
Adj Asg. Remarks:	on WP. Liab: Dispute(NR). Agree on SJE. Assign: LKK Auto Consultants. Contact: Albert Tan @ 6746 5519.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View All

Search Tasks

Create New Task

Complete

View Sent Message

This mail is associated with :

***EU6188H (599528)**
[SLV3133Y]

TP
LIM PHAIK FANG
Jul 9 2019 5:00PM
[ZHANG YAN]
Hua Meng Spray Painting Workshop

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 12/07/2019 14:27 PM.
To MSI_WCS
Subject TP SURVEY EU 6188H

Dear Katherine,

Please be informed that we have inspected the vehicle EU 6188H on 12/7/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


[SEARCH](#)

[Advanced Search](#)

Home > Used Cars > Direct Owners > Honda Airwave 1.5A M (COE till 09/2028)

Honda Airwave 1.5A M (COE till 09/2028)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[DIRECT OWNER](#)

Price	\$52,000		
Depreciation ⓘ	\$5,670 /yr	Reg Date	10-Sep-2008 (9yrs 1mth 28days COE left)
Mileage	211,606 km (19.5k /yr)	Manufactured ⓘ	2008
Road Tax ⓘ	\$750 /yr	Transmission	Auto
Dereg Value ⓘ	\$29,654 as of today (change)	OMV ⓘ	\$14,617
COE ⓘ	\$32,339	ARF ⓘ	\$13,862
Engine Cap	1,496 cc	Power	81.0 kW (108 bhp)
Curb Weight ⓘ	1,160 kg	No. of Owners ⓘ	4
Type of Vehicle	Stationwagon		

Features

Reliable 1.5L DOHC VTEC Engine, 7 Speed Automatic Transmission, 2 x Airbags, ABS, Climatic Aircon Control, Paddle Shift Control. View Specs Of The Hon View specs of the Honda Airwave (2008-2014)

Accessories

Sports Rims, Leather Seats, Retractable Side Mirrors, Reverse Sensors, Rear Knockdown Seats, Audio.

Description

Well Maintained With No Expenses Spared. Regular Servicing Done. No Repairs Needed. Good To Go For The Many More Years To Come. Safe Buy. Minimum Value To Lose. Feel Free To WhatsApp Me For Viewing.

Category

COE Car, Direct Owner Sale

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER



Preferred Viewing Area

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Contact Person(s) Zhang
Contact No. 97932700

ESSENTIAL TRANSACTION FORMS

- Indemnity form
- Sales agreement
- Receipt
- Hand-over form
- Ownership Transfer



GET HELP WITH
PAPERWORK

SGCARMART
CONNECT
Without Extra Costs

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with Car Loans, Insurance, Payments & Ownership Transfer. FREE for all sgCarMart Advertised Vehicles.



Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers & Sellers

Product url: 23-Jan-2019 | Last updated url: 07-Jul-2019

Upfront Payment

[+ more financial info](#)

Transfer Fee ⓘ	\$25	
Down Payment ⓘ	\$15,600 (change)	Maximum 70% loan
	\$547	Based on 3.95% interest rate
	\$1,145 onwards	

Powered by



AutoInn
The Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

15 vehicles

Search

Airwave

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Airwave

Any

Any

> 10 year(s)
old

Any

Any

Any

Available

 ☐ **Honda Airwave 1.5A M (New** **\$25,888** **\$5,170 /yr** **01-Sep-2008** **1,496 cc** **140,000 km** **Stationwagon** **Available**
5-yr COE]
Full Loan Available, Excellent Condition,High Trade In. Please Call/SMS Now! Don't Miss.
 ☆ **Posted: 15-Nov-2019** **Tags: 2008 Honda Airwave, 2008 honda airwave, Honda Airwave, honda airwave, Honda Airwave, Airwave, Used Honda**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

	Honda Airwave LSA M (COE till 10/2028)	\$47,500	\$5,130 /yr	13-Oct-2008	1,496 cc	126,783 km	Stationwagon	Available
Brand New Coat Of Paint, New Headunit, Fog Lights, Fully Serviced, Well Maintain. Great Boot Space For PDV!								
	Parked - 10-Jul-2018	Type: 2008 Honda Airwave, 2008 honda airwave, honda airwave, honda airwaves, hondo airwave, airwave, c-hat headon						

☐	Honda Airwave 1.5A M Skyroof (COE till 10/2023)	\$25,200	\$5,880 /yr	23-Oct-2008	1,496 cc	200,600 km	Stationwagon	Available
--------------------------	---	----------	-------------	-------------	----------	------------	--------------	-----------

Consignment Code: A121. Loan Packages Available To Choose From. High Trade In Value For Your Car! No Hidden Cost. For Further

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4579F
Vehicle Details	
Vehicle No.:	EU6188H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5A
Primary Colour:	White
Manufacturing Year:	2005
Engine No.:	L15A5035487
Chassis No.:	GJ11029793
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$18,563.00
Original Registration Date:	12 Sep 2006
First Registration Date:	12 Sep 2006
Transfer Count:	0
Actual ARF Paid:	\$20,420.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2026
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$51,518.00
COE Rebate Amount:	\$36,755.00
Total Rebate Amount:	\$36,755.00

The information contained herein is correct as at 12 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/07/2019 16:18
Date Of Accident	09/07/2019 16:30
Exact Location Of Accident	PORTSDOWN AVE FLYOVER JUNCTION TWDS QUEENSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EU6188H
Insured/Policyholder	
Name Of Registered Owner	LIM PHAIK FANG
NRIC No	S2554579F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98575163
Alternative Phone No	OFFICE-98575163

Vehicle Particulars

Manufacturer	HONDA
Model	AIRWAVE
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5105549321
Cover Note Number	-

Driver

Name of Driver	TAN KUAN YONG JIMMY
NRIC No	S7304482J
Date Of Birth	22/01/1973
Occupation	OUTDOOR
Date Of Driving Pass	02/02/1994
Driving Experience	25 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91990607
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 470 AMK AVE 10 #12-900
Postcode	560470
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WANG ZIYU
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV3133Y / <i>Harnier</i>
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN KUAN YONG JIMMY
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	EU6188H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	WANG ZIYU
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	EU6188H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please read carefully the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may cause insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insured companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiry by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
SAC/CRN No.

Accident Sketch Plan

DATE: 01/01/2024



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary along Lane 1 of Portdown Ave facing south. Continuity of portdown ave higher junction on rd of 30th St. Traffic light was red at that time. Suddenly, I heard a heavy impact and felt an impact from rear portion of my vehicle. Vehicle 15 was collided into my rear portion of my vehicle.

DECLARATION

I declare the foregoing particulars are true in every respect.

Witness's Signature
Date & Time:

Driver's Signature
(If driver is not the party involved)
Date & Time:

Reporting Person's Signature
Name
Date & Time:

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

GJ11029793

LIM PHAIK FANG

BLK 166 BEDOK SOUTH AVE 3

#11-451

S 460166

TPMS16
Veron-

Date

:16.07.2019

Vehicle No

:EU 6188 H

Make/Model

:HONDA AIRWAVE

Accident date

:09.07.2019

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

List Items

1	Rear windscreen rubber <i>New</i>	1	\$ 67.8 ✓
2	Rear windscreen <i>Shattered</i>	1	\$ 1232 ✓
3	Rear wiper arm <i>cut</i>	1	\$ 59.4 ✓
4	Rear wiper arm cover <i>cut</i>	1	\$ 13.2 ✓
5	Rear wiper blade <i>New</i>	1	\$ 52.8 ✓
6	Rear wiper motor <i>Damaged</i>	1	\$ 344.3 ✓
7	Rear tailgate <i>Distorted</i>	1	\$ 1188.8 ✓
8	Rear tailgate hinges @ \$ 82.30 <i>New</i>	2	\$ 164.6 ✓
9	Rear tailgate upper lock <i>Damaged</i>	1	\$ 239.6 ✓
10	Rear tailgate lower lock <i>Not New</i>	1	\$ 75 ✓
11	Rear tailgate shock absorber @ \$ 191.20 <i>Not New</i>	2	\$ 382.4 ✓
12	Rear tailgate inner board <i>cracked</i>	1	\$ 375.1 ✓
13	Rear tailgate inner handle <i>Not New</i>	1	\$ 83.6 ✓
14	Rear tailgate weather strip <i>cut</i>	1	\$ 115.5 ✓
15	Rear tailgate handle <i>cracked</i>	1	\$ 193.6 ✓
16	Rear tailgate H logo <i>New</i>	1	\$ 30.9 ✓
17	Rear tailgate Airwave emblem <i>New</i>	1	\$ 43.6 ✓
18	Rear tailgate reflector @ \$ 278.30 <i>cracked</i>	2	\$ 556.6 ✓
19	Rear tailgate centre garnish <i>cracked</i>	1	\$ 350.9 ✓
20	Rear number plate lamp <i>New</i>	1	\$ 71.5 ✓
21	Rear number plate <i>Best</i>	1	\$ 55 <i>30(SN)</i>
22	Rear number plate holder <i>Deland</i>	1	\$ 55 <i>30(SN)</i>
23	Rear lamp @ \$ 346.10 <i>cracked</i>	2	\$ 692.2 ✓
24	Rear lamp housing @ \$ 229.90 <i>Repsis</i>	2	\$ 459.8 ✓
25	Rear end panel <i>Damaged</i>	1	\$ 375.1 ✓
26	Rear end panel inner top garnish <i>Deland</i>	1	\$ 229.9 ✓
27	Rear bumper <i>Deland</i>	1	\$ 602.6 ✓
28	Rear bumper lower lip <i>Deland</i>	1	\$ 693 <i>380(SN)</i>
29	Rear bumper reverse sensor @ \$ 418.00 <i>Damaged</i>	2	\$ 836 <i>200(SN)</i>
30	Rear bumper clips (1 set) <i>New</i>	1	\$ 55 <i>30</i>
31	Rear bumper beam @ \$ 223.90 <i>Best</i>	2	\$ 447.8 <i>185.10</i>

101426

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

LIM PHAIK FANG

BLK 166 BEDOK SOUTH AVE 3

#11-451

S 460166

Date

:16.07.2019

Vehicle No

:EU 6188 H

Make/Model

:HONDA AIRWAVE

Accident date

:09.07.2019

No	DESCRIPTION	Qty	Amount (\$S)
32	Rear spare tyre well <i>Repair</i>	1	\$ 869 <i>X</i>
33	Rear spare tyre top cover <i>Not N/A</i>	1	\$ 254.1 <i>X</i>
34	Rear spare tyre well insulation @ \$ 57.20 <i>Not N/A</i>	3	\$ 171.6 <i>X</i>
35	Rear bumper side holder @ \$ 33.90 <i>Not N/A</i>	2	\$ 67.8 <i>✓</i>
36	Rear windscreen solar flim <i>Not N/A</i>	1	\$ 165 <i>✓</i>
37	Rear camera <i>Done</i>	1	\$ 880 380 (SN)
38	Rear LH fender <i>Repair</i>	1	\$ 1050.5 <i>X</i>
39	Rear fender inner garnish @ \$ 375.10 <i>Not N/A</i>	2	\$ 750.2 <i>X</i>
40	Rear fender inner shield @ \$ 171.60 <i>Not N/A</i>	2	\$ 343.2 <i>X</i>
41	Rear exhaust pipe <i>Repair</i>	1	\$ 822.8 <i>X</i>
42	Rear exhaust pipe chrome <i>Not N/A</i>	1	\$ 88 <i>X</i>
43	Rear exhaust pipe mounting <i>Not N/A</i>	1	\$ 33.9 <i>X</i>
			\$ 15638.7
		Less 25% Disc	\$ 3909.7
		Total	\$ 11729

Labour Cost

1	To supply rear end panel inner sealant	\$ 200 <i>60</i>
2	To supply rear windscreen sealant	\$ 50 <i>✓</i>
3	Remove & reinstall rear windscreen	\$ 150 120
4	Remove & reinstall camera	\$ 100 50
5	Remove & reinstall exhaust pipe	\$ 150 80
6	Remove & reinstall bootlid inner garnish	\$ 200 80
7	Remove & reinstall petrol tank	\$ 200 <i>X</i>
8	Remove & reinstall reverse sensor	\$ 150 50
9	Remove, replace & repair consistent to the accident	\$ 2500 1000
10	Respray painting	\$ 1800 900
11	Tuff kote	\$ 150 60
	Total	\$ 5650

Grand Total \$ 17379 18160.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Total: 9197.20

2/3: 65K (Nett Value)

OT Days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19012324/AGVF3N2

Date: 24/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29067050QMX
Claimant Vehicle No :	EU6188H	Insured Vehicle No :	SLV3133Y
Date of Loss:	09/07/2019	Nature of Claim:	TP
		Claim No:	599528

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EU6188H	Engine No:	L15A5035487
Make & Model:	HONDA AIRWAVE, 1.5 (A)	Chassis No:	GJ11029793
Reg. Date:	12/09/2006 (Man. Year: 2005)	Odometer:	85487 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Double Star 6 mm	Rear Left Side:	Double Star 6 mm
Front Right Side:	Double Star 6 mm	Rear Right Side:	Double Star 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,760.96	6,857.20	5,903.76	46.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	2,340.00	3,060.00	56.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,160.96	9,197.20	8,963.76	49.36
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	18,160.96	6,500.00	11,660.96	64.21

INSPECTION

Date of Assignment:	11/07/2019	
Date Inspected:	12/07/2019	Inspected At:
		Hua Meng Spray Painting Workshop (HQ)
		No 1 Kaki Bukit Avenue 6, #01-61
		Autobay@Kaki Bukit
		Singapore 417883
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2019)
Parts:	M1-MPV	HONDA AIRWAVE 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EU6188H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Necessary	67.80 FL	*67.80 FL
2	1		*REAR WINDSCREEN	Shattered	1,232.00 FL	*1,232.00 FL
3	1		*REAR WIPER ARM	Cut	59.40 FL	*59.40 FL
4	1		*REAR WIPER ARM COVER	Cut	13.20 FL	*13.20 FL
5	1		*REAR WIPER BLADE	Not Necessary	52.80 FL	*- FL
6	1		*REAR WIPER MOTOR	Damaged	344.30 FL	*344.30 FL
7	1		*REAR TAILGATE	Distorted	1,188.80 FL	*1,188.80 FL
8	2		*REAR TAILGATE HINGES	Not Necessary	164.60 FL	*- FL
9	1		*REAR TAILGATE UPPER LOCK	Damaged	239.60 FL	*239.60 FL
10	1		*REAR TAILGATE LOWER LOCK	Not Necessary	75.00 FL	*- FL
11	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	382.40 FL	*- FL
12	1		*REAR TAILGATE INNER BOARD	Cracked	375.10 FL	*375.10 FL
13	1		*REAR TAILGATE INNER HANDLE	Not Necessary	83.60 FL	*- FL
14	1		*REAR TAILGATE WEATHER STRIP	Cut	115.50 FL	*115.50 FL
15	1		*REAR TAILGATE HANDLE	Cracked	193.60 FL	*193.60 FL
16	1		*REAR TAILGATE H LOGO	Necessary	30.90 FL	*30.90 FL
17	1		*REAR TAILGATE AIRWAVE EMBLEM	Necessary	43.60 FL	*43.60 FL
18	2		*REAR TAILGATE REFLECTOR	Cracked	556.60 FL	*556.60 FL
19	1		*REAR TAILGATE CENTRE GARNISH	Cracked	350.90 FL	*350.90 FL
20	1		*REAR NUMBER PLATE LAMP	Not Necessary	71.50 FL	*- FL
21	2		*REAR LAMP	Cracked	692.20 FL	*692.20 FL
22	2		*REAR LAMP HOUSING	Repair	459.80 FL	*- FL
23	1		*REAR END PANEL	Dented	375.10 FL	*375.10 FL
24	1		*REAR END PANEL INNER TOP GARNISH	Deformed	229.90 FL	*229.90 FL
25	1		*REAR BUMPER	Deformed	602.60 FL	*602.60 FL
26	1		*SET REAR BUMPER CLIPS	Necessary	55.00 FL	*30.00 FL
27	2		*REAR BUMPER BEAM	Bent	447.80 FL	*185.10 FL
28	1		*REAR SPARE TYRE WELL	Repair	869.00 FL	*- FL
29	1		*REAR SPARE TYRE TOP COVER	Not Necessary	254.10 FL	*- FL
30	3		*REAR SPARE TYRE WELL INSULATION	Not Necessary	171.60 FL	*- FL
31	2		*REAR BUMPER SIDE HOLDER	Necessary	67.80 FL	*67.80 FL
32	1		*REAR WINDSCREEN SOLAR FILM	Necessary	165.00 FL	*165.00 FL
33	1		*REAR LH FENDER	Repair	1,050.50 FL	*- FL
34	2		*REAR FENDER INNER GARNISH	Not Necessary	750.20 FL	*- FL
35	2		*REAR FENDER INNER SHIELD	Not Necessary	343.20 FL	*- FL
36	1		*REAR EXHAUST PIPE	Repair	822.80 FL	*- FL
37	1		*REAR EXHAUST PIPE CHROME	Not Necessary	88.00 FL	*- FL
38	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	33.90 FL	*- FL
39	1		*REAR NUMBER PLATE	Bent	44.00 FS	*30.00 FS
40	1		*REAR NUMBER PLATE HOLDER	Deformed	44.00 FS	*30.00 FS
41	1		*REAR BUMPER LOWER LIP	Deformed	554.40 FS	*380.00 FS
42	2		*REAR BUMPER REVERSE SENSOR	Damaged	668.80 FS	*200.00 FS
43	1		*REAR CAMERA	Damaged	704.00 FS	*380.00 FS
44	1		*REAR END PANEL INNER SEALANT	Necessary	200.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					15,384.90	8,289.00
- List Item Discount on L Items 20.00/20.00% (S\$)					2,623.94	1,431.80
Total Parts (S\$)					12,760.96	6,857.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
2	REMOVE & REINSTALL CAMERA	New	100.00	50.00
3	REMOVE & REINSTALL EXHAUST PIPE	New	150.00	80.00
4	REMOVE & REINSTALL BOOTLID INNER GARNISH	New	200.00	80.00
5	REMOVE & REINSTALL PETROL TANK	New	200.00	0.00
6	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
7	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	2,500.00	1,000.00
8	RESPRAY PAINTING	New	1,800.00	900.00
9	TUFF KOTE	New	150.00	60.00
Gross Labour Cost (S\$)			5,400.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >