

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0848/2019/GW
Date : 11-Jul-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Goh Choi Sia Madeline
Address : Blk 312 C Clementi Ave 4
#32-185
Singapore 123312
Telephone : (HP)+90017500
Type of Claim : Third Party Claims
Policy No. : 71661531 QMY
Vehicle No : **SMA 2436 D**
Model Code : Q2 1.0 TFSI S Tronic
Model / Year : May-18
Engine No : CHZ 646493
Chassis No : WAUZZZGA4JA058069
Mileage : 37082 KM
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jul-19
Place of Accident : Chang South Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMA 2436 D

S/n	Nature of Jobs	Estimated Charges	
1	To tow and recover vehicle from scene of accident.	S/N	AIG
2	To carry out first measurement test on car-oliner.	S/N \$	800.00
3	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy.	S/N \$	360.00
4	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,400.00
5	To dismantle both front door panel trims. To remove and reinstall both wing mirror assy.	S/N \$	600.00
6	To renew engine components and intake manifold. To inspect for further damage.	S/N \$	480.00
7	To remove and reinstall engine assy with gearbox assy to facillitate car-oliner repairs.	S/N \$	2,800.00
SUB TOTAL LABOUR CHARGES		:	\$ 6,440.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 2436 D

S/N	Nature of Jobs	Estimated Charges
8	To remove and reinstall front suspension assy with subframe to facillitate car o-liner repairs.inspect for damages and renew if necessary.	S/N \$ 2,400.00
9	To place vehicle on car o-liner.	S/N \$ 1,800.00
10	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To repair both front doors. To remove and renew front lock carrier. To align front chassis frame to position. Re-organise crash management components . Reinstall all parts removed.	\$ 9,200.00
11	To respray front bumper, bonnet, hinges, both front fenders, both front doors and rhs upper A-pillar.	\$ 7,100.00
12	To carry out wheel alignment.	S/N \$ 240.00
13	To carry out diagnostic check.	S/N \$ 192.00
TOTAL LABOUR CHARGES		: <u>\$ 27,372.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 2436 D

S/N		Parts Description	Damaged Parts & Prices S/Nett	
1		FRONT BUMPER	\$	1,706.00
2		FRONT BUMPER FIXING PARTS	\$	314.00
3		FRONT BUMPER GRILLE-CENTER	\$	179.00
4		FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$	308.00
5		FRONT BUMPER END CAP-LH/RH	2 \$	62.00
6		FRONT BUMPER SPOILR	\$	273.00
7		FRONT BUMPER CLOSING ELEMENT	\$	142.00
8		FRONT WHEEL SPOILER-LH/RH	2 \$	62.00
9		FRONT ADAPTER-LH	\$	32.00
10		FRONT ADAPTER-RH	\$	38.00
11		RADIATOR GRILLE	\$	1,301.00
12		RADIATOR GRILLE STRIKER PLATE	\$	114.00
13		FRONT BUMPER CARRIER	\$	625.00
14		FRONT BUMPER FOAM FILLER PIECE	\$	71.00
15		FRONT BUMPER COVER	\$	91.00
16		FRONT BUMPER GUIDE SECTION-LH/RH	2 \$	64.00
17		FRONT SIGN 'CAUTION'	\$	13.00
18		STICKER AIR CODITIONER	\$	7.00
19		SIGNAL HORN-RH	\$	180.00
20		FANFARE-LH	\$	262.00
SUB - TOTAL SPARE PARTS CHARGES			:	<u>\$ 5,844.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 2436 D

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
21	SPRING SHACKLE-LH/RH	2 \$	58.00
22	FRONT FENDER-LH/RH	2 \$	2,094.00
23	FRONT FENDER ATTACHMENT PARTS	2 \$	72.00
24	FRONT FENDER REAR BRACKET-LH/RH	2 \$	28.00
25	FRONT FENDER CENTRE BRACKET-LH/RH	2 \$	86.00
26	FRONT FENDER BRACKET-LH/RH	2 \$	28.00
27	FRONT FENDER POP RIVET	12 \$	36.00
28	FRONT FENDER BRACE-LH/RH	2 \$	58.00
29	FRONT WHEEL HOUSING LINER-LH/RH	2 \$	366.00
30	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	2 \$	103.00
31	BONNET	\$	2,549.00
32	BONNET ATTACHMENT PART	\$	149.00
33	BONNET LID HINGE-LH/RH	2 \$	112.00
34	BONNET GAS FILLED STRUT	\$	93.00
35	BONNET STRIKER-LH/RH	2 \$	200.00
36	BONNET SOUND ABSORBER	\$	201.00
37	BONNET IMPACT PROTECTION	3 \$	82.00
38	PLENUM CHAMBER COVER	\$	144.00
39	WATER BOX SEAL FRONT PANEL	\$	124.00
40	BONNET LID LOCK WITH MICRO -SWITCH	2 \$	367.00
SUB - TOTAL SPARE PARTS CHARGES		:	\$ 6,950.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 2436 D

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>		<u>S/Nett</u>
41	FLAT CONNECTOR HOUSING	\$	12.00
42	BONNET BOWDEN CABLE -CENTER	\$	53.00
43	BONNET LID LOCK CABLE	\$	67.00
44	BONNET LID LOCK CABLE COVER	\$	9.00
45	BONNET RELEASE ELEMENT	\$	53.00
46	BONNET BOWDEN CABLE -CENTER	\$	53.00
47	BONNET BOWDEN CABLE-LH/RH	2 \$	106.00
48	RELEASE LEVER	\$	12.00
49	HEADLIGHT MOUNTING-LH	\$	107.00
50	LED HEADLIGHT MOUNTING-LH/RH	2 \$	214.00
51	LED HEADLIGHT-LH/RH	2 \$	8,982.00
52	LED HEADLIGHT POWER MODULE	\$	693.00
53	LED HEADLIGHT CONTROL UNIT	\$	508.00
54	LED HEADLIGHT WITH HEAT SINK-RH	\$	666.00
55	LED HEADLIGHT HOSE-RH	\$	26.00
56	LED HEADLIGHT LIFT CYLINER-LH/RH	2 \$	256.00
57	LED HEALDIGHT LIFT CULINDER HOSE	\$	170.00
58	LED HEADLIGHT DISTRIBUTOR	\$	27.00
59	LED HEALDIGHT ELBOW FITTING	3 \$	81.00
60	LED HEADLIGHT PUMP	\$	147.00
SUB - TOTAL SPARE PARTS CHARGES		:	\$ 12,242.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 2436 D

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
61	WINDSCREEN WASHER SYSTEM PUMP	\$	118.00
62	WASH WATER RESERVOIR	\$	156.00
63	RADIATOR LOCK CARRIER WITH MOUNTING	\$	907.00
64	A/C CONDENSER WITH FLUID RESERVOIR	\$	503.00
65	REFRIGERANT LINE FOR A/C CONDENSER CUT OFF POINT	\$	601.00
66	REFRIGERANT LINE FOR A/C COMPRESSOR	\$	461.00
67	RADIATOR	\$	878.00
68	INTERCOOLER	\$	837.00
69	READY-MIX COOLANT-1.5LTR	4 \$	84.00
70	RADIATOR UPPER BRACKET	2 \$	77.00
71	RADIATOR LOWER BUSH	2 \$	18.00
72	RADIATOR FAN WITH FAN RING	\$	1,483.00
73	RADIATOR AIR GUIDE-LH/RH	2 \$	54.00
74	RADIATOR SEAL-RH OUTER	\$	6.00
75	RADIATOR AIR GUIDE-UPPER CENTRE	\$	19.00
76	AIR INTAKE	\$	53.00
77	AIR INTAKE HOSE	\$	62.00
78	AIR DUCT	\$	19.00
79	AIR INTAKE WATER DRAINAGE HOSE	\$	31.00
80	AIR FILTER	\$	259.00
SUB - TOTAL SPARE PARTS CHARGES		:	\$ 6,626.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 2436 D

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
81	INTERCOOLER TUBE	\$	129.00
82	INTAKE MANIFOLD	2 \$	588.00
83	INTERCOOLER GASKET	\$	13.00
84	FRONT WHEEL COVER-LH/RH	2 \$	588.00
85	FRONT NO. PLATE	S/N \$	40.00
95	SUNDRIES	\$	800.00
TOTAL SPARE PARTS CHARGES		:	\$ 33,820.00
TOTAL LABOUR CHARGES			\$ 27,372.00
GRAND TOTAL			\$ 61,192.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved