

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0868/2019/KK
Date : 17-Jul-19

Vehicle NOT IN workshop. Please arrange for survey

Your Insured Vehicle no : SMC 734 C

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Wan Yew Heng Lindy
Address : Blk 679B Jurong West Central 1
#07-02
Singapore 642679
Telephone : HP +65 96589377
Type of Claim : Third Party Claim
Policy No. : 10644674
Vehicle No : **SFS 1148 E**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : 26-02-14
Engine No : CXS 055041
Chassis No : WAUZZZ8V8E1014373
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jul-19
Place of Accident : Along Woodlands Ave 2

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFS 1148 E

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 250 300 250
3	To respray rear bumper.	\$ 900.00 550 180 550
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 2,422.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SFS 1148 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>repair</i>	\$ 1,708.00	
2	REAR BUMPER FIXING PARTS <i>X</i>	\$ 175.00	
3	REAR BUMPER GUIDE SECTION - LH/RH <i>X</i>	\$ 30.00	
4	LOCKING MECHANISM <i>X</i>	2 \$ 106.00	
5	REAR LIGHT REFLECTOR - LH/RH <i>X</i>	\$ 76.00	
6	REAR BUMPER SPOILER <i>X</i>	\$ 216.00	
7	REAR BUMPER REINFORCEMENT <i>X</i>	\$ 522.00	
8	HEX COLLARED BOLT <i>all</i>	8 \$ 144.00	
9	REAR BUMPER BRACKET - LH/RH <i>!</i>	\$ 24.00	
10	REAR SENSOR - INNER/OUTER <i>!</i>	2 \$ 924.00	
11	REAR SENSORE SEAL RING <i>u</i>	4 \$ 48.00	
12	SUNDRIES <i>!</i>	\$ 27.00	
TOTAL SPARE PARTS		\$ 4,000.00	
TOTAL LABOUR CHARGES		\$ 2,422.00	
GRAND TOTAL		\$ 6,422.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: *Rossul - Hp 90010068*

Surveyed Date

: *3 days*

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

18/07/19 @ 1045
Reay after repair

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant