

# **SERVICE ESTIMATE**

#### - C00001      SL: SERVICE SALES - PC

Mr Jessen Johann Heinrich  
9A Swiss Club Road

GST Reg.No:M28920628X

Inv.No. : B&P      0      Page: 1

Inv.date : 11/07/2019

WIP No. : 24771

Veh.In/Out:

Singapore 288146

\*Tel.No. : Mobile: 91715152

Reg.No. : SMK6558G

Closed by : Patricia Kueh Anak S

Reg.date : 18/04/2019

Svc Consultant :

Mileage : 0

Remarks : Mr Jessen Johann Hei

Chassis No: SADHA2ALIKIF72749

| Op.No | Description                                                                                                | Mech | Qty | Price   | Disc% | Pkg | Amount   | G |
|-------|------------------------------------------------------------------------------------------------------------|------|-----|---------|-------|-----|----------|---|
| 802   | TO REPLACE FRT DOOR LH,<br>REAR DOOR LH,REAR BUMPER,<br>FRT DOOR MOULDING LH,<br>REAR DOOR MOULDING LH,ETC |      | 0   | 3150.00 | 0     |     | 3,150.00 | S |
| 800   | TO PUTTY SPRAYPAINT ON<br>FRT DOOR LH, REAR DOOR LH,<br>REAR BUMPER,ETC                                    |      | 0   | 2800.00 | 0     |     | 2,800.00 | S |
| 802   | TO TRANSFER FRT DOOR LH PARTS                                                                              |      | 0   | 500.00  | 0     |     | 500.00   | S |
| 802   | TO TRANSFER REAR DOOR LH PARTS                                                                             |      | 0   | 500.00  | 0     |     | 500.00   | S |
| 280   | TO CHECK WIRING INCLUDE<br>RESETTING OF ALL ELECTRICAL MODULES                                             |      | 0   | 510.00  | 0     |     | 510.00   | S |
| 0031  | TO REPLACE REAR RIM LH                                                                                     |      | 0   | 50.00   | 0     |     | 50.00    | S |
| 419   | WHEEL ALIGNMENT                                                                                            |      | 0   | 280.00  | 0     |     | 280.00   | S |
|       | PANEL-DOOR FRT LH                                                                                          | 1.0  | EA  | 3354.40 |       |     | 3,354.40 | S |
|       | PANEL-DOOR REAR LH                                                                                         | 1.0  | EA  | 3321.70 |       |     | 3,321.70 | S |
|       | MOULDING DOOR FRT LH                                                                                       | 1.0  | EA  | 448.60  |       |     | 448.60   | S |
|       | MOULDING DOOR REAR L                                                                                       | 1.0  | EA  | 714.10  |       |     | 714.10   | S |

# **SERVICE ESTIMATE**

##### - C00001      SL: SERVICE SALES - PC

Mr Jessen Johann Heinrich  
9A Swiss Club Road

GST Reg.No: H28920628X

Inv.No. : B&P      0 Page 2

Inv.date. : 11/07/2019

WIP No. : 24771

Veh.In/Out:

\*Tel.No. : Mobile: 91715159

Reg.No. : SMK65586

Reg.date. : 18/04/2019

Mileage : 0

Chassis No: SADHA2A11K1F72749

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Mr Jessen Johann Hei

| Op.No | Description        | Mech Qty | Price   | Disc% | Pkg | Amount   | G |
|-------|--------------------|----------|---------|-------|-----|----------|---|
|       | MOULDING-BODY SIDE | 1.0 EA   | 341.90  |       |     | 341.90   | S |
|       | FINISHER LHF       | 1.0 EA   | 169.50  |       |     | 169.50   | S |
|       | FINISHER LOWER LHF | 1.0 EA   | 158.50  |       |     | 158.50   | S |
|       | FINISHER LOWER LHR | 1.0 EA   | 148.70  |       |     | 148.70   | S |
|       | FINISHER UPPER LHR | 1.0 EA   | 495.50  |       |     | 495.50   | S |
|       | SEAL-DOOR FRT      | 1.0 EA   | 176.10  |       |     | 176.10   | S |
|       | SEAL-DOOR REAR     | 1.0 EA   | 177.00  |       |     | 177.00   | S |
|       | WHEEL-ROAD-ALLOY   | 1.0 EA   | 5644.90 |       |     | 5,644.90 | S |
|       | LINER-WHEELARCH    | 1.0 EA   | 158.20  |       |     | 158.20   | S |
|       | COVER-BUMPER REAR  | 1.0 EA   | 1887.40 |       |     | 1,887.40 | S |
|       | PANEL-VALANCE      | 1.0 EA   | 878.00  |       |     | 878.00   | S |
|       | MOUNTING-BRACKET   | 1.0 EA   | 811.60  |       |     | 811.60   | S |
|       | BRACKET-BUMPER     | 1.0 EA   | 177.50  |       |     | 177.50   | S |
|       | BRACKET-BUMPER     | 1.0 EA   | 177.50  |       |     | 177.50   | S |
|       | MOUNTING-BRACKET   | 1.0 EA   | 113.70  |       |     | 113.70   | S |
|       | MOUNTING-BRACKET   | 1.0 EA   | 113.70  |       |     | 113.70   | S |
|       | BRACKET-BUMPER     | 1.0 EA   | 56.80   |       |     | 56.80    | S |

### SERVICE ESTIMATE

##### - C00001 SL: SERVICE SALES - PC

Mr Jessen Johann Heinrich  
9A Swiss Club Road

Singapore 288146

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 3

Inv.date: 11/07/2019

WIP No. : 24771

Veh.In/Out:

\*Tel.No. : Mobile: 91715159

Reg.No. : SMK6558G

Reg.date: 18/04/2019

Mileage : 0

Chassis No: SADHA2A11K1F72749

Closed by .... : Patricia Kueh Anak S

Svc Consultant :

Remarks ..... : Mr Jessen Johann Hei

| Op.No | Description          | Mech Qty | Price  | Disc% | Pkg | Amount | G |
|-------|----------------------|----------|--------|-------|-----|--------|---|
|       | BRACKET-BUMPER       | 1.0 EA   | 56.80  |       |     | 56.80  | S |
|       | PATCH-TAPE           | 1.0 EA   | 30.30  |       |     | 30.30  | S |
|       | BODY PANEL SEALANT X | 1.0 EA   | 883.20 |       |     | 883.20 | S |
|       | ADHESIVE SEALER FL2  | 1.0 EA   | 669.10 |       |     | 669.10 | S |
|       | SOUND DEADENING PAD  | 2.0 EA   | 250.00 |       |     | 500.00 | S |

Gross Total. 29,454.70

Labour Total 7,790.00  
Parts Total 21,664.70  
Package Total 0.00

Net..... 29,454.70  
GST @ 7.0% 2,061.83  
Total..... 31,516.55  
Paid..... 0.00  
Please Pay.. 31,516.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated