

22/03/2002

ASS. REC. BY:

REF:

CS/AIG/19012342/Kqd302k

Special Instruction:

Surname: Kenneth

Merrimen

ASSIGNMENT (Office)

From (Person): Fan Winnie

of

AIG

Date/Time: 12/7/19 @ 11:01 am

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMF 182Y

Insured:

at Workshop m/s

Tong Luck

Tel:

6250 0088

of

160 Sin Ming Drive #07-01/06

Policy No:

999995580

Claim No:

337394X80556

Sum Insured:

Excess:

TBA / 500

Make of Veh:

(Client's Record)

D.O.A.

10/07/2019

CA / (REV)

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:17 am @ 12/7/19

Person Contacted:

Yuching

Vehicle

(IN/OUT)

Date/Time	Action/Instruction
	Tong Luck! ✓
	SMF 182Y - X
12/7/19 @ 3:25pm	visit to Winnie Fan via Merrimen.
15/7/19 @ 2:38pm	Victor informed C/A via Merrimen.
16/7/19 @ 10:40am	Informed Tong Luck C/A to EX: \$1500 by email.
	Kenneth finalised final fig \$7159.50 (Red \$4649.50, 39%.)

ASS. REC. BY:

REF: AIG / CS / AIG 19012347 / K9d3Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8330k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMI-1824Yr Regn: 08, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: MercedesColour: M.R. BlackSp. Reading: 40204

Eng/No: _____

C/No: WDC 1668562B137766Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / RIM or

Tyre Size: F: _____

R: 295/40ZR21BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 10/7/19

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 12/7/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 23 AUG 2019

Date/Time, File Pass to?

1) 23/8 14:15

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ - RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 7199.5020011211

- Estimated cost of repair for repairing of vehicle no.: SMF182Y - Own Da...

From: AIG SGP, Claims-Survey

To:

Cc:

Sent: 7/12/2019 11:01:10 AM

Attachments:  SMF182Y - Estimate.pdf

Hi LKK,

Kindly assist to survey.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Operation / Yu Ching [mailto:operation@tlauto.com.sg]

Sent: Friday, July 12, 2019 10:55 AM

To: AIG SGP, Claims-Survey

Cc: Chin, Lee-Ying

Subject: [EXTERNAL] Estimated cost of repair for repairing of vehicle no.: SMF182Y - Own Damaged Claim

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop

Kindly arrange your surveyor to inspect the vehicle at an earlier date

Thanks & regards,

Yu Ching



Tong Luck Auto Pte Ltd

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 16 July 2019 10:40 AM
To: tlauto@singnet.com.sg
Cc: SUR
Subject: OD VEHICLE SMF 182Y (DOA: 10/07/2019)

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **SMF 182Y (Excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	10 Jul 2019 16:46	Clim Veh Model Changed		[] Merimen Administrator
2	10 Jul 2019 16:46	Clim Created	Reg No: SMF182Y, Policy No: 999995580, Acct Date: 2019/07/10, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MBHH19089957	[I] Merimen Administrator
3	12 Jul 2019 12:56	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] Nivitha Govindasamy
4	12 Jul 2019 12:56	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Nivitha Govindasamy
5	12 Jul 2019 12:56	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
6	12 Jul 2019 12:56	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/23	[A] Nivitha Govindasamy
7	12 Jul 2019 12:56	Adj Mandate Set	Approved:8000.00.ReInsp:Adj decides.	[A] Nivitha Govindasamy
8	12 Jul 2019 12:56	Clim Registration Modified	Rep:1137->200237.	[A] Nivitha Govindasamy
9	12 Jul 2019 12:56	Clim Veh Model Changed	(206312) MERCEDES-BENZ GLS400 3.0 4MATIC (R21 LED SR) (A).	[A] Nivitha Govindasamy
10	12 Jul 2019 12:56	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Nivitha Govindasamy
11	12 Jul 2019 15:17	Adj Rpt Initiated		[A] SHIAU CHAN
12	12 Jul 2019 15:17	Clim Dtl Modified	JPJ Reg, Date: -> 2018/08/17.	[A] SHIAU CHAN
13	12 Jul 2019 15:17	Clim Details Notified		[A] SHIAU CHAN
14	12 Jul 2019 15:20	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/07/23	[A] SHIAU CHAN
15	12 Jul 2019 15:25	Adj Mandate Request	Cur.Reg:6164.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	15 Jul 2019 14:20	Clim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 1500.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Nadaraja, Deeban
17	15 Jul 2019 14:20	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
18	15 Jul 2019 14:38	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/23. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
19	15 Jul 2019 14:38	Adj Mandate Set	Approved:6164.50:Re-inspection to be done for damage check and supplementary items / labour. ReInsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2210355	12/07/2019 15:17	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMF182Y		11.77

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 12 Jul 2019

Preliminary Advice

Vehicle No	: SMF182Y	Accident Date	: 10/07/2019
Make	: MERCEDES-BENZ GLS400	Policy No.	: 999995580
Assignment Date	: 12/07/2019	Excess	: S\$0.00
Date of Inspection	: 12/07/2019	Est. Duration of Repair	: 4.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,731.00
Revised Amount	:S\$	6,021.50
Check Items (Estimated)	:S\$	143.00
Total	:S\$	6,164.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	330,000.00
COE / PARF Rebate	:S\$	139,486.00
Salvage Value	:S\$	
Margin for Repair	:S\$	190,514.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3778Z
Vehicle Details	
Vehicle No.:	SMF182Y
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jul 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLS400 4MATIC (R21 LED SR)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	27682130848460
Chassis No.:	WDC1668562B137766
Maximum Power Output:	245.0 kW (328 bhp)
Open Market Value:	\$92,607.00
Original Registration Date:	17 Aug 2018
First Registration Date:	17 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$138,693.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Aug 2028
PARF Rebate Amount:	\$104,019.00
Intended COE Rebate Details	
COE Expiry Date:	16 Aug 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,001.00
COE Rebate Amount:	\$35,467.00
Total Rebate Amount:	\$139,486.00

The information contained herein is correct as at 12 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/07/2019 11:15
Date Of Accident	10/07/2019 07:20
Exact Location Of Accident	EAST COAST RD SHELL STATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF182Y
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	OSMAN.AFFAN@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-98385314

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	GLS400 4MATIC (R21 LED SR)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	NA

Driver

Name of Driver	MOHAMMAD ZAIREEN BIN ABDUL HALIM
NRIC No	S8039076I
Date Of Birth	14/12/1980
Occupation	OUTDOOR
Date Of Driving Pass	11/12/2007
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98385314
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Making a left turn to Shell station. While turning, accidentally brushed onto the metal pole. The pole was still intact, only the paint a bit chip.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	METAL POLE
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

Making a left turn to SHELL STATION. While turning, accidentally brushed onto the metal pole. The pole was still intact, only the paint a bit chip.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time


10 July 2019 at 10:00 AM

Date/Time:

10 July 2019 at 10:00 AM

Identification Card

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S80390761





Name
MOHAMAD ZAIREEN BIN
ABDUL HALIM
محمد زيرين بن عبدالحليم

Race
MALAY

Date of birth
14-12-1980

Sex
M

Country of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S80390761

Name:
MOHAMAD ZAIREEN BIN ABDUL
HALIM

Birth Date: 14 Dec 1980

Issue Date: 04 Jan 2016



002515227A



Identification Card



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$	11 Dec 2007

NP 428A



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH19089957 Vehicle Registration No: SMF182Y
Name (as shown in NRIC) : MOHAMMAD ZAIREEN BIN ABDUL HALIM NRIC/FIN/Passport No : S8039076I
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : Singapore()
Contact (Tel) : Mobile No. : 98385314
Email Address :
Date of Accident : 10/07/2019 Time of Accident : 07:20 HRS
Place of Accident : EAST COAST RD SHELL STATION
Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMEND TO OD CLAIM.

Policyholder / Driver's Signature
Date:

Elizabeth
Reporting Centre Personnel's Signature
Name: Elizabeth
NRIC/FIN No.:
Date: 12/07/2019

**CERTIFICATE OF INSURANCE**

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M Z 400

COMPREHENSIVE COMMERCIAL MOTOR
CERTIFICATE NO. 999994155/100864460-00000

OWN DAMAGE EXCESS S\$1,500.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)
SUM INSURED S\$1.00
INSURING WITH COE/PARF YES

- 1) **VEHICLE REGISTRATION NO.** SMF182Y
2) **NAME OF INSURED** Daimler Fleet Management Singapore Pte Ltd
3) **EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT** 1 Jan 2019
4) **DATE OF EXPIRY OF INSURANCE** 31 Dec 2019
5) **PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE ***

- 1) Any drivers who is driving on the Insured's order or with their permission.
2) Excess \$2,500 applies to drivers age 21 to 26 years old unless otherwise specified
3) Additional Excess \$3,500 applies to drivers age below 21 or above 65 years old and or less than years driving experience unless otherwise specified

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

1) Use for social, domestic, pleasure purposes and business purposes of the Insured and or hirer whom the vehicle is hired to.

The Policy does not cover:

- 1) Use for the carriage of passengers for hire or reward
2) Use for driving tuition, driving test, racing, pace-making, reliability trial or speed-testing. 3) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
4) Use for any purpose in connection with the Motor Trade.

In the event of accident claim, the repairs to the Vehicle must be carried out by either one of our AIG Authorized Repairers or a particular Repairer approved by AIG

LOSS OF USE NOT INCLUDED

*** NAMED DRIVER** N/A

HIRE PURCHASE COMPANY NA

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 12 Apr 2019

AIG ASIA PACIFIC INSURANCE PTE. LTD.

030023-000
JARDINE LLOYD THOMPSON PTE LTD
138 MARKET STREET
#07-01 CAPITAGREEN
SINGAPORE 048946


Authorized Representative

ORIGINAL

SSCDSK



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 10/07/2019

ESTIMATE

NO : QUOT201907-000041(00)

DATE : 11/07/2019

POLICY NO : 999994155

VEH REG NO : SMF182Y

MAKE/MODEL : MERCEDES BENZ GLS400
4MATIC (R21LED SR)

CHASSIS NO : WDC1668562B137766

ENGINE NO : 27682130848460

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMF182Y

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
PARTS			
1 Front door - LH	1	2,400.00	2,400.00
2 Front door weatherstrip - LH	1	185.00	185.00
3 Front door trimboard rivets - LH	20	6.50	130.00
4 Rear door - LH	1	2,600.00	2,600.00
5 Rear door weatherstrip - LH	1	185.00	185.00
6 Rear door trimboard rivets - LH	20	6.50	130.00
7 Stepboard garnish - LH	1	1,350.00	1,350.00
8 Stepboard garnish chrome - LH	1	350.00	350.00
9 Stepboard garnish clips - LH	8	10.00	80.00
			7,410.00
		Add 10%	741.00
			8,151.00
LABOUR			
10 To transfer LH front & rear damaged door interior mechanism and glass to new door	1	300.00	300.00
11 To check and rectify wiring system	1	80.00	80.00
12 To panel beat and straighten LH centre door pillar including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
13 To putty and spray same on affected areas	1	1,200.00	1,200.00
			2,580.00
		TOTAL	S\$ 10,731.00
		ADD GST @ 7%	751.17
		GRAND TOTAL	S\$ 11,482.17

SINGAPORE DOLLAR ELEVEN THOUSAND FOUR HUNDRED EIGHTY-TWO AND CENTS SEVENTEEN ONLY

Not Withheld
Repair by paint
Ex TBA

Body

62564315

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 10/07/2019

ESTIMATE

NO : QUOT201907-000041(00)

DATE : 11/07/2019

POLICY NO : 999994155

VEH REG NO : SMF182Y

MAKE/MODEL : MERCEDES BENZ GLS400
4MATIC (R21 LED SR)

CHASSIS NO : WDC1668562B137766

ENGINE NO : 27682130848460

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMF182Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Front door - LH	1	2,400.00	2,400.00
2 Front door weatherstrip - LH	1	185.00	185.00
3 Front door trimboard rivets - LH	20	6.50	130.00
4 Rear door - LH	1	2,600.00	2,600.00
5 Rear door weatherstrip - LH	1	185.00	185.00
6 Rear door trimboard rivets - LH necessary	20	6.50	130.00
7 Stepboard garnish - LH	1	1,350.00	1,350.00
8 Stepboard garnish chrome - LH	1	350.00	350.00
9 Stepboard garnish clips - LH	8	10.00	80.00
10 Stepboard carrier - LH			7,410.00
		Add 10%	741.00
			8,151.00
LABOUR			
10 To transfer LH front & rear damaged door interior mechanism and glass to new door	1	300.00	300.00
11 To check and rectify wiring system	1	80.00	80.00
12 To panel beat and straighten LH centre door pillar including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
13 To putty and spray same on affected areas	1	1,200.00	1,200.00
			2,580.00
		TOTAL	S\$ 10,731.00
		ADD GST @ 7%	751.17
		GRAND TOTAL	S\$ 11,482.17

SINGAPORE DOLLAR ELEVEN THOUSAND FOUR HUNDRED EIGHTY-TWO AND CENTS SEVENTEEN ONLY

Not to be used

Repair by paint

Ex TBA



NLS Body

Fax: 62564315

FOR TONG LUCK AUTO PTE LTD

Unking

AUTHORISED SIGNATURE

TAX INVOICE

INVOICE NO. **8154185**

DATE	13/07/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	SMF182Y	OUR REF.	47119

GST REG.NO.: M2-0090482-6 CO REG.NO.: 198905613E

ACCOUNT NUMBER: TONG LUCK1 TIME: 09:27

TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

575722

Telephone No: 62500088

ROUTE
SM1

DELIVER TO:

TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA166 730 03 05	REAR DOOR	3C-02A	1 PC	2,600.00	2,600.00
2 MBA166 690 00 75	STEP	3C-1C	1 PC	1,350.00	1,350.00
3 MBA166 690 05 75	STEP INSERT		1 PC	350.00	350.00
4 MBA204 727 11 87	W204 FR & RR DOOR RH & LH WEATHE	1D-02E	1 PC	185.00	185.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.

Exclusive Distributor

HDK

Stockists



Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046

Account No.: 503-309-511-3
*Please send a screen shot of your payment/transfer confirmation to account@minghee.com

TOTAL SIN 4,485.00

ADD GST 7% 313.95

AMOUNT DUE SIN 4,798.95

SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



明義純車私人有限公司
MIN GHEE AUTO PTE LTD

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

TAX INVOICE

INVOICE NO. 8155074

DATE	20/07/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	SMF182Y	OUR REF.	56027

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: TONGLUC1 TIME: 10:39
TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722
Telephone No: 62500088

ROUTE
SM1

DELIVER TO:

TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA166 690 00 10	BEAM		1 PC	980.00	980.00
2 MBA000 995 03 83	CONNECTOR HOLDER		8 PCS	10.00	80.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE

Exclusive Distributor



Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046

Account No.: 503-309-511-3
*Please send a screen shot of your payment/
transfer confirmation to
account@minghee.com

TOTAL SIN 1,060.00

ADD GST 7% 74.20

AMOUNT DUE SIN 1,134.20

SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.



For MIN GHEE AUTO PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2019		12 Jul 2019 12:56 Edit Adj Rpt	S\$7,159.50 Edit Estimates	S\$7,159.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z								
Vehicle Reg. No.:	SMF182Y	Date of Loss:	10/07/2019 07:00 - :59 [10 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 3373947805SG	Policy/Cover Note No.:	999995580 (Comprehensive)						
		Excess:	S\$1,500.00						
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban@nadaraja.Nadaraja@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/07/2019]								
Driver/Custodian:	MOHAMMAD ZAIREEN BIN ABDUL HALIM (38 / Male) , NRIC: S80390761, Tel: +6598385314 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (15/07/2019): Alert - Adj Mandate Approved (S\$6164.50) - SMF182Y - Claim Handler: Nadaraja, De... AIG_SG (15/07/2019): SMF182Y / OD / 10/07/2019 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMF182Y (3373947805SG)
OD

Jul 10 2019 7:20AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]
Tong Luck Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	12/07/19 15:20	Adjuster Immediate Advice												1	Load HTM			
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
2	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
3	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
4	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
5	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
6	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
7	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
8	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
9	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
10	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
11	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
12	15/07/19 13:55	Odometer Reading												1	Load JPG	<input checked="" type="checkbox"/>		
13	15/07/19 13:55	General View												1	Load JPG	<input checked="" type="checkbox"/>		
14	15/07/19 13:55	Chassis Number												1	Load JPG	<input checked="" type="checkbox"/>		
15	23/08/19 11:38	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>		
16	23/08/19 11:38	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>		
17	23/08/19 11:38	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>		
18	23/08/19 11:38	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>		
19	23/08/19 11:38	Reinspection Photo												1	Load JPG	<input checked="" type="checkbox"/>		
Documentation															1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	12/07/19 15:23	ESTIMATE												1	Load PDF			
2	18/07/19 10:44	UNDERTAKING & INTERVIEW FORM												1	Load PDF			
3	26/08/19 15:00	Parts Invoice												1	Load PDF			

Linked Accident Report Documents

View

View in Browser

Assessment Reports					
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	10/07/19 16:46	Accident Statement		Load HTM	
2	12/07/19 10:02	Addendum Sheet		Load TIFF	
3	12/07/19 10:03	Accident Statement Addm. #1		Load HTM	
Photos/Images					
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail Print
1	10/07/19 12:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	10/07/19 12:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	10/07/19 12:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	10/07/19 12:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	10/07/19 12:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	10/07/19 12:51	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	10/07/19 12:51	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	10/07/19 12:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	10/07/19 12:52	Identification Card		Load JPG <input checked="" type="checkbox"/>
10	10/07/19 12:52	Identification Card		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail Print
1	10/07/19 12:49	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	10/07/19 12:56	Common Statement		Load TIF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19012342/KQD3E2

Date: 26/08/2019

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Policy No: 999995580
Date of Loss: 10/07/2019 Nature of Claim: OD Claim No: 3373947805SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF182Y**
Make & Model: MERCEDES-BENZ GLS400, 3.0 4MATIC (R21 LED SR) (A) Engine No: 27682130848460
Reg. Date: 17/08/2018 (Man. Year: 2018) Chassis No: WDC1668562B137766
Colour: Metallic Dark Blue Odometer: 40204 km
Engine Capacity: 2996 cc
Market Value/New Car Price: S\$330,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/40Z R21 Rear Tyre Size: 295/40Z R21
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,229.00	6,159.50	3,069.50	33.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,000.00	1,580.00	61.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,809.00	7,159.50	4,649.50	39.37
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	10,309.00	5,659.50	4,649.50	45.10
+ GST 7.00/7.00% (S\$)	721.63	396.17	325.46	45.10
Nett Amount (S\$)	11,030.63	6,055.67	4,974.96	45.10

INSPECTION

Date of Assignment: 12/07/2019

Date Inspected: 12/07/2019 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 SIN MING DRIVE #07-01/06
SIN MING AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH (WCP)	Repair	2,400.00 F	*- F
2	1		*FRONT DOOR WEATHERSTRIP - LH (WCP)	Serviceable	185.00 F	*- F
3	20		*FRONT DOOR TRIMBOARD RIVETS - LH (WCP)	Not Necessary	130.00 F	*- F
4	1		*REAR DOOR - LH (WCP)	Bent	2,600.00 F	*2,600.00 F
5	1		*REAR DOOR WEATHERSTRIP - LH (WCP)	Necessary	185.00 F	*185.00 F
6	20		*REAR DOOR TRIMBOARD RIVETS - LH	Necessary	143.00 FS	*60.00 FS
7	1		*STEPBOARD GARNISH - LH (WCP)	Cracked	1,350.00 F	*1,350.00 F
8	1		*STEPBOARD GARNISH CHROME - LH (WCP)	Bent	350.00 F	*350.00 F
9	8		*STEPBOARD GARNISH CLIPS - LH (WCP)	Necessary	80.00 F	*80.00 F
10	1		*STEPBOARD CARRIER - LH (WCP)	Cracked	980.00 F	*980.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	8,403.00	5,605.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	826.00	554.50

Total Parts (\$\$)	9,229.00	6,159.50
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER LH FRONT & REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	300.00	80.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN LH CENTRE DOOR PILLAR INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	500.00
4	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS	New	1,200.00	400.00
Gross Labour Cost (S\$)			2,580.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >