



凱摩多服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 11/07/2019

Attn: The Motor Claims Department

Your Insured veh no : SCF 3228 Z

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way

07-16 Chartis Building

Singapore 079120

WITHOUT PREJUDICE

(By Email Only)

Dear Sir / Madam

Estimate Cost repair Bill To NISSAN LATIO SJU 1120 B & SCF 3228 Z on 10/07/2019.

To Supply :-

1pc	Rear boot Cover <i>Dented</i>	\$ 787.50	nett	✓
2pcs	Rear boot cover hinge <i>new</i> 88.00 x 2pcs	\$ 176.00	nett	✓
1pc	Rear boot cover rubber <i>at</i>	\$ 88.40	nett	✓
1pc	Rear boot cover Top Chrome <i>new</i>	\$ 297.70	nett	+
1pc	Rear Bumper <i>Distorted</i>	\$ 532.40	nett	✓
10pcs	Rear bumper clips <i>new</i> 5.00 x 10pcs	\$ 50.00	nett	30
1pc	Rear bumper bracket <i>new</i> 50.40 x 2pcs	\$ 100.80	nett	+
1pc	Rear Bumper Side Retainer <i>new</i> 36.00 x 2pcs	\$ 72.00	nett	✓
1pc	Rear Sponge <i>new</i>	\$ 40.50	nett	+
2pcs	Rear lamp LH & RH <i>RH could</i> 279.00 x 2pcs	\$ 558.00	nett	278
2pcs	Rear Lamp Clips <i>new</i> 7.70 x 2pcs	\$ 15.40	nett	✓
1pc	Rear Exhaust Box <i>new</i>	\$ 480.00	nett	+
1pc	Rear Exhaust Rubber <i>new</i>	\$ 16.00	nett	+
		\$ 3,214.70		

1pc Rear reverse sersor *Damaged* *200* \$ 350.00 *s/nett* *200 (sw)*

To dismanlte & replace damage parts, panel beat where

necessaev. Consultants hence notify

To putty apply primer & spray paint on the affecte portion.

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

To check wiring functions

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

To remove reverse sensor
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 800.00 *600*

\$ 880.00 *800*

\$ 80.00 *30*

\$ 60.00 *40*

\$ 5,384.70

Supplementary: 1146.42

total: 4477.10

L/S : 3550

Adrian hij
L/S 11/07/19
06 Days



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 12/07/2019

Attn: The Motor Claims Department

Your Insured veh no : SCF 3228 Z

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way

07-16 Chartis Building

Singapore 079120

WITHOUT PREJUDICE

(By Email Only)

Dear Sir / Madam

Estimate Cost repair Bill To NISSAN LATIO SJU 1120 B & SCF 3228 Z on 10/07/2019.

Supplementary Items

To Supply :-

1pc	Rear Panel <i>Painted</i>	\$ 476.60	nett ✓
1pc	Rear lamp Panel <i>Repis</i>	\$ 168.60	nett ✗
1pc	Rear Boot "Nissan" Logo <i>2</i>	\$ 45.60	nett ✓
1pc	Rear Boot "Latio" Logo <i>1pc</i>	\$ 68.60	nett ✓
1pc	Rear Panel Inner Garnish <i>could</i>	\$ 73.00	nett ✓
1pc	Rear Spare Tyre Top Cover <i>Deland</i>	\$ 495.00	nett ✓
1pc	Rear Boot Cover Lock <i>Donc</i>	\$ 115.00	nett ✓
1pc	Rear Number Plate <i>new</i>	\$ 55.00	s/nett ✗
		\$ 1,497.40	

Adrian Lj
12/07/19.

Supplementary : 1273.80
1146.42