

22/03/2002

ASS. REC. BY:

REF: CS/SMO19012347/RTF301 Special Instruction:

Supervisor: RASUASSIGNMENT (Office)From (Person): Gnoh Pan Loong of SMO Date/Time: 12/7/2019.

Estimated Cost: _____ Bill to: _____

① OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLG 2627A Insured: _____at Workshop m/s Hitachi Capital Asia Pacific Tel: 64663022of NO. 8 Fourth Lok Yang Road, Singapore 629705Policy No: D18MTRENT000661 Claim No: CMTD1903347Sum Insured: _____ Excess: \$750Make of Veh: _____ D.O.A. 9/7/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
15/7/2019 @ 15:09	Revert via menimen
15/7 @ 17:20	mandate approval by Gnoh Pan Loong
16/7 @ 9:55am	Inform workshop via email proceed repair excess \$750

ASSIGNMENT

From

Date:

Estimated Cost:

☒ OB / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLG 2627Aat Workshop m/s: HITACHI CAPRONof Pouant Lokyanh RDInsured: Smo

Policy No.

Claims No.

Sum Insured:

Excess:

750

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

82K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG 2627AYr Regn: 2016 / SEPType: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic 1-6 VTI c.c. 1597

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

041998

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRHF256506T000212Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

215/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

02/07/19

D.O.I.

12/07/19

Survey held at

HITACHI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Part by Part \$1987. 3 days. (Red: 2842.50; 58%)

RECEIVED 06 AUG 2019

Date/Time, File Pass to?

1) 618 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.T. : \$ 1987

OD

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

25011261

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 15 Jul 2019

Preliminary Advice

Vehicle No	: SLG2627A	Accident Date	: 09/07/2019
Make	: HONDA CIVIC	Policy No.	: D18MTRENT000661
Assignment Date	: 12/07/2019	Excess	: S\$750.00
Date of Inspection	: 12/07/2019	Est. Duration of Repair	: 3.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages from n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,288.50
Revised Amount	:S\$	2,295.50
Check Items (Estimated)	:S\$	0.00
		2,295.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	48,433.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,567.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :2 items pending for part price, repair on part by part.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2019	12 Jul 2019	12 Jul 2019		Last:IA 15 Jul 2019 14:56		Pending for Survey Report Cancel Case
	Sendback Est	10:53 S\$4,829.50	13:17 Edit Adj Rpt				
Supp #1	12 Jul 2019 17:49	12 Jul 2019 17:58 S\$459.00	12 Jul 2019 17:58			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Vehicle Reg. No.:	SLG2627A	Date of Loss:	09/07/2019 13:00 - :59 [33 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1903347	Policy/Cover Note No.:	D18MTRENT000661 (Comprehensive)
		Excess:	S\$750.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/07/2019]		
Driver/Custodian:	MORITA KEN (48 / Male) , NRIC: G3237071W, Tel: +6596360458 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 16 July 2019 9:55 AM
To: JiongHow, Ng; SUR
Cc: Vonn, LM Siow; Jamilah, Binte MohdKassim
Subject: RE: SLG2627A OD CLAIM DOA: 09/07/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLG2627A (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Monday, 15 July 2019 10:43 AM
To: JiongHow, Ng <jionghow.ng@hcspl.com.sg>; SUR <sur@lkkauto.com>
Cc: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Subject: RE: SLG2627A OD CLAIM DOA: 09/07/2019

Dear Jiong How,

Please call Rasul at 90010068, urgent

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Sent: Monday, 15 July 2019 10:11 AM
To: SUR <sur@lkkauto.com>

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 6 August 2019 9:19 AM
To: Admin-D (LKKAUTO); 'Chong Boon Sen'; assignments; Claims Dept of CTI
Cc: SUR
Subject: RE: OUR REF: SNM19D203486/TAYHP - FW: Accident involving GX4621Y & GX3154K on 12.06.2019 O ref: JEQ/190726/0719/IMP (zl)

Dear All,

Anybody can help to create? Boon Sen is not around.

IMPERIUM AUTOMOTIVE
25 Kaki Bukit Road 4 #01-49,
Synergy@KB
Singapore 417800

Make and model: Nissan p/up lowbed

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Monday, 5 August 2019 2:02 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; 'Chong Boon Sen' <boonsen.chong@sg.cntaiping.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OUR REF: SNM19D203486/TAYHP - FW: Accident involving GX4621Y & GX3154K on 12.06.2019 O ref: JEQ/190726/0719/IMP (zl)

Dear Boon Sen,

Please Create merimen

IMPERIUM AUTOMOTIVE
25 Kaki Bukit Road 4 #01-49,
Synergy@KB
Singapore 417800

Make and model: Nissan p/up lowbed

View Received Message

This mail is associated with :
SLG2627A (CMTD1903347)
OD
Jul 9 2019 1:00PM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Hitachi Capital Asia Pacific Pte. Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 15/07/2019 17:20 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2295.50) - SLG2627A - Claim Handler: GNOH PAU LOONG

Approved:2295.50.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0399N
Vehicle Details	
Vehicle No.:	SLG2627A
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	R16B21600315
Chassis No.:	MRHFC5650GT000212
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,474.00
Original Registration Date:	26 Sep 2016
First Registration Date:	26 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$19,474.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Sep 2026
PARF Rebate Amount:	\$14,605.00
Intended COE Rebate Details	
COE Expiry Date:	25 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$33,828.00
Total Rebate Amount:	\$48,433.00

The information contained herein is correct as at 15 Jul 2019

OK

82,000
48,433

33,567

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/07/2019 17:37
Date Of Accident	09/07/2019 13:00
Exact Location Of Accident	AYE TWDS TUAS NEAR NORMAN PARK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG2627A
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64663022

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 VTI CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTRENT000661
Cover Note Number	

Driver

Name of Driver	MORITA KEN
Passport No/FIN	G3237071W
Date Of Birth	25/09/1970
Occupation	INDOOR
Date Of Driving Pass	15/06/2016
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96360458
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHMENT

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	STONE
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, SLG2627A was driving on AYE towards Tuas near Norman Park Exit. I found something (like tree) in my front but couldn't turn to next lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

HITACHI
 Inspire the Next

 INSURER: **Sompo Insurance Singapore Pte. Ltd. (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MTRENT000661	Date of Loss:	09/07/2019
Vehicle Reg. No.:	SLG2627A	Driveable?	
Driver Age/Info:	48 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD		
Driver:	MORITA KEN		
Make/Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Vehicle Reg. Date:	26/09/2016
Vehicle Colour:	SILVER		
Engine No:	R16B21600315	Chassis No:	MRHFC5650GT000212
Odometer:	50000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS	Amount
Parts	2,249.50
Miscellaneous Items	0.00
Labour	2,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,889.50
+ GST 7.00% (\$\$)	338.07
Nett Amount (\$\$)	5,167.57

 This claim is handled by: **NG JIONG HOW**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jul 2019)

Parts: 143 HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 10:53

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bumper <i>set X repair</i>	0.00	0.00	*270.00 F
2	10		*Front Bumper Clips <i>nu</i>	0.00	0.00	*20.00 F ✓
3	2		*Front Bumper Outer Bracket LH/RH <i>X suc</i>	0.00	0.00	*20.00 F
4	1		*Front Engine Undercover <i>MIS</i>	0.00	0.00	*170.00 F ✓
5	10		*Front Engine Undercover Clips <i>nu</i>	0.00	0.00	*20.00 F ✓
6	1		*Front Engine Undercover Lip <i>at</i>	0.00	0.00	*20.00 F ✓
7	10		*Front Engine Undercover Lip Clips <i>nu X nn</i>	0.00	0.00	*20.00 F
8	1		*Fog Lamp Cover LH <i>X nn</i>	0.00	0.00	*20.00 F
9	1		*Front Centre Grille Base <i>X nn</i>	0.00	0.00	*65.00 F
10	1		*Front Centre Grille Outer Chrome <i>X old damage nn</i>	0.00	0.00	*70.00 F
11	1		*Front H Logo <i>X</i>	0.00	0.00	*20.00 F
12	1		*Headlamp LH <i>X</i>	0.00	0.00	*420.00 F
13	1		*Headlamp Lower Bracket LH <i>X } nn</i>	0.00	0.00	*25.00 F
14	1		*Front Fender Shield LH <i>set X suc</i>	0.00	0.00	*45.00 F
15	10		*Front Fender Shield LH Clips <i>nu</i>	0.00	0.00	*20.00 F ✓
16	1		*Front Crossmember <i>bt</i>	0.00	0.00	*820.00 F ✓

F=Franchise part.

Sub Total (\$\$)	2,045.00
+ Margin on L,N Items 10.00% (\$\$)	204.50
Total Parts (\$\$)	2,249.50

Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 10:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Remove, repair & replace parts for affected areas	New	800 250 1,000.00
2	Spray paint on the affected areas	New	250 250 1,000.00
3	Check wiring, re-align headlamp & ensure proper functioning	New	120 80.00
4	Remove & Replace Front Undercarriage & Subframe	New	250 500.00
Gross Labour Cost (S\$)			2,580.00

Hitachi Capital Asia Pacific Pte. Ltd./SLG2627A/12/07/2019 10:53. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >


© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835

www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591


 15/7/19
 Rasul

Hp 90010068

4 3 days
 P/P

12/07/19 @ 1620

EXCESS: 750

R retur

Recovery before paint

(SUPPLEMENTARY)

INSURER: **Sompo Insurance Singapore Pte. Ltd. (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MTRENT000661	Date of Loss:	09/07/2019
Vehicle Reg. No.:	SLG2627A	Driveable?	
Driver Age/Info:	48 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD		
Driver:	MORITA KEN		
Make/Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Vehicle Reg. Date:	26/09/2016
Vehicle Colour:	SILVER		
Engine No:	R16B21600315	Chassis No:	MRHFC5650GT000212
Odometer:	50000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	209.00
Miscellaneous Items	0.00
Labour	250.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	459.00
+ GST 7.00% (S\$)	32.13
Nett Amount (S\$)	491.13
+ Previous Estimates (S\$)	5,167.57
Claim Total (S\$)	5,658.70

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2019)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 17:58	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Engine Floor Panel Undercover LH/RH 2H=cut X SVC	0.00	0.00	*150.00 F
2	20		*Engine Floor Panel Undercover LH/RH Clips not X SVC	0.00	0.00	*40.00 F
3	1		*Rear Exhaust & Pipe X 27	0.00	0.00	*-F
4	1		*Rear Exhaust Gasket X 27	0.00	0.00	*-F
5	1		*Mud Flap RH set X SVC	0.00	0.00	? *-F
6	5		*Mud Flap Clips not X SVC	0.00	0.00	? *-F

F=Franchise part.

Sub Total (S\$)	190.00
+ Margin on L,N Items 10.00% (S\$)	19.00
Total Parts (S\$)	209.00

Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 17:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Check, Re-adjust and computerise wheel alignment / side slip test	New	250.00 60
Gross Labour Cost (S\$)			250.00

Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 17:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised 12 Jul 2019)
 Parts: 143 HONDA CIVIC 1.6 VTI CVT (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 10:53
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bumper <i>SL</i>	0.00	0.00	*270.00 F
2	10		*Front Bumper Clips <i>SL</i>	0.00	0.00	*20.00 F
3	2		*Front Bumper Outer Bracket LH/RH <i>X</i>	0.00	0.00	*20.00 F
4	1		*Front Engine Undercover <i>M (1)</i>	0.00	0.00	*170.00 F
5	10		*Front Engine Undercover Clips <i>SL</i>	0.00	0.00	*20.00 F
6	1		*Front Engine Undercover Lip <i>SL</i>	0.00	0.00	*20.00 F
7	10		*Front Engine Undercover Lip Clips <i>SL X</i>	0.00	0.00	*20.00 F
8	1		*Fog Lamp Cover LH <i>X</i>	0.00	0.00	*20.00 F
9	1		*Front Centre Grille Base <i>X</i>	0.00	0.00	*65.00 F
10	1		*Front Centre Grille Outer Chrome <i>X old damage</i>	0.00	0.00	*70.00 F
11	1		*Front H Logo <i>X</i>	0.00	0.00	*20.00 F
12	1		*Headlamp LH <i>X</i>	0.00	0.00	*420.00 F
13	1		*Headlamp Lower Bracket LH <i>X</i>	0.00	0.00	*25.00 F
14	1		*Front Fender Shield LH <i>SL</i>	0.00	0.00	*45.00 F
15	10		*Front Fender Shield LH Clips <i>SL</i>	0.00	0.00	*20.00 F
16	1		*Front Crossmember <i>SL</i>	0.00	0.00	*820.00 F

F=Franchise part

Sub Total (S\$) 2,045.00
 + Margin on L,N Items 10.00% (S\$) 204.50
 Total Parts (S\$) 2,249.50

Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 10:53. Not valid without Reference section
 Generated using Merimen e-Claims IEAS

Parts - \$1070.00
 +10% - \$ 107.00
\$ 1177.00

labour - \$ 810.00

Total - \$1987.00

Estimates on Miscellaneous Items

There are no new miscellaneous items selected

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			250
1	Remove, repair & replace parts for affected areas	New	500 1,000.00
2	Spray paint on the affected areas	New	250 1,000.00
3	Check wiring, re-align headlamp & ensure proper functioning	New	X 80.00
4	Remove & Replace Front Undercarriage & Subframe	New	250 500.00
Gross Labour Cost (S\$)			2,580.00

Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 10:53. Not valid without Reference section
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax: 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

Resul

Ap 900/100/68

3 days

P/P

12/07/19 @1620

EXCESS: 750

REPAIR

Recovery before paint

(SUPPLEMENTARY)

INSURER: Somp Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MTRENT000661	Date of Loss:	09/07/2019
Vehicle Reg. No.:	SLG2627A	Driveable?	
Driver Age/Info:	48 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD		
Driver:	MORITA KEN		
Make/Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Vehicle Reg. Date:	26/09/2016
Vehicle Colour:	SILVER		
Engine No:	R16B21600315	Chassis No:	MRHFC5650GT000212
Odometer:	50000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO ATTACHMENT		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	209.00
Miscellaneous Items	0.00
Labour	250.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	459.00
+ GST 7.00% (S\$)	32.13
Nett Amount (S\$)	491.13
+ Previous Estimates (S\$)	5,167.57
Claim Total (S\$)	5,658.70

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jul 2019)
 Parts: 143 HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 17:58
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Engine Floor Panel Undercover LH RH <i>LH - cut</i>	0.00	0.00	*150.00 F
2	20		*Engine Floor Panel Undercover LH RH Clips <i>Clips</i>	0.00	0.00	*40.00 F
3	1		*Rear Exhaust & Pipe <i>X</i>	0.00	0.00	*-F
4	1		*Rear Exhaust Gasket <i>X</i>	0.00	0.00	*-F
5	1		*Mud Flap RH <i>Scd</i>	0.00	0.00	*-F
6	5		*Mud Flap Clips <i>Scd</i>	0.00	0.00	*-F
Sub Total (S\$)						190.00
+ Margin on L,N Items 10.00% (S\$)						19.00
Total Parts (S\$)						209.00

F=Franchise part

Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 17:58. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Check, Re-adjust and computerise wheel alignment / side slip test	New	60 250.00
Gross Labour Cost (S\$)			250.00

Hitachi Capital Asia Pacific Pte. Ltd/SLG2627A/12/07/2019 17:58. Not valid without Reference section.
Generated using Meriman e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591



HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

TO: HITACHI CAPITAL ASIA PACIFIC PTE.LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

CIVIC

MR HOW

NO: HL19063343

PAGE: 1

DATE: 16/07/2019

A/C CODE: LDHC008

TERMS: CR

VEH NO: SLG2627A-

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
✓H91505-TM8-003	✓CLIP BUMPER	HDS	10	2.00	20.00
✓H74110-TEA-T00	FR.ENG UNDERCOVER	HU3-53	1	170.00	170.00
✓H74113-TEA-T00	UNDERCOVER LID	H2/2	1	20.00	20.00
✓H91501-TR0-003	✓CLIP COWLING	HDS	10	2.00	20.00
✓H50200-TEA-T01	FR.SUB FRAME(T02)	HU3-12	1	820.00	820.00
✓H91505-TM8-003	✓CLIP FRONT UNDER COVER	HDS	10	2.00	20.00
TOTAL QUANTITY:			33	TOTAL	SIN 1,070.00
				ADD GST @ 7%	74.90
				GRAND TOTAL	<u>SIN 1,144.90</u>

/R:
R WENG

Print / LSK / 16/7/2019 2:47:28 PM

LES MAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E & O.E.

GOODS RECEIVED BY





Stamford Tyres Int'l Pte Ltd
19 LOK YANG WAY, JURONG S628635
JURONG MEGAMART
PH:6262 3355, FAX:62621494

FCB Reg. No.: 198904415C
GST Reg. No.: M2-0088778-6
feedback@stamfordtyres.com

TAX INVOICE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
4 FOURTH LOK YANG ROAD
SINGAPORE 629705

DATE : 18/07/19 17:57:24 CAR NO.: SLG2627A
INVOICE NO : 315447/21 W/O D/O : 19004271/G1

MILEAGE/CAR : 42008km/Honda Civic
CUST PO : HITACHI CAPITAL ASIA PACIF

PRODUCT CODE	DESCRIPTION OF GOODS	QUANTITY	PRICE	AMOUNT
TMS022	TRS - 4 WHEELS ALIGNMENT	1	50.00	50.00

Total Amount Before 7.000 % of GST 50.00
INCLUDES 7.000 % GST OF 3.50

TOTAL \$ 53.50

Any irregularity of delivery should be reported within seven (7) days, otherwise no claim will be entertained.
Compound interests at the rate of 1% per month will be charged on late payment.
Cheques should be crossed and made payable to STAMFORD TYRES INTERNATIONAL PTE LTD or order.

PA Consent

I hereby consent and authorized STAMFORD TYRES INTERNATIONAL PTE LTD to have mobile number registered in STIS Notification System. I am also notified of its use and expected notification by STIPL for all available services.

STIS Notifications System provide the following:

- Pre/Post Sales Promotion
- Service appointment reminder
- Vehicle service status notification
- Periodical maintenance reminder

GOODS RECEIVED IN GOOD ORDER & CONDITION

COMPANY STAMP

RECIPIENT'S SIGNATURE & DATE

FOR STAMFORD TYRES INTERNATIONAL PTE LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2019 Sendback Est	12 Jul 2019 10:53 S\$4,829.50	12 Jul 2019 13:17 Edit Adj Rpt	S\$1,987.00 Edit Estimates	S\$1,987.00 View Rpt		Pending for Survey Report Cancel Case
	12 Jul 2019 17:49	12 Jul 2019 17:58 S\$459.00	12 Jul 2019 17:58			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N								
Vehicle Reg. No.:	SLG2627A	Date of Loss:	09/07/2019 13:00 - :59 [33 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / CMTD1903347	Policy/Cover Note No.:	D18MTRENT000661 (Comprehensive)						
		Excess:	S\$750.00						
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/07/2019]								
Driver/Custodian:	MORITA KEN (48 / Male) , NRIC: G3237071W, Tel: +6596360458 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> SOMPO_SG (15/07/2019): Alert - Adj Mandate Approved (S\$2295.50) - SLG2627A - Claim Handler: GNOH PAU LO... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLG2627A (CMTD1903347)
 OD
 Jul 9 2019 1:00PM
 [HITACHI CAPITAL ASIA PACIFIC PTE LTD]
 Hitachi Capital Asia Pacific Pte. Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser		
Assessment Reports		1 per page v <input checked="" type="checkbox"/>		
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	11/07/19 18:13	Accident Statement	Load HTM	<input type="checkbox"/>
2	12/07/19 10:53	Repairer Estimates	Load HTM	<input type="checkbox"/>
3	12/07/19 17:58	Repairer Estimates Suppl. #1	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/07/19 14:56	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images		3 per page v <input checked="" type="checkbox"/>		
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	11/07/19 17:59	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	11/07/19 17:59	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	11/07/19 17:59	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	11/07/19 17:59	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	11/07/19 17:59	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	11/07/19 17:59	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	11/07/19 17:59	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	15/07/19 15:06	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	06/08/19 09:32	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	06/08/19 09:32	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	06/08/19 09:32	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	06/08/19 09:32	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	06/08/19 09:32	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	06/08/19 09:32	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Documentation		1 per page v <input checked="" type="checkbox"/>		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	12/07/19 13:18	Driver's Driving License IC & DL		Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/07/19 15:05	ESTIMATE MARKING		Load PDF	
2	07/08/19 11:46	Parts Invoice		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	11/07/19 18:13	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	11/07/19 17:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	11/07/19 17:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	11/07/19 17:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	11/07/19 17:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	11/07/19 17:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	11/07/19 17:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	11/07/19 17:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)		Thumbnail	Print
1	11/07/19 18:08	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19012347/R1TF3E2

Date: 07/08/2019

REFERENCE

Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD	Policy No:	D18MTRENT000661		
Date of Loss:	09/07/2019	Nature of Claim:	OD	Claim No:	CMTD1903347

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG2627A	Engine No:	R16B21600315
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650GT000212
Reg. Date:	26/09/2016 (Man. Year: 2016)	Odometer:	41998 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R15	Rear Tyre Size:	215/65 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,458.50	1,177.00	1,281.50	52.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	810.00	2,020.00	71.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,288.50	1,987.00	3,301.50	62.43
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	5,288.50	1,237.00	4,051.50	76.61
+ GST 7.00/7.00% (S\$)	370.20	86.59	283.61	76.61
Nett Amount (S\$)	5,658.70	1,323.59	4,335.11	76.61

INSPECTION

Date of Assignment:	12/07/2019 Present Location:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)
Date Inspected:	12/07/2019 Inspected At:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road Singapore 629705
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Aug 2019)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG2627A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front Bumper (WCP)	Repair	270.00 F	*- F
2	10		*Front Bumper Clips (WCP)	Necessary	20.00 F	*20.00 F
3	2		*Front Bumper Outer Bracket LH/RH (WCP)	Serviceable	20.00 F	*- F
4	1		*Front Engine Undercover (WCP)	Missing	170.00 F	*170.00 F
5	10		*Front Engine Undercover Clips (WCP)	Necessary	20.00 F	*20.00 F
6	1		*Front Engine Undercover Lip (WCP)	Cut	20.00 F	*20.00 F
7	10		*Front Engine Undercover Lip Clips (WCP)	Not Necessary	20.00 F	*- F
8	1		*Fog Lamp Cover LH (WCP)	Not Necessary	20.00 F	*- F
9	1		*Front Centre Grille Base (WCP)	Not Necessary	65.00 F	*- F
10	1		*Front Centre Grille Outer Chrome (WCP)(NOT NECESSARY)	Old Damage	70.00 F	*- F
11	1		*Front H Logo (WCP)	Not Necessary	20.00 F	*- F
12	1		*Headlamp LH (WCP)	Not Necessary	420.00 F	*- F
13	1		*Headlamp Lower Bracket LH (WCP)	Not Necessary	25.00 F	*- F
14	1		*Front Fender Shield LH (WCP)	Serviceable	45.00 F	*- F
15	10		*Front Fender Shield LH Clips (WCP)	Necessary	20.00 F	*20.00 F
16	1		*Front Crossmember (WCP)	Bent	820.00 F	*820.00 F
Supplementary #1						
17	1		*Engine Floor Panel Undercover LH/RH (WCP)	Serviceable	150.00 F	*- F
18	20		*Engine Floor Panel Undercover LH/RH Clips (WCP)	Serviceable	40.00 F	*- F
19	1		*Rear Exhaust & Pipe (NPA)	Not Necessary	0.00 F	*- F
20	1		*Rear Exhaust Gasket (NPA)	Not Necessary	0.00 F	*- F
21	1		*Mud Flap RH (NPA)	Serviceable	0.00 F	*- F
22	5		*Mud Flap Clips (NPA)	Serviceable	0.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	2,235.00	1,070.00
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				+ Margin on L,N Items 10.00/10.00% (S\$)	223.50	107.00
				Total Parts (S\$)	2,458.50	1,177.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Remove, repair & replace parts for affected areas	New	1,000.00	250.00
2	Spray paint on the affected areas	New	1,000.00	250.00
3	Check wiring, re-align headlamp & ensure proper functioning	New	80.00	0.00
4	Remove & Replace Front Undercarriage & Subframe	New	500.00	250.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
5	Check, Re-adjust and computerise wheel alignment / side slip test	New	250.00	60.00
Gross Labour Cost (\$\$)			2,830.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >