



©

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Attn: Marcus (L.K.K.)

5 days

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0091456 / CHINA TAIPING
Chassis No: JHMRU1810JX200226
License No: SMD8129K
Mileage: 12224
Engine No: L15B5670222

Document No: SVO19053284
Printed By: CSLIM
Order Date: 20. August 2019
Order Time: 10:00:16 AM
Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 73273) OWNER: CYNTHIA FUA TAN KAI LENG OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 10/7/2019 SURVEYED BY: MARCUS (L.K.K.) DATE: 15/07/2019 @ 12:20PM REF NO: SNM19D203236-TAYHP TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L TP VEH: SJH900S						
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	5	18.33	1.28	19.61
73226-SZW-000	DAMPERSTD 5X5	1	8.50	5	8.07	0.56	8.63
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	5	18.33	1.28	19.61
76711-T6A-003	CAPPIVOT	1	4.80	5	4.56	0.32	4.88
91501-S70-003	FASTENER BW/SHIELD	4	5.30	5	20.14	1.41	21.55
91502-S70-003	FASTENER B	2	5.30	5	10.07	0.70	10.77
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	5	7.22	0.51	7.73
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
68100-T8P-U10ZZ	TAILGATE COMP	1	855.70	5	812.91	56.90	869.81
75722-T7W-A01	EMBLEMRR.	1	13.30	5	12.63	0.88	13.51
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	5	13.77	0.96	14.73
75701-T4G-000	EMBLEM	1	24.20	5	22.99	1.61	24.60
90301-ST0-003	NUTPUSH 3MM	2	2.10	5	3.99	0.28	4.27
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	5	440.51	30.84	471.35
91505-TM8-003	CLIP,BUMPER	8	2.30	5	17.48	1.22	18.70
90676-SA7-003	GROMMET,SCREW.5	2	2.30	5	4.37	0.31	4.68
74940-TZ5-A01	BUZZER ASSYSMART	1	60.40	5	57.38	4.02	61.40
	SUM PARTS:				1,912.75	133.88	2,046.63
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R	EXT-YJ	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BG02D	EXT-YJ	1	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN. (N)						
BC011R	EXT-YJ	1	300.00		300.00	21.00	321.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BC012R	0760	1	300.00		300.00	21.00	321.00
	RESET VEHICLE SMART ENTRY						
BMI02D	EXT-YJ	1	250.00		250.00	17.50	267.50
	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR SEATS, TRUNK LININGS, GARNISHES & ETC.(N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0091456 / CHINA TAIPING
Chassis No: JHMRU1810JX200226
License No: SMD8129K
Mileage: 12224
Engine No: L15B5670222

Document No: SVO19053284
Printed By: CSLIM
Order Date: 20. August 2019
Order Time: 10:00:16 AM
Service Advisor: LIM CHOU SIONG

BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00	380.00	26.60	406.60
BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	1,120.00	1,120.00	78.40	1,198.40
BP06R	EXT-YBH SPRAY PAINTING ON TAILGATE, RR BUMPER, RR PANEL, FLOOR PANEL, RR R FENDER & RR L FENDER	1	1,350.00	1,350.00	94.50	1,444.50

SUM LABOUR: 4,230.00 296.10 4,526.10

TOTAL SGD 6,142.75 429.98 6,572.73

Total Payable (SGD) 6,572.73

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Page 3/3

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT19003715	Page	1
Registration No	: SMD8129K	Date	: 24. Aug 2019	Customer No.	: WZC008
Chassis No	: JHMRU1810JX200226	Svc Advisor	: LIM CHOU SIONG	Engine No	: L15B5670222
Model	: HRV DX-SIN CVT YM 2018	Date Time	: 24. Aug 2019 9:25:38 AM	Surveyor Name	: MARCUS (L.K.K.)
Owner's Name	: CYNTHIA FUA TAN KAI LENG	Survey Date	: 15/7/2019	Authorisation Date	: 15/8/2019
Ins Policy No.	:				
Date of Accident	: 10/7/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	SUPPLEMENTARY LABOUR & PARTS						
90676-SA7-003	GROMMET.SCREW.5	2	2.30	5	4.37	0.31	4.68
				Sum Item	4.37	0.31	4.68

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 4.37 0.31 4.68
Total (Inclusive of GST) **4.68**

Printed on 24/8/2019 9:38:03 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.