

ASS. REC. BY:

REF:

CS/AIG/19012356/Kvd3m

Special Instruction:

Surveyor:

Kennedy

ASSIGNMENT (Office)

From (Person):

Hor Yinmi

of

MG

Date/Time:

12/7/19 09:04am

Estimated Cost:

Bill to:

OD / AT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 42992

Insured:

SLF 3842T

at Workshop n/s:

Massive Trading

Tel:

9108 2728

of

Blk 5038 Amk Ind. park 2 # 01-405

Policy No:

2100480406

Claim No:

8256854592 SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:43am 12/7/19

Person Contacted:

Anthony

Vehicle: IN / OUT

Date/Time

Action/Instruction

1-31/10/19 ✓

GBF 42992 - X

SLF 3842T - X

25/7 61Ry 857501 Confirmed (Ref 4827-18, 4610)

ASS. REC. BY:

REF:

A161

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

File post to

RECEIVED 25 JUL 2019

Veh No:

GBI-42988

Fr Regn:

10, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

By 1/1/19

c.c

2P82

Colour

M. Pike

A/C:

Insured / Std / NI / NA

Sp. Reading

42435

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDH 201. 0194631

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / 8/Rim / STD A/Rim or

Tyre Size:

F:

1P5 R15 X8

R:

BS / QUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

6

mm

L/Bal.

9

mm

L/Bal.

6

mm

D.O.A.

11/7/19

D.O.I.

12/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Area N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prelim. Report

11



: Final Report

Date/Time, File Return to?

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

250

11

Fuel:

Others:

TOTAL

261

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

25/7- typist

Report Format:

merimen

Lump Sum / I.B.I. (\$

5750/2

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jul 2019 Edit Reg		12 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LEE KOK HUAT, ID: S71304771		
Main Claimant:	HO LEE ELECTRICAL ENGINEERING, Co. Reg. No.: 53209012L		
Vehicle Reg. No.:	GBF4299Z	Date of Loss:	11/07/2019 11:00 - :59
Claim Type:	TP / 8256854592SG	Policy/Cover Note No.:	2100480406 (Comprehensive)
Vehicle Reg. No. (Insured):	SLF3842T	Policy No. (Claimant):	
		Excess:	
Repairer:	Massive Trading & Auto - Amk (HQ) Blk 225 #07-579 Ang Mo Kio Ave 1, 560225 Ang Mo Kio - Tel: 9187 7187		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJlQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/07/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION REQUEST – GBF4299Z vs SLF3842T (OI) on D.O.A.: 11/07/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahain
Sent: 7/12/2019 9:04:32 AM
Attachments: 20190711143656278.pdf; 20190711143656278.pdf

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**.
Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.ae

From: Janice Kee [mailto:janice.kee@ksteoptr.com]
Sent: Thursday, July 11, 2019 5:27 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahain; Anthony Cheong
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3842T AND GBF4299Z ON 11/07/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir

Our client has agreed to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards,
Janice Kee
c/o Teo Keng Siang LLC
111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

On Thu, Jul 11, 2019 at 2:43 PM Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน
ให้เปิดไฟล์แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-07-18 14:43 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual or entity named in the message. If you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2006-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul.Hor@sig.com
To: janice.kee@ksteopr.com
Cc: Andy-SY.Fong@sig.com, Winnie-LW.Fan@sig.com, NoorMariessa.AbuKassim@sig.com, Syazairdina.Azlan@sig.com, yoke.shi.chan@sig.com, ShengYang.Lim@sig.com, Aashweenjeetkaur.Mithoosingh@sig.com, Divyashni.Subramaniam@sig.com, Wahxin.Tong@sig.com
Subject: sigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF3842T AND GBF4299Z ON 11/07/2019
Date: Thu, 11 Jul 2019 06:43:10 +0000
Without Prejudice

Your Reference : TKSF/M492-ACC-42205.19/sf
Our Reference : SLF3842T

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations - Auto

Yinnul.Hor@sig.com | www.aig.sg

From: Janice Kee [mailto:janice.kee@ksteopr.com]
Sent: Thursday, July 11, 2019 2:40 PM
To: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; Hor, Yinnul
Cc: Anthony Cheong
Subject: [EXTERNAL] Pre Repair Survey for GBF 4299 Z (Your Ref: SLF 3842 T Our Ref: TKSF/M492-ACC-42205.19/sf)

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you

Regards,
Janice Kee
c/o Teo Keng Siang LLC
111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098

Tel: 6333 4222 Fax: 6333 5676

Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688
Email: KSTEOCO@singnet.com.sg
(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

FROM: TEO KENG SIANG LLC
PDX Box No. 8902

Our Ref : TKSF/M492-ACC-42205.19/sf (mc)
Your Ref : SLF 3842 T
Date : 11 July 2019

Secretary in charge: Janice
Tel : 6333 4222 (ext 60)
Fax : 6333 5676 / 6333 5688
Email : janice.kee@ksteopttr.com

To: AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16 Singapore 079120
Attn: Motor Claims Dept

**WITHOUT PREJUDICE
BY PDX# 8181 & FAX 6835 7416 ONLY**

Cc: Lee Kok Huat (Li GeFa) (Owner & Driver)
755 Upper East Coast Road
Singapore 466622

BY POST ONLY

Dear Sirs

**RE: ACCIDENT INVOLVING GBF 4299 Z / SLF 3842 T ON 11/7/19 ALONG PIE TOWARDS
TUAS AFTER BKE EXIT**


We are instructed by Ho Lee Electrical Engineering to notify you of a road traffic accident on 11/7/19 at about 11:50 hours at **ALONG PIE TOWARDS TUAS AFTER BKE EXIT** involving our client's vehicle registration number **GBF 4299 Z** and vehicle registration number **SLF 3842 T** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **GBF 4299 Z** is now at the following workshop:-

Massive Trading & Auto
Blk 5038 Ang Mo Kio Industrial Park 2
#01-405
Singapore 569541
Contact: 9108 2728 Anthony

Yours faithfully,


M/s Teo Keng Siang LLC
encs

****Survey was conducted by:-**

Name of Surveyor:

Date of Survey:

Time of Survey:

Signature

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9012L
Vehicle Details	
Vehicle No.:	GBF4299Z
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2606978
Chassis No.:	KDH2010194631
Maximum Power Output:	-
Open Market Value:	\$23,829.00
Original Registration Date:	28 Oct 2016
First Registration Date:	28 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$1,192.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Oct 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$43,670.00
COE Rebate Amount:	\$31,801.00
Total Rebate Amount:	\$31,801.00

The information contained herein is correct as at 15 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/07/2019 13:47
Date Of Accident	11/07/2019 11:50
Exact Location Of Accident	PIE TWDS TUAS AFTER BKE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF4299Z
Insured/Policyholder	
Name Of Registered Owner	HO LEE ELECTRICAL ENGINEERING
Co Reg No	53209012L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97980840
Alternative Phone No	OFFICE-97980840
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094575331-01
Cover Note Number	
Driver	
Name of Driver	LEE CHEONG HO
NRIC No	S6999175J
Date Of Birth	25/08/1969
Occupation	OUTDOOR
Date Of Driving Pass	16/04/2008
Driving Experience	11 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97980840
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 545 SERANGOON NORTH AVE 3 #08-202
Postcode	550545
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 11/7/2019 @ ARD 1150HRS, I WAS TRAVELLING ALONG PIE TOWARDS TUAS. AFTER BKE EXIT, DUE TO ROAD WORKS ON THE EXTREME RIGHT LANE, THE CAR INFRONT OF MINE SLOWED DOWN SO I ALSO SLOWED DOWN AND EVENTUALLY CAME TO A STOPPED. SUDDENLY I FELT AN STRONG IMPACT FROM THE REAR OF MY VEHICLE. I GOT OUT OF MY VEHICLE AND REALISED THAT VEHICLE B (SLF 3842 T) HAD COLLIDED INTO MY VEHICLE LEFT REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	KIV, SUBMIT BY CLAIMANT W/S
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF3842T
Vehicle Make/Model/Colour	LAND ROVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE KOK HUAT
NRIC/Passport Number	S7130477I
Contact Number	97668287
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11/7/2019 @ around 11:50hrs, I was travelling along PIE towards Tuen. After BKE exit, due to roadworks on the extreme right lane, the car in front of mine slowed down so I also slowed down and eventually came to a stop. Suddenly I felt a strong impact from the rear of my vehicle. I got out of my vehicle and realised that veh 3 (SLF3842T) had collided into my vehicle left rear portion.

DECLARATION
I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIH No.:

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Industrial Pk 2 Singapore 560225

H/p 91082728

Fax : 64816131

Ho Lee Electrical Engineering
Blk 545 Serangoon North Ave 3
#08-202
Singapore 550545

Not Authorized
1-12-1, 11/12/87

Vehicle No : GBF 4299 Z
Make/Model : Toyota Hiace
Year : 2016

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	<i>Rt</i> \$1,875.60	✓
1 pc	Rear n/s tail-gate damper	<i>Sm</i> \$155.60	X
1 pc	Rear tail-gate windscreen moulding	<i>rm</i> \$75.20	—
1 pc	Rear tail-gate emblem " Logo "	<i>rm</i> \$55.30	—
1 pc	Rear tail-gate sticker " Toyota "	<i>rm</i> \$55.10	—
1 pc	Rear tail-gate sticker " HIACE "	<i>rm</i> \$57.10	—
1 pc	Rear tail-gate emblem " GL "	<i>rm</i> \$40.10	—
1 pc	Rear boot rubber		
1 pc	Rear n/s tail-lamp assy	<i>CM</i> \$387.30	✓
1 pc	Rear n/s tail-lamp panel	<i>Rt</i> \$455.10	✓
1 pc	Rear n/s tail-lamp apron panel	<i>Rt</i> \$155.70	✓
1 pc	Rear n/s fender	<i>Rt</i> \$1,480.70	✓
1 pc	Rear n/s fender inner panel	<i>rt</i> \$755.10	X
1 pc	Rear n/s fender inner trim board	<i>Sm</i> \$287.50	X
1 pc	Rear n/s fender corner panel	<i>Rt</i> \$755.60	✓
1 pc	Rear n/s sliding roller rail	<i>Sm</i> \$285.10	X
1 pc	Rear n/s sliding roller rail cover	<i>Sm</i> \$65.10	X
1 pc	Rear bumper	<i>Rt</i> \$405.20	✓
1 pc	Rear n/s bumper side retainer	<i>CM</i> \$55.10	✓
1 pc	Rear end panel		
1 pc	Rear n/s fender air duct - 205.10	<i>CM</i> \$550.60	✓
		\$8,137.80	
		Less 25 %	\$2,034.45
			\$6,103.35

S Nett Item

2 pcs	Rear windscreen sealant	\$40.00	<i>rm</i> \$80.00	✓
1 pc	Rear tail-gate sticker " 70 kmph "		<i>rm</i> \$20.00	15/12
1 pc	Rear tail-gate sticker " 6 Pax "		<i>rm</i> \$20.00	15/12
1 pc	Rear reverse sensor		\$200.00	✓
1 set	Rear tail-lamp chrome		\$745.00	
		balance c/f	\$6,423.35	

LKK Auto Consultants hereby notify
the insured of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Part prices are subject to confirmation
• Third party liability is on a "Without Prejudice" basis
• No illegal inducements are allowed
• Supplementary liability must be resurveyed and
is subject to final approval from Insurance Company

Authorised by Repairs
Signature:

GBF 4299 Z

balance b/f \$6,423.35

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.	\$1,800.00	1100
To putty and spray paint	\$1,500.00	800
Check & reconnect wiring.	\$30.00	200
Remove/refit rear windscreen glass to facilitate repair	\$120.00	✓
Remove/refit rear tail-gate mechanism, inner trim to new door.	\$100.00	600
Remove/refit roof lining to facilitate repair on rear n/s fender	\$150.00	800
Remove/refit rear n/s fender glass to facilitate repair	\$120.00	1000
Total	<u>\$10,243.35</u>	

KV

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Industrial Pk 2 Singapore 560225
H/p 91082728

Fax : 64816131

Ho Lee Electrical Engineering
Blk 545 Serangoon North Ave 3
#08-202
Singapore 550545

Vehicle No : GBF 4299 Z
Make/Model : Toyota Hiace
Year : 2016

Not Authorized

1. A1, 61 Lp 87

61 Lp 85750/h

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	1775.30	A4	\$1,875.60	✓
1 pc	Rear n/s tail-gate damper		RM	\$155.00	
1 pc	Rear tail-gate windscreen moulding		RM	\$75.20	✓
1 pc	Rear tail-gate emblem "Logo"		RM	\$55.30	✓
1 pc	Rear tail-gate sticker "Toyota"		RM	\$55.10	✓
1 pc	Rear tail-gate sticker "HIACE"		RM	\$57.10	✓
1 pc	Rear tail-gate emblem "GL"		RM	\$40.10	✓
1 pc	Rear boot rubber	photo	92-851N 113	\$185.70	✓ 5081N
1 pc	Rear n/s tail-lamp assy		CM	\$387.30	✓
1 pc	Rear n/s tail-lamp panel		R	\$455.10	✓
1 pc	Rear n/s tail-lamp apron panel		R	\$155.70	✓
1 pc	Rear n/s fender	1321.70	A1	\$1,480.70	✓
1 pc	Rear n/s fender inner panel		A	\$755.10	
1 pc	Rear n/s fender inner trim board		RM	\$287.60	
1 pc	Rear n/s fender corner panel	691.50	RM	\$755.60	✓
1 pc	Rear n/s sliding roller rail		RM	\$285.10	
1 pc	Rear n/s sliding roller rail cover		RM	\$85.10	
1 pc	Rear bumper		R	\$405.20	✓
1 pc	Rear n/s bumper side retainer		CM	\$55.10	✓
1 pc	Rear end panel	photo 440.50	RM	\$550.60	✓
1 pc	Rear n/s fender air duct - 205.10	photo	CM	\$8,137.80	6,794.50
			Less 25 %	\$2,034.45	1,698.63
				\$6,103.35	5,095.87

S Nett Item

2 pcs	Rear windscreen sealant	\$40.00	RM	\$80.00	✓
1 pc	Rear tail-gate sticker "70 kmph"		RM	\$20.00	151N
1 pc	Rear tail-gate sticker "6 Pax"		RM	\$20.00	151N
1 pc	Rear reverse sensor	photo	RM	\$200.00	7 X
1 set	Rear tail lamp chrome	- \$180.00	RM	\$745.00	310.00
		1205N	balance c/f	\$6,423.35	

GBF 4299 Z

balance b/f \$8,423.35

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.	\$1,800.00	1100
To putty and spray paint	\$1,500.00	900
Check & reconnect wiring.	\$30.00	20
Remove/refit rear windscreen glass to facilitate repair	\$120.00	✓
Remove/refit rear tail-gate mechanism, inner trim to new door.	\$100.00	60
Remove/refit roof lining to facilitate repair on rear n/s fender	\$150.00	80
Remove/refit rear n/s fender glass to facilitate repair	\$120.00	100
Total	\$10,243.35	1200

10,577.18

Hi Kenneth

Part -	5,095.87
SNCT -	310.00
Labour -	2,200.00
	<hr/>
	7,785.87
	6,200.00

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19012356/KVD3N2

Date: 29/07/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100480406
Claimant Vehicle No :	GBF4299Z	Insured Vehicle No :	SLF3842T
Date of Loss:	11/07/2019	Nature of Claim:	TP
		Claim No:	8256854592SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4299Z	Engine No:	1KD2606978
Make & Model:	TOYOTA HIACE, 2.5 (A)	Chassis No:	KDH2010194631
Reg. Date:	28/10/2016 (Man. Year: 2016)	Odometer:	42435 km
Colour:	Metallic Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,757.18	4,954.32	1,802.86	26.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	2,380.00	1,440.00	37.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,577.18	7,334.32	3,242.86	30.66
Approved Total (Overridden) (S\$)		5,750.00		
Nett Amount (S\$)	10,577.18	5,750.00	4,827.18	45.64

INSPECTION

Date of Assignment:	12/07/2019		
Date Inspected:	12/07/2019	Inspected At:	Bik 5038 AMK Ind Park 2 #01-405 Repairer: Massive Trading & Auto
Estimated Period of Repair:	8.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	1,875.60 FL	*1,775.30 FL
2	1		*REAR N/S TAIL-GATE DAMPER	Serviceable	155.60 FL	*- FL
3	1		*REAR TAIL-GATE WINDSCREEN MOULDING	Necessary	75.20 FL	*75.20 FL
4	1		*REAR TAIL-GATE EMBLEM LOGO	Necessary	55.30 FL	*55.30 FL
5	1		*REAR TAIL-GATE STICKER TOYOTA	Necessary	55.10 FL	*55.10 FL
6	1		*REAR TAIL-GATE STICKER HIACE	Necessary	57.10 FL	*57.10 FL
7	1		*REAR TAIL-GATE EMBLEM GL	Necessary	40.10 FL	*40.10 FL
8	1		*REAR N/S TAIL-LAMP ASSY	Cracked	387.30 FL	*387.30 FL
9	1		*REAR N/S TAIL-LAMP PANEL	Bent	455.10 FL	*455.10 FL
10	1		*REAR N/S TAIL-LAMP APRON PANEL	Bent	155.70 FL	*155.70 FL
11	1		*REAR N/S FENDER	Bent	1,480.70 FL	*1,321.70 FL
12	1		*REAR N/S FENDER INNER PANEL	Repair	755.10 FL	*- FL
13	1		*REAR N/S FENDER INNER TRIM BOARD	Serviceable	287.50 FL	*- FL
14	1		*REAR N/S FENDER CORNER PANEL	Bent	755.60 FL	*691.50 FL
15	1		*REAR N/S SLIDING ROLLER RAIL	Serviceable	285.10 FL	*- FL
16	1		*REAR N/S SLIDING ROLLER RAIL COVER	Serviceable	65.10 FL	*- FL
17	1		*REAR BUMPER	Bent	405.20 FL	*405.20 FL
18	1		*REAR N/S BUMPER SIDE RETAINER	Cracked	55.10 FL	*55.10 FL
19	1		*REAR END PANEL	Buckled	550.60 FL	*440.50 FL
20	1		*REAR N/S FENDER AIR DUCT	Cracked	205.10 FL	*205.10 FL
21	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
22	1		*REAR TAIL-GATE STICKER 70KMPH	Necessary	20.00 FS	*15.00 FS
23	1		*REAR TAIL-GATE STICKER 6PAX	Necessary	20.00 FS	*15.00 FS
24	1		*REAR REVERSE SENSOR	Serviceable	200.00 FS	*- FS
25	1		*SET REAR TAIL LAMP CHROME	Necessary	180.00 FS	*120.00 FS
26	1		*REAR BOOT RUBBER (50%)	Distorted	139.28 FS	*92.85 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,796.48	6,498.15
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,039.30	1,543.83

Total Parts (\$\$)	6,757.18	4,954.32
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	1,800.00	1,100.00
2	TO PUTTY AND SPRAY PAINT	New	1,500.00	900.00
3	CHECK & RECONNECT WIRING	New	30.00	20.00
4	REMOVE/REFIT REAR WINDSCREEN GLASS TO FACILITATE REPAIR	New	120.00	120.00
5	REMOVE/REFIT REAR TAIL-GATE MECHANISM,INNER TRIM TO NEW DOOR	New	100.00	60.00
6	REMOVE/REFIT ROOF LINING TO FACILITATE REPAIR ON REAR N/S FENDER	New	150.00	80.00
7	REMOVE/REFIT REAR N/S FENDER GLASS TO FACILITATE REPAIR	New	120.00	100.00
Gross Labour Cost (S\$)			3,820.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >