

000000

INS. CASE OWNER:

CC 6/AIG19012358, U6639

LKK:  
IDAC:

Surveyor:

marling

DOI:

ASSIGNMENT

12/7/19

Date / Time:

12/7/19

Registered in Merimen:

12/7/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLT 96494

Name of Insured:

POPULAR RENT A CAR PTE LTD

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

Excess Sec II :SS

D.O.A.:

70/6/19

Place of Accident:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO

NO

TP GIA REPORT: YES / NO

NO

Insured Liability:

%

Final ? Yes / No

FBK 1705L



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

BHH



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

6/9/19  
Khanh Chau

FBK 1705L -X SLT 96494 -X  
File pass to Shu Pei to close

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OE

After call 1st to OE

15/7/19

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OE

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

SS 450

( 3 days) Reduction:

60

Email

Call

FINAL SETTLEMENT

Date/Time:

6/9/19

Confirm with:

Raymond

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

41681

SS 481.50

(Q.D. REAR END TP)

Loss of Rental (LOR):

SS

-

( - days)

Loss of Use (LOU):

SS

60

(S 20 x 3 days)

Loss of Income (LOI):

SS

-

(S - x - days)

LOR only

LOU only

✓

LOR + LOU

LOR + LO

LOU + LO

(Tick only one)

GIA/LTA Search

SS

7.45

Medical:

SS

-

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

-

(e.g. Tow/ Independent)

2) Report Format

Legal Cost

SS

-

3) Survey fee:

Total:

SS

548.95

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

548.95

Name 1:

BAH HOCK HIN COMPANY PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:





**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197002200K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE  
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL  
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

## QUOTATION

Customer :

NO. : 34411

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
MOTOR CLAIMS DEPT

DATE : 06/07/2019  
CLAIM NO. : 11381  
POLICY NO. : AVFMSB0000591904

FROM : RAYMOND

VEHICLE NO. : FBK1705L  
MAKE/MODEL : YAM / YBR125

*Handwritten notes:*  
2 of April  
4/5 = 450  
3 dpt.  
12/7/19  
To high pr. AH-127

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$350.00	350.00 X
2	COVER TAIL CENTRE REAR P/N: 54315	REPLACE	1.00	\$48.00	48.00
3	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	\$90.00	90.00
4	COVER TAIL RH (RED) P/N: 53007	REPLACE	1.00	\$90.00	90.00
5	HANDLE SEAT P/N: 42567	REPLACE	1.00	\$98.00	98.00 X
6	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$195.00	195.00
7	LAMP TAIL ASSY P/N: 58245	REPLACE	1.00	\$75.00	75.00
8	LENS (V_SYS) C3 HD (WARRANTY) P/N: 57945	REPLACE	1.00	\$56.00	56.00
9	MUDGUARD REAR P/N: 45416	REPLACE	1.00	\$68.00	68.00
10	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$16.00	16.00
11	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00

SUB TOTAL

\$1,121.00

GST @ 7 %

\$78.47

GRAND TOTAL

\$1,199.47



bigSAFE<sub>3</sub>



*Handwritten numbers:*  
419  
572.1  
457

Address: No. 6, Delu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE  
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL  
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

## QUOTATION

Customer :

NO. : 34411

- Rev. 2

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
MOTOR CLAIMS DEPT

DATE : 06/07/2019  
CLAIM NO. : 11381  
POLICY NO. : AVFMSB0000591904

FROM : RAYMOND

VEHICLE NO. : FBK1705L  
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER TAIL CENTRE REAR P/N: 54315	REPLACE	1.00	\$48.00 Disc %: 10.00	43.20
2	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	\$90.00 Disc %: 10.00	81.00
3	COVER TAIL RH (RED) P/N: 53007	REPLACE	1.00	\$90.00 Disc %: 10.00	81.00
4	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$150.00	150.00
5	LAMP TAIL ASSY P/N: 58245	REPLACE	1.00	\$75.00 Disc %: 10.00	67.50
6	LENS (V_SYS) C3 HD (WARRANTY) P/N: 57945	REPLACE	1.00	\$56.00 Disc %: 10.00	50.40
7	MUDGUARD REAR P/N: 45416	REPLACE	1.00	\$68.00 Disc %: 10.00	61.20
8	PLATE NUMBER REAR (8.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$10.00	10.00
9	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00

SUB TOTAL

\$579.30

GST @ 7 %

\$40.55

GRAND TOTAL

\$619.85

50% deposit required before ordering of parts.

Validity: 30 days



biSAFE<sub>3</sub>



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 200214080  
ISS: 06/11/2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	For & on Behalf of			Acknowledge & Accepted By	
	<b>BAN HOCK HIN CO PTE LTD</b>				



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

bizSAFE<sub>3</sub>



**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000288K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

NO. : 34411

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
MOTOR CLAIMS DEPT

DATE : 06/07/2019  
CLAIM NO. : 11381  
POLICY NO. : AVFMSB0000591904

FROM : RAYMOND

VEHICLE NO. : FBK1705L  
MAKE/MODEL : YAM / YBR125

*N of April*  
*2/5*  
*3 dy.*  
*12/7/19*  
*Wheeler. AH-129*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29581	REPLACE	1.00	\$350.00	350.00 X
2	COVER TAIL CENTRE REAR P/N: 54315	REPLACE	1.00	\$48.00	48.00
3	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	\$90.00	90.00
4	COVER TAIL RH (RED) P/N: 53007	REPLACE	1.00	\$90.00	90.00 ?
5	HANDLE SEAT P/N: 42567	REPLACE	1.00	\$98.00	98.00 X
6	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$195.00	195.00
7	LAMP TAIL ASSY P/N: 58245	REPLACE	1.00	\$75.00	75.00 ?
8	LENS (V_SYS) C3 HD (WARRANTY) P/N: 57945	REPLACE	1.00	\$56.00	56.00
9	MUDGUARD REAR P/N: 45416	REPLACE	1.00	\$68.00	68.00
10	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$16.00	16.00 10
11	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00

SUB TOTAL

\$1,121.00

GST @ 7 %

\$78.47

GRAND TOTAL

\$1,199.47



bizSAFE<sub>3</sub>



<u>S/N.</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
-------------	--------------------	---------------	------------	-------------------	---------------

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



*bizSAFE<sub>3</sub>*



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-4-0001  
ISO 9001:2015

### Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	FBK1705L		
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	YAMAHA		
Vehicle Model:	YBR125		
Chassis No.:	LBPKE1787E0025744		
Propellant:	Petrol		
Engine No.:	E3J2E015032		
Engine Capacity:	124 cc		
Maximum Power Output:	-		
Maximum Laden Weight:	320 kg		
Unladen Weight:	114 kg		
Year Of Manufacture:	2013		
Original Registration Date:	13 Apr 2015		
Lifespan Expiry Date:	-		
COE Category:	D - Motorcycle		
Quota Premium:	\$4,800.00		
COE Expiry Date:	12 Apr 2025		
Road Tax Expiry Date:	12 Apr 2020		
Inspection Due Date:	12 Apr 2020		
Intended Transfer Date:	11 Jul 2019		
CO2 Emission:	-		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print



## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Thursday, 5 September 2019 5:48 PM  
**To:** Raymond  
**Cc:** Admin A  
**Subject:** RE: Accident Involving FBK1705L & SLT9649Y on 30/06/2019  
**Attachments:** AIG DV.pdf

Tracking:	Recipient	Delivery
	Raymond	
	Admin A	
	shupei@lkkauto.com	Delivered: 5/9/2019 5:48 PM
	Meikwan@lkkauto.com	Delivered: 5/9/2019 5:48 PM
	olivialau@lkkauto.com	Delivered: 5/9/2019 5:48 PM

Without Prejudice

Our Ref: CC6/AIG19012358/Ukb3

Dear Raymond,

We refer to the above matter.

We confirm settlement as follows:

1. Cost of Repair (w/GST)	\$ 481.50
2. Loss of Use (3 days x \$20)	\$ 60.00
3. LTA Search Fee	\$ 7.45
<b>Total</b>	<b>\$ 548.95</b>

We attach herewith a copy of the DV for your further action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Khanchna** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.  
Attn : Chan, Kian-Meng

Your Ref : 4303677460SG  
Our Ref : CC6/AIG19012358/UKB3  
Date : 05 Sep 2019

**"WITHOUT PREJUDICE"****ACCIDENT INVOLVING SLT9649Y & FBK1705L ON 30/06/2019**

Refer to the above accident.

The accident occurred when Insured vehicle rear ended Third party vehicle. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SLT9649Y) and third party claimant (vehicle no. FBK1705L).

Summary of offer made to workshop Ban Hock Hin Co. Pte Ltd is as follows :

	Claimed	Revised
Cost of Repairs (w/GST)	\$ 619.85	\$ 481.50
Loss of Use (3 days x \$20)	\$ 60.00	\$ 60.00 (3 days x \$20)
LTA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 687.30	\$ 548.95

Amount of claim at **Liability 100%** \$ 548.95

**\*\* 3 days recommendation for repair**

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,  
Khanchna Pothuraj  
LKK Auto Consultants Pte Ltd

## Khanchna (LKK Auto)

---

**From:** Chan, Kian-Meng <Kianmeng.Chan1@aig.com>  
**Sent:** Thursday, 5 September 2019 5:26 PM  
**To:** Khanchna (LKK Auto)  
**Cc:** Admin A  
**Subject:** RE: Mandate Request - TP / 4303677460SG [ACCIDENT INVOLVING FBK 1705L & SLT 9649Y (AIG) ON 30/06/2019]

Dear Khanchna,

Kindly assist to settle at not more than \$548.95.  
Let me know if you require further assistance.

Best regards,  
**Chan Kian Meng**  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120  
Tel +(65) 6419 1678  
[KianMeng.Chan1@aig.com](mailto:KianMeng.Chan1@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]  
**Sent:** Thursday, September 05, 2019 4:02 PM  
**To:** Chan, Kian-Meng  
**Cc:** Admin A  
**Subject:** [EXTERNAL] Mandate Request - TP / 4303677460SG [ACCIDENT INVOLVING FBK 1705L & SLT 9649Y (AIG) ON 30/06/2019]

This message is from an external sender; be cautious with links and attachments.

Dear Mr. Chan Kian Meng,

Summary mandate IA uploaded in Merimen.

All the relevant documents had been uploaded in Merimen.

For your approval please.

Thank you.

Best Regards,  
**Khanchna** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000288K  
MOTORCYCLE ACCESSORIES / SERVICE CENTRE  
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL  
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

02 AUG 2019

Your Ref : SLT9649Y  
Our Ref : TP/11381/FBK1705L/SLT9649Y

BY EMAIL & HAND

AIG Asia Pacific Insurance Pte Ltd  
CHARTIS BUILDING  
78 Shenton Way  
#07-16  
Singapore 079120

ATTN: MOTOR CLAIMS DEPT

Dear Sir / Madam,,

Accident Involving FBK1705L & SLT9649Y on 30/06/2019

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$ 481.50
2. Loss of Use (3 days x \$20)	\$ 60.00
3. LTA Vehicle Insurance Search Fee	\$ 7.45
<b>TOTAL</b>	<b>\$ 548.95</b>

We attached our Tax Invoice and GIA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext.220.

Thank you.

**BAN HOCK HIN CO PTE LTD**

Raymond Tan  
Manager/Insurance Dept



Address: No. 6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 200211030  
ISS 04/01/2018

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Thursday, 18 July 2019 1:55 PM  
**To:** annieloh@popularcar.com  
**Cc:** Admin A  
**Subject:** ACCIDENT INVOLVING SLT9649Y & FBK1705L ALONG DUNEARN ROAD ON 30/06/2019

Tracking:	Recipient	Delivery
	annieloh@popularcar.com	
	Admin A	
	olivialau@lkkauto.com	Delivered: 18/7/2019 1:55 PM
	Meikwan@lkkauto.com	Delivered: 18/7/2019 1:55 PM
	shupei@lkkauto.com	Delivered: 18/7/2019 1:55 PM

Our Ref: CC6/AIG19012358/Ukb3  
Your Ref: SLT9649Y [Driver: MUHD SHAHAR BIN LATIP]

### **POPULAR RENT A CAR PTE LTD**

#### **Policy Holder**

Dear Sir/Madam,

#### **ACCIDENT INVOLVING SLT9649Y & FBK1705L ALONG DUNEARN ROAD ON 30/06/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from FBK1705L against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,  
**Khanchna** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, BAN HOCK HIN COMPANY PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$481.50 (Repair Cost), S\$60.00 (Loss of Use/Rental), S\$7.45 (Disbursement) for vehicle no. FBK1705L that was damaged pursuant to the accident which occurred on 30/06/2019 (date) along DUNEARN ROAD (location) involving vehicle no/s SLT9649Y. This is pursuant to the inspection conducted on 12/07/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner BAN HOCK HIN COMPANY PTE LTD (the third party claimant") of vehicle no. FBK1705L make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to FBK1705L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 6th (day) of Sept (month) 20 19 (year)

  
CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)



**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000280K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## TAX INVOICE

GST Reg No : M2-0010542-7

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120  
MOTOR CLAIMS DEPT

Invoice No. : LECR20037133-I11381  
Invoice Date : 01/08/2019  
Payment Due Date : 31/08/2019

CLAIM NO. : 11381  
POLICY NO. : AVFMSB0000591904  
VEHICLE NO. : FBK1705L  
MAKE/MODEL : YAM / YBR125

<u>S/N</u>	<u>Description</u>	<u>Amount</u>
1	LUMPSUM REPAIR	\$450.00
SUB TOTAL		\$450.00
GST @ 7 %		\$31.50
GRAND TOTAL		<b>\$481.50</b>

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Printed by : RAYMOND

*bizSAFE<sub>3</sub>*



&gt; Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 10 Jul 2019 / 15:51:50

Receipt Date/Time : 10 Jul 2019 / 15:51:50

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-190710-002458

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLT9649Y				
As at 30 Jun 2019/19:30:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLT9649Y			
	Enquiry Fee	7.00	0.49	7.49
	20190710155004827411			
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
Paid By				
	20190710155032758	Direct Debit: eNETS Debit (Internet Banking)		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



[> Back to OneMotoring](#)**Vehicle Insurance Particulars Result**

Vehicle No.	Incident Date/Time	Insurance Company Name
SLT9649Y	30 Jun 2019 / 19:30:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Print](#)[OK](#)[Save as PDF](#)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jul 2019 <a href="#">Edit Reg</a>		12 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$5450.00</b> <a href="#">Edit Estimates</a>	<b>\$5450.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	POPULAR RENT A CAR PTE LTD, Co. Reg. No.: 199608195Z								
Main Claimant:	BAN HOCK HIN CO PTE LTD, Co. Reg. No.: 197000288K								
Vehicle Reg. No.:	FBK1705L	Date of Loss:	30/06/2019 00:00 - :59 [50 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4303677460SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLT9649Y	Policy No. (Claimant):	AVFMSB0000591803						
		Excess:							
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	Allied World Assurance Company, Ltd (HQ) - Tel: 62201188								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/07/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (15/07/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBK1705L (4303677460SG)  
[SLT9649Y]  
TP  
BAN HOCK HIN CO PTE LTD  
Jun 30 2019 12:00AM  
[POPULAR RENT A CAR PTE LTD]  
Ban Hock Hin Co. Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <span>View in Browser</span>		
Letters/Correspondences														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit				
Assessment Reports														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	05/09/19 15:58	Adjuster Immediate Advice											Load HTML				
Photos/Images														3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	13/07/19 12:24	Chassis Number											Load JPG	<input checked="" type="checkbox"/>			
2	13/07/19 12:24	Odometer Reading											Load JPG	<input checked="" type="checkbox"/>			
3	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
4	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
5	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
6	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
7	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
8	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
9	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
10	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
11	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
12	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
13	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
14	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
15	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
16	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
17	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
18	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
19	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
20	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
21	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
22	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
23	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
24	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
25	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
26	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
27	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
28	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
29	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
30	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
31	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
32	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
33	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
34	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
35	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			
36	13/07/19 12:25	General View											Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	13/07/19 12:25	General View		<input checked="" type="checkbox"/>
38	13/07/19 12:25	General View		<input checked="" type="checkbox"/>
39	13/07/19 12:25	General View		<input checked="" type="checkbox"/>
40	13/07/19 12:25	General View		<input checked="" type="checkbox"/>
41	13/07/19 12:25	General View		<input checked="" type="checkbox"/>
42	02/08/19 08:19	After Repair Photo		<input checked="" type="checkbox"/>
43	02/08/19 08:19	After Repair Photo		<input checked="" type="checkbox"/>
44	02/08/19 08:19	After Repair Photo		<input checked="" type="checkbox"/>
45	02/08/19 08:19	After Repair Photo		<input checked="" type="checkbox"/>
46	02/08/19 08:19	After Repair Photo		<input checked="" type="checkbox"/>
47	02/08/19 08:19	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/07/19 17:44	TP ESTIMATE- MARKED		<input type="checkbox"/>
2	15/07/19 17:44	TP GIA REPORT		<input type="checkbox"/>
3	18/07/19 13:55	EMAIL TO OI		<input type="checkbox"/>
4	05/09/19 15:50	TP LOD		<input type="checkbox"/>
5	05/09/19 15:53	TP FINAL REPAIR INVOICE, LTA SEARCH		<input type="checkbox"/>
6	16/09/19 10:53	WORKSHOP INVOICE		<input type="checkbox"/>
7	16/09/19 10:53	Release Voucher		<input type="checkbox"/>
8	16/09/19 10:53	LTA SEARCH		<input type="checkbox"/>
9	16/09/19 10:53	LOD		<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/07/19 11:02	OI GIA REPORT		<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> ^ v </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLT9649Y (Insd veh)	Model:	YAMAHA YBR125 123CC
	FBK1705L (TP veh)		(M)
Date of Accident:	30/06/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	1,199.47
Final Repair Cost	:	\$	481.50
Loss of Use	:	\$	60.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	548.95

3.00 days at \$20.00 per day  
days

**Is Third Party Workshop GIA Registered?** ☐ YES ☒ NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Ban Hock Hin Co Pte Ltd	:	\$ 548.95
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

16 Sep  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19012358/UKB3Q2

Date: 16/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant FBK1705L

Insured Vehicle No : SLT9649Y

Vehicle No : FBK1705L

Nature of Claim: TP

Claim No: 4303677460SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBK1705L

Make &amp; Model: YAMAHA YBR125, 123cc (M)

Engine No: E3J2E015032

Reg. Date: 13/04/2015 (Man. Year: 2013)

Chassis No: LBPKE1787E0025744

Colour: Red

Odometer: 95699 km

Engine Capacity: 124 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 2.75-18

Rear Tyre Size: 90/90-18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	891.00	394.30	496.70	55.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	230.00	185.00	45.00	19.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,121.00</b>	<b>579.30</b>	<b>541.70</b>	<b>48.32</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>450.00</b>		
(S\$)	1,121.00	450.00	671.00	59.86
<b>+ GST 7.00/7.00% (S\$)</b>	<b>78.47</b>	<b>31.50</b>	<b>46.97</b>	<b>59.86</b>
<b>Nett Amount (S\$)</b>	<b>1,199.47</b>	<b>481.50</b>	<b>717.97</b>	<b>59.86</b>
<b>+ Loss of Use (3.0 x S\$20.00/day) (S\$)</b>		<b>60.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>7.45</b>		
<b>Nett Liability (S\$)</b>		<b>548.95</b>		

## INSPECTION

Date of Assignment: 12/07/2019

Date Inspected: 12/07/2019 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALIGNMENT BODY	Not Necessary	350.00 F	*- FL
2	1		*COVER TAIL CENTRE REAR	Cracked	48.00 F	*48.00 FL
3	1		*COVER TAIL LH (RED)	Cracked	90.00 F	*90.00 FL
4	1		*COVER TAIL RH (RED)	Cracked	90.00 F	*90.00 FL
5	1		*HANDLE SEAT	Not Necessary	98.00 F	*- FL
6	1		*LAMP TAIL ASSY	Cracked	75.00 F	*75.00 FL
7	1		*LENS (V-SYS) C3 HD (WARRANTY)	Scratched	56.00 F	*56.00 FL
8	1		*MUDGUARD REAR	Distorted	68.00 F	*68.00 FL
9	1		*PLATE NUMBER REAR (6.5 INCH X9 INCH)	Bent	16.00 FS	*10.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>891.00</b>	<b>437.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>42.70</b>
<b>Total Parts (\$\$)</b>	<b>891.00</b>	<b>394.30</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TRANSPORT CHARGES	New	35.00	35.00
2	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	195.00	150.00
Gross Labour Cost (S\$)			<b>230.00</b>	<b>185.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >