



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34411

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 06/07/2019
CLAIM NO. : 11381
POLICY NO. : AVFMSB0000591904

FROM : RAYMOND

VEHICLE NO. : FBK1705L
MAKE/MODEL : YAM / YBR125

*Not Approved
2/5
3 days
12/7/19
The high. All in*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$350.00	350.00 <i>17</i> X
2	COVER TAIL CENTRE REAR P/N: 54315	REPLACE	1.00	\$48.00	48.00 <i>one</i>
3	COVER TAIL LH (RED) P/N: 45418	REPLACE	1.00	\$90.00	90.00 <i>one</i>
4	COVER TAIL RH (RED) P/N: 53007	REPLACE	1.00	\$90.00	90.00 <i>one</i> ?
5	HANDLE SEAT P/N: 42567	REPLACE	1.00	\$98.00	98.00 <i>17</i> X
6	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	<i>1/2</i>	1.00	\$195.00	195.00 <i>150</i>
7	LAMP TAIL ASSY P/N: 58245	REPLACE	1.00	\$75.00	75.00 ?
8	LENS (V_SYS) C3 HD (WARRANTY) P/N: 57945	REPLACE	1.00	\$56.00	56.00 <i>scr</i>
9	MUDGUARD REAR P/N: 45416	REPLACE	1.00	\$68.00	68.00 <i>Dis</i>
10	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE <i>*</i>	1.00	\$16.00	16.00 <i>10</i>
11	TRANSPORT CHARGES P/N: 07169	<i>*</i>	1.00	\$35.00	35.00 ✓

SUB TOTAL

\$1,121.00

GST @ 7 %

\$78.47

GRAND TOTAL

\$1,199.47



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LAN Auto Consultants hence notify
the Repairs of the following:

- To resurvey before water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification is allowed
- Supplementary damage must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



bizSAFE₃

