

NGS TRADING

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelynngstrading@gmail.com
Reg No.: 51106300L

QUOTATION

No. : QT-09329

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIMS DEPT
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Your Ref. :
Our Ref : QT-09329/SJV4330
C. C. :
Date : 11-07-2019
Page : 1 of 2

TEL : 6419 3000

FAX :

Description	Qty	U/ Price	Amount
		S\$	S\$
ACCIDENT ON 05/07/2019@21:00HRS ALONG SEGAR RD INVOLVING SJV4330L & SLK3881D, CLAIMS AGAINST SLK3881D (AIG)			
REPLACEMENT PARTS: HD STREAM			
HEADLAMP RH	1	748.70	748.70
FRT FENDER RH	1	519.30	519.30
FRT FENDER LINING RH	1	105.70	105.70
FRT BUMPER	1	635.60	635.60
FRT HEADLAMP RETAINER RH	1	43.00	43.00
SIDE RETAINER RH	1	28.70	28.70
RAD GRILLE BASE	1	240.60	240.60
RAD GRILLE CHROME	1	280.80	280.80
REINFORCEMENT	1	219.00	219.00
SUPPORT PANEL	1	496.00	496.00
BONNET	1	768.00	768.00
FENDER MARK RH	1	52.50	52.50
BUMPER LOWER COVER RH	1	68.40	68.40
SubTotal			4,206.30
Less 20%	1	-841.26	-841.26
FENDER SHIELD CLIPS 10PCS	10	3.50	35.00
SPORTS RIM	1	480.00	480.00
REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENT, RESHAPED/REALIGN DENTED PANEL, REPLACE DAMAGED PARTS, REFIT INTO POSITION.	1	1,000.00	1,000.00
SPRAY PAINTING	1	600.00	600.00
CHECK WIRING/LIGHT PROPER FUNCTION	1	40.00	40.00

Not Notified
6/11/19 @ 2900h
Paying After Repair
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Alignment \$80

600