

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : JESSICA WONG HUI TING
21 FERVALE CLOSE
22-03 RIVERTREES RESIDENCES
SINGAPORE 797460
TEL: 91112823
ATTN:

Claim No: MC1900524
No: MF1900609
Date: 02 Oct 2019
Policy No: PNPV2019-00004194
Veh Reg No: SLX7431A
Make/Model: VOLKSWAGEN GOLF
TSI TL

Your Ref No: SLX7431A
Claim Type: Third Party
Accident Date: 14/06/2019
TP Veh Reg No: SBX622E

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLX7431A

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	1,056.55	
2 REAR BUMPER CLIPS	12 PC	30.00	
		1,086.55	
	Less 10%	108.66	977.90
Special Nett			
3 REVERSE SENSOR	1 SET	200.00	
		200.00	200.00
LABOUR			
4 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	10.00	
5 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
6 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	
7 TO SPRAY REAR BUMPER	1 PC	200.00	
		460.00	460.00
	Total		S\$ 1,637.90
	Less Excess		S\$ 0.00
	Amount Before GST		S\$ 1,637.90
	Add GST @ 7%		114.65
	Total Amount Payable		S\$ 1,752.55

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SEVEN HUNDRED FIFTY TWO AND CENTS FIFTY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 12/07/2019

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JESSICA WONG HUI TING
 21 FERNVALE CLOSE
 22-03 RIVERTREES RESIDENCES
 SINGAPORE 797460
 TEL: 91112823
 ATTN:

Estimate No: MC1900524
 Date: 11 Jul 2019
 Policy No: PNPV2019-00004194
 Veh Reg No: SLX7431A
 Make/Model: VOLKSWAGEN GOLF
 TSI TL

Your Ref No: SLX7431A
 Claim Type: Third Party - AIG
 Accident Date: 14/06/2019
 TP Veh Reg No: SBX622E

LKIC
 2-4

Not with air
 Running by paint

2 days

Estimate Repair Cost to Vehicle No :SLX7431A

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	Buena 1 PC	1,056.55	✓
2 REAR-BUMPER-SIDE-RETAINERS-LH-&RH	2 PC	96.30	X
3 REAR BUMPER CLIPS	12 PC	30.00	✓
4 NO-PLATE LAMP	2 PC	58.50	X
5 REAR BUMPER TOW-COVER	1 PC	23.65	X
		1,265.00	
	Less 10%	126.50	1,138.50
Special Nett			
6 NUMBER PLATE	1 PC	35.00	X
7 REVERSE SENSOR	1 SET	200.00	2 Photo
		235.00	235.00
LABOUR			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	100
9 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	500
10 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD. TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	2000
11 TO SPRAY REAR BUMPER	1 PC	400.00	2000
		900.00	900.00
	Total		S\$ 2,273.50
	Add GST @ 7%		159.15
	Total Amount Payable		S\$ 2,432.65

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FOUR HUNDRED THIRTY TWO AND CENTS SIXTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

01-08-19
 meng

02-08-19 man take photo

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE